

 Preview Solution CBR-2545-3

## U114688 VMCU Communication Fault - AN (4) - PR (4) - VN (4)

Published 6 July 2026

### Valid For

Mack Chassis - AN (4), PR (4)

Volvo Chassis - VN (4)

Model Year - 2024 to current.

The purpose of this CBR is to provide guidance on fault code U114688.

### Overview

When fault code U114688 is active please follow steps listed below:

1. Ensure the truck has been updated to Service Pack 6.0 for Volvo or 3.0 for Mack. The new software allows the fault to self-heal.
  - a. If fault code **does not** return, release unit back to service.
  - b. If fault code **does** return please use PTT to diagnose fault.

### Related links and attachments

No links or attachments available



#### Share

to others that might find it helpful



#### Feedback

[Give feedback](#)

to help improve the content of this article