

	SERVICE BULLETIN	Issue no.	RE-IB-SB-93
		Issue date	7 th April 2026
		Page No	Page 1 of 2
SUBJECT	MODIFICATION IN SIDE STAND ASSEMBLY		
APPLICABLE MODELS	HIMALAYAN 450		

This Service Bulletin is to inform about the change in the side stand assembly dimensions.

Reason: Continuous improvement

Modification: Side stand dimension changed to reduce the Motorcycle Lean angle from 19.4 Degrees to 13.8 degrees

Before Modification	After Modification
	

Parts Details and Interchangeability Information

SI #	Part Description	Models	Action			Qty .	Inter changeable	Remarks
			Addition	Deletion	Modification			
1	SIDE STAND	HIMALAYAN 450		RAW00401/H	RAW00511/B	1	Y	

Cut-Off Details:

ZONE	FRAME NUMBER	ENGINE NUMBER	MODEL
EUROPE	ME3TKKGT6TK002244	K5W6FAT1021611	HIMALAYAN 450
APAC	ME3TKKGT6TK002316	K5W6FAT1021552	HIMALAYAN 450
LATAM	ME3TKKGT6TK002120	K5W6FAT1021223	HIMALAYAN 450
MEA	ME3TKKGT6TK002365	K5W6FAT1021848	HIMALAYAN 450
North America	ME3BGK405TK501784	K5W6FAT1021596	HIMALAYAN 450
Brazil	95V6P1C2TTM002433	K5W6FATC010848	HIMALAYAN 450
SAARC	ME3K5A6FMSN000020-NEPAL	K5W6FMS1001819	HIMALAYAN 450
ARGENTINA & COLOMBIA	VIN details shall be shared separately		HIMALAYAN 450

Royal Enfield (A Unit of Eicher Motors Ltd.)

Thiruvottiyur High Road | Thiruvottiyur | Chennai - 600019 | Tamil Nadu | India


	SERVICE BULLETIN	Issue no.	RE-IB-SB-93
		Issue date	7th April 2026
		Page No	Page 2 of 2
SUBJECT	MODIFICATION IN SIDE STAND ASSEMBLY		
APPLICABLE MODELS	HIMALAYAN 450		

Action Required:

- No action required on customer motorcycles and stock motorcycles.
- No action is required for the existing spares parts in the stock

Applicable Countries: All countries, except Bangladesh, Argentina and Colombia.

Please update your Spare Parts master and request to share this information to all the concerned.



Head-Service & Parts (International Business)