

Technical Service Bulletin (TSB) Windshield Wiper Blade Flipped

REFERENCE:	TSB: 23-044-26 REV. A GROUP: 23 - Body	Date:	September 25, 2026	REVISION:	23-044-26
VEHICLES AFFECTED:	2026 (JL) Jeep Wrangler This bulletin applies to vehicles built on or after **January 08, 2026 (MDH 0108XX)** and on or before June 17, 2026 (MDH 0617XX) equipped with Right Hand Drive (Sales Code 519).			MARKET APPLICABILITY: ☒ NA☒ MEA ☐ SA☒ IAP ☐ EE☐ CH NOTE: This bulletin applies to North America, India & Asia Pacific and Middle East & Africa markets.	
CUSTOMER SYMPTOM:	Customers must experience one or more of the following: - Streaking wiper blade. - Buzz, squeak or rattle from the outer side of wiper blade on the glass.				
CAUSE:	Incorrect installation				

This bulletin supersedes Technical Service Bulletin (TSB) 23-044-26, date of issue September 17, 2026, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an updated build date.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-170, date of issue September 17, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves replacing the driver's side windshield wiper blade.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-43-45-91	Blade, Windshield Wiper - Replace (0 - Introduction)	6 - Electrical and Body Systems	0.1 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	68752616AA	Windshield Wiper Blade	

DIAGNOSIS:

If a customers VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

REPAIR PROCEDURE:

1. Replace the windshield wiper. Refer to the detailed procedures available DealerCONNECT > Service Library> under: 08 - Electrical / 8R - Wipers/Washers / Blade, Wiper / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.