



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100079

Date Received

2003 MAR 27
13-FEB-2003

Repository ☐

Reference No.
10007387

OWNER INFORMATION (Type or Print)

Name

Address

City

NEOSHO

State MO

Zip Code

Daytime Telephone Number

Evening Telephone Number

E-mail Address

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☐ YES ☒ NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner

Date

VEHICLE INFORMATION

Make
FORD

Model
ESCORT

Model Year
1991

Date Purchased

Dealer's Name and Telephone Number

Engine:
No. Cylinders

Fuel Type:

Original Owner

Dealer's City

State

Zip Code

Transmission Type

☐ Antilock Brakes

Powertrain

☐ Cruise Control

Vehicle Component Code
116000 ELECTRICAL SYSTEM:IGNITION

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)

12-FEB-2003

Failure Mileage

Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19A BC036)

☐ Original Equipment
☒ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

Number of Deaths

Reported to Police

N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure, i.e., parts repaired or replaced (and if old part is available).

THE IGNITION SWITCH WAS STUCK IN ONE POSITION. POSSIBLY RELATED TO RECALL 93V057000.*JB

Include, if available: Police/Police Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.