



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236) **2003 JUN - 4 AM 9:30**
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100079

Date Received

Repository ☐

Reference No.
10017468

OWNER INFORMATION (Type or Print)

Name

Address

City HARLBORO

State NJ

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☒ YES ☐ NO
In the absence of your signature, please provide your name or address to the vehicle manufacturer.
Signature of Owner Date 5/16/03

VEHICLE INFORMATION

Make BUICK		Model CENTURY		Model Year 2000	
Date Purchased		Dealer's Name and Telephone Number		Engine: No. Cylinders	
Original Owner ☐		Dealer's City		State Zip Code	
Transmission Type ☐ Antilock Brakes ☐ Cruise Control		Powertrain		Vehicle Component Code 060000 ENGINE AND ENGINE COOLING	
Multiple Failure:					

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) 23-APR-2003	Failure Mileage	Failure Speed
---------------------------------	-----------------	---------------

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: 50TMA19ABC036)	☐ Original Equipment ☐ Prior Repair	Failure Location:
Tire Component Code		Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(es).)

Crash ☐ Yes ☒ No	Fatality ☐ Yes ☒ No	Number of Persons Injured	Number of Deaths	Reported to Police N
--	---	---------------------------	------------------	-------------------------

Alternative Description of Incident(s), Crash(es), and Injury(es).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure;
i.e., parts repaired or replaced (and if old part is available).

THE VEHICLE OVER HEATED WHILE DRIVING. THE VEHICLE WAS TAKEN TOT HE DEALER WHO STATED THAT THE INTAKE MANIFOLD BROKE AND CAUSED OIL TO LEAK INTO THE COOLING SYSTEM. *NLM

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY.

This Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.