



U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100145

Date Received

Repository

28-JUL-2004 08:01 AM

Reference No. 10083558

OWNER INFORMATION (Type or Print)

Name

Address

City SAN ANTONIO

State TX

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to use your information in the absence of your signature?
Signature of Owner

or vehicle? YES NO
the vehicle manufacturer.
28/12/04

17 digit Vehicle Identification Number located at bottom of windshield on driver's side

1G2NF12T41K

Make

PONTIAC

Model

GRAND AM

Model Year

2001

Date Purchased

Dealer's Name and Telephone Number

Engine:

No: Cylinders

Fuel Type:

Original Owner

Dealer's City

State

Zip Code

Transmission Type

AUTOMATIC

Antilock Brakes

Cruise Control

Powertrain

Vehicle Component Code

128100 EXTERIOR LIGHTING:TURN SIGNAL/FLASHER UNIT

Multiple Failure: 10

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)
15-JUL-2004

Failure Mileage
83000

Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/85R15)

DOT No. (Example: DOTM18ABC038)

Original Equipment
 Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

Yes No

Fire

Yes No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

Y

Narrative Description of Incident(s), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure, i.e. parts repaired or replaced (and if old part is available).

TURN SIGNAL FLASHER FAILED. AS A RESULT, WHEN ATTEMPTING TO TURN LEFT WITH THE TURN INDICATOR FAILING VEHICLE WAS REAR ENDED. *AK

Also on or about 2002, of June i was attempting to make a left turn as i was getting off the expressway on I10 west off of culebra i came to a midway of completing the turn as a car scrapes my whole frontend of the vehicle because he apperently did not see my turn signal and i had the car repaired and the cost was 1,100 with new bumper.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect, if the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.