

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

②. Third incident: Aug 7, 04, 27,000 mile. Vehicle shook uncontrollably at 60 mph. Drove to Bill Ray Nissan. Dealer confirmed right rear tire bubble. Dealer installed new tire.

Summary: All four tires were original tires installed by manufacturer. All incident occurred on the same tires at about 7000 miles apart from previous incident. Reported incidents/tire failure to Nissan on Aug 9, 04. No response from Nissan after repeated phone calls. (Though Nissan said normal response time was 4 business days.) Nissan case ID#: 4641759

ATTACH ADDITIONAL SHEETS IF NECESSARY

US Department of Transportation
National Highway Traffic Safety Administration
400 Seventh St., S.W.
Washington, D.C. 20590
Official Business
Penalty for Private Use \$300




NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL. HWY. TRAFFIC SAFETY ADMIN.

U.S. Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NVS-216
400 7th Street, SW
Washington, DC 20590



US Department of Transportation
National Highway Traffic Safety Administration
<http://www.safercar.gov>

DOT Auto Safety Hotline
(DASH) & DOT

1-888-DASH-2-DOT
1-888-327-4236

and dial toll free at

DASH2DOT

TO REPORT VEHICLE SAFETY DEFECTS
COMPLETE THIS FORM
OR

DOT AUTO SAFETY HOTLINE

**VEHICLE
OWNER'S
QUESTIONNAIRE**

**THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).**