

Type: Customer E-mail
From: [REDACTED]
To: webmaster@nhtsa.dot.gov
Subject: Chevy Malibu Maxx 2004 Steering Wheel

Received 1/18/05

10127998

On aug 4/13/27/ sep.28/ nov.23 2004 MY CAR WAS AT THE DEALER,MARTIN CHEVROLET, FOR:
(ACCORDING TO WORKORDERS)

"THE VEHICLE PULLS LEFT ON TAKE OFF FROM A STOP AND ALSO DRIFTS LEFT WHILE DRIVING,
TAKE OFF HANDS OF THE WHEEL, OFFCENTER TO THE LEFT "

UNTIL NOW PROBLEM NOT SOLVED,IN LAST VISIT TO DEALER,NOV.23,SERVICE MANAGER
SUGESTED TO TRY OTHER DEALER,ALSO, THIS IS THE WAY THIS CAR DRIVES.

WHAT CAN I DO?

[REDACTED]

*WPK
aab
7/1/05*