



7-18-05  
E 1-349-697-774  
866-432-4366  
EXT 35255  
CYNTHIA WALLACE

# PONTIAC · GMC

Division of General Motors Corporation

RECEIVED  
5/26/05

May 2005

Dear GMC Customer:

Part of our commitment to you as a member of the GM family is giving you important information whenever a specific concern or problem may affect your vehicle.

Recently the media reported that General Motors will be announcing a safety recall involving certain 2001 model year GMC Yukon XL vehicles.

On some of these vehicles, the fuel module reservoir assembly that contains the fuel pump wires and/or connectors may overheat under certain operating conditions. This condition may result in one or more of the following conditions: 1) an engine stall or no-start condition due to a blown fuse, 2) inaccurate fuel level readings, and/or, 3) a Service Engine Soon light. A Service Engine Soon light may be an indication that fuel vapor, or in some cases liquid fuel, may leak out of the top of the fuel tank when the fuel level is above  $\frac{3}{4}$  full.

At this time, we are working with our suppliers to develop and obtain a service kit to permanently correct this condition as quickly as possible. Until parts become available, if you smell fuel or experience any of the conditions listed above, please contact your GMC dealer to arrange a service appointment as soon as possible.

If the condition is due to overheated wiring in the fuel module reservoir assembly, your dealer will repair your vehicle with the existing service parts. As service kits become available, we will send you another letter asking you to take your vehicle to your GMC dealer and have your vehicle repaired with the new service kit. If you have any questions or need any assistance, please call the GMC Customer Assistance Center between the hours of 8:00 AM and 11:00 PM, EST, Monday through Friday. They can be reached at 1.866.996.9483. The deaf, hearing impaired, or speech impaired should call Text Telephone (TTY), 1.800.462.8583.

We understand the concern this situation may cause and the need to correct it as quickly as we can. We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Pontiac-GMC Division  
General Motors Corporation

Enclosure  
05027



Recall Processing Center  
 P.O. Box 909989  
 Milwaukee, WI 53209-9989



MAIL THIS FORM ONLY if any of the items below apply to this vehicle. This will help us in contacting the present owner/lessee and ensure that you do not continue to receive notifications for this vehicle.

**CHECK (X) APPROPRIATE BOX.**

My new address OR Vehicle sold/traded to:

Owner Name \_\_\_\_\_

Address \_\_\_\_\_

City, State, Zip \_\_\_\_\_

Phone (\_\_\_\_) \_\_\_\_\_

I have never owned/leased this vehicle.

Vehicle was damaged beyond repair and scrapped.

Vehicle was stolen and not recovered.

Other: \_\_\_\_\_

By providing the information above you are authorizing an update to our records for this vehicle.



CLEARWATER, FL

**CUSTOMER REPLY FORM**

To mail: Fold so the return address on the back of this panel is showing. Place a piece of tape on each of the shorter ends to seal the mailer.

THE ATTACHMENTS TO THIS  
DOCUMENT HAVE BEEN REMOVED  
TO PROTECT UNWARRANTED  
INVASION OF PERSONAL PRIVACY  
PURSUANT TO EXEMPTION 6 OF  
THE FREEDOM OF INFORMATION  
ACT (FOIA), 5 U.S.C. 552(b)(6).