

NHTSA Ref.
F.Y.T.

[REDACTED]
Antioch, Ca. [REDACTED]

Attachment 1

10133472

1st Incident - Report 836192 - Claim "A" - 6/25/05 at approximately 11:30am.

Driving south on highway 99 in middle lane at approximately 65mph. Shortly before the Briggsmore exit in Modesto, the front left tire came apart. I veered into the fast lane momentarily, then gained control and worked my way over to the shoulder. AAA towing put my spare on front left side of vehicle.

2nd Incident - Report 836192 - Claim "B" - 6/27/05 at approximately 11:00am.

Driving north on highway 99 in slow lane at approximately 60mph. A mile or so before the Hammer Lane exit in Stockton, the rear left tire came apart. I pulled over to the shoulder right away. AAA towing carried my F250 to Firestone dealer at 720 E. Hammer Lane, Stockton, Ca. 95210.

Firestone Service Advisor Phil, @209.951.2403, said he was not qualified to analyze the damage to my two Steeltex tires but wanted to sell me new tires at retail price without prorating damaged tires.

This attachment accompanies my claim forms and the damaged tires.

I was forced to file a claim with my insurance company in order to get my vehicle repaired into safe working order by August. We have a prepaid vacation scheduled and need the truck for towing.

(1)


8/3/05 11:52

WAR
adg
8/3/05

COMMENT: Should my claim even be approved, it would have left my truck unsafe to drive for at least two months. That is unacceptable. It's too bad that you cannot hire or train a qualified tire inspector on the West Coast. One that would be a knowledgeable, experienced employee, whose judgment you trust, to evaluate and assess damaged tires here and report back to BENT, LLC in Nashville.

SPECIAL NOTE: Should my claim be denied, please return damaged tires and pictures to me as soon as possible. I realize I will be responsible for shipping charges.

Sincerely,

A black rectangular redaction box covering the signature area.

Attachments (Pictures)

cc: John Lampe
James Padilla
NHTSA ✓



A

Time and Place	Date of Incident 6/25/05	Time 11:00 AM/PM	Exact Location Where Incident Occurred HWY 99 MODESTO SOUTH	
Customer Vehicle	Vehicle Make FORD	Year 2001	Model F250	Mileage 39,701
	Owner of Auto			
	Address		City ANTIOCH	State CA.
	Driver		Minor Yes ☐ No ☒	Telephone Number
	Address		City ANTIOCH	State CA
	Passenger (List All)		Minor Yes ☐ No ☐	Telephone Number
	Address		City	State Zip Code
	Vin Number 1FTNX21F91E		Trailer Hitch? Yes ☒ No ☐	
	Vehicle Usage: Recreational ☐ Personal ☒ Commercial ☐		What is towed? No	
	Is this a motorhome or conversion van? Yes ☐ No ☒ Has the vehicle been modified? Yes ☐ No ☒ If Yes? What is Model? If so, how?			
Property Damage to Customer's Car	Did the vehicle rollover? Yes ☐ No ☒		Was the vehicle involved in a crash? Yes ☐ No ☒	
	Damage to Customer Vehicle SEE ATTACHED ESTIMATES		Estimated Cost \$2,630.96	
	Have you submitted this to your insurance company? Yes ☒ No ☐			
	Are you planning to submit this claim to insurance company? Yes ☒ No ☐			
	Has your vehicle been repaired? Yes ☐ No ☒ DEDUCTIBLE AMOUNT \$ 50.00			
	Customer Insurance Co. (Please include telephone number) AAA 888-582-3008 EXT. 7179			
Property Damage to Other Car (If applicable)	Was another Vehicle involved? Yes ☐ No ☒		Name and Address	
	Damage		Estimated Cost	
	Does Owner of Vehicle Have Insurance? Yes ☐ No ☐	Covering Damages to Car? Yes ☐ No ☐	Covering Damages to Other Car? Yes ☐ No ☐	
	Other Property Damage			
Injury?	Was Anyone Injured? Yes ☐ No ☒		If Yes, Nature of Injury	
Tire Data (If Available)	Tire Size LT 265/75R16		Pattern Name STEELTEX RADIAL A/T	Position Mounted LEFT FRONT
	DOT Number (10 or 11 digit # located on sidewall) VNW8 1XL 4900		Mileage on Tire 39,701	
Description Of Incident	SEE ATTACHMENT 1 + PICTURES			
Signature of Customer CUSTO			Date Signed 7/7/05	

OR PROCESSING

ATTACHMENT IR 836192 'A'

1 of 2

Date: 6/28/2005 12:25 PM
Estimate ID: 465
Estimate Version: 0
Preliminary
Profile ID: ANTIOCH

Antioch Auto Body, Inc.

1401 Verne Roberts Circle EMAIL: bodytech@sbcglobal.net Antioch, CA 94509-7915
(925) 757-3586

Fax: (925) 757-5246

Tax ID: 68-0336031 BAR #: AK236169 EPA #: CAR000004440

Damage Assessed By: Sergio Gonzalez

Deductible: 0.00
Claim Number: 465

Insured: [REDACTED]
Address: [REDACTED] ANTIOCH, CA [REDACTED]
Telephone: [REDACTED] Work Phone: [REDACTED] Home Phone: [REDACTED]

Mitchell Service: 914624

Description: 2001 Ford Pickup F250 XLT
Body Style: 2D PkUpXCb 8' Bed 158" WB
VIN: 1FTNX21F91E [REDACTED]
Mileage: 39,853
OEM/ALT: O

Drive Train: 7.3L Turbo Inj 8 Cyl Dsl 4WD
License: [REDACTED]

Search Code: None

Color: DK GREEN

Options: 4WD OR AWD, ALUM/ALLOY WHEELS, AIR CONDITIONING, POWER WINDOWS, POWER DOOR LOCKS
CRUISE CONTROL, AUTOMATIC TRANSMISSION, XLT (F PICKUP)
AM-FM STEREO/CDPLAYER(SINGLE)

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	400001	BDY	REMOVE/INSTALL	FRT BUMPER ASSY			INC
2	AUTO	BDY	OVERHAUL	FRT BUMPER ASSY			1.5
3	403326	BDY	REMOVE/REPLACE	FRT UPR BUMPER VALANCE PANEL	1C3Z 17626 AAD	97.52	INC
4	900500	BDY *	REPAIR	ALIGN SUSPENSION	Sublet	89.99 *	0.0*
5	402683	BDY	REMOVE/REPLACE	FRT LWR BUMPER VALANCE PANEL	3C3Z 17626 AAA	68.12	INC
6	402395	BDY	REMOVE/REPLACE	L FRT BUMPER SUPPORT	F81Z 17752 AD	46.45	INC
7	407570	BDY	REMOVE/INSTALL	L FRT COMBINATION LAMP			0.4 #
8	400265	BDY	REPAIR	L FENDER PANEL	Existing		3.0* #
9	AUTO	REF	REFINISH	L FENDER OUTSIDE			C 2.3
10	400267	BDY	REMOVE/REPLACE	L FENDER LINER	5C7Z 16055 AA	72.10	0.4
11	400323	MCH	REMOVE/REPLACE	L ABS FRT SENSOR -M	F81Z 2C204 BB	138.92	0.5 #
12	402788	BDY	REMOVE/REPLACE	WHEEL	4C3Z 1007 RA	355.45	0.3
13	900500	BDY *	REMOVE/INSTALL	BUGSHIELD	Existing		0.5*
14	900500	BDY *	REMOVE/INSTALL	GRILLE GUARD	Existing		1.0*
15	403254	BDY	REMOVE/REPLACE	L STEP RAIL ASSEMBLY	3C3Z 16451 BAA	268.27	0.4
16	900500	BDY *	ADD'L LABOR OP	MOUNT AND BALANCE - PER TIRE	Sublet	15.00 *	0.0*
17	900500	BDY *	REMOVE/REPLACE	MASK FOR OVERSPRAY	**Qual Repl Part	5.00 *	0.1*
18	900500	BDY *	REMOVE/REPLACE	MUDGUARD	**Qual Repl Part	50.00 *	0.3*
19	900500	BDY *	REPAIR	PINSTRIPES	Sublet	45.00 *	0.0*
20	401135	REF	BLEND	L FRT DOOR OUTSIDE			C 1.1

ESTIMATE RECALL NUMBER: 6/28/2005 12:15:10 465

UltraMate is a Trademark of Mitchell International

Mitchell Data Version: MAY_05_A
UltraMate Version: 5.0.206

Copyright (C) 1994 - 2003 Mitchell International
All Rights Reserved

Page 1 of 3

Date: 6/28/2005 12:25 PM
 Estimate ID: 465
 Estimate Version: 0
 Preliminary
 Profile ID: ANTIOCH

21	401155	BDY	REMOVE/INSTALL	L FRT DOOR POWER MIRROR			0.7 #
22	402543	BDY	REMOVE/REPLACE	L FRT DOOR ADHESIVE MOULDING	1C3Z 2820879 AAF	46.47	0.2
23	401264	BDY	REMOVE/INSTALL	L FRT OTR DOOR BELT MOULDING	Existing		0.2*
24	405215	BDY	REMOVE/REPLACE	L FRT DOOR ADHESIVE NAMEPLATE	3C3Z 9942528 DA	39.30	0.2
25	401193	BDY	REMOVE/INSTALL	L FRT DOOR TRIM PANEL			INC
26	401209	BDY	REMOVE/INSTALL	L FRT OTR DOOR HANDLE			0.6 #
27	936012		ADD'L COST	HAZARDOUS WASTE DISPOSAL		3.00 *	
28	AUTO	REF	ADD'L OPR	CLEAR COAT			1.2*
29	AUTO		ADD'L COST	PAINT		138.00 *	

* - Judgement Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

I. Labor Subtotals						II. Part Replacement Summary			Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				
Body	9.8	70.00	0.00	149.99	835.99	Taxable Parts			1,187.60
Refinish	4.6	70.00	0.00	0.00	322.00	Sales Tax	@	8.250%	97.98
Mechanical	0.5	70.00	0.00	0.00	35.00	Total Replacement Parts Amount			1,285.58
Non-Taxable Labor					1,192.99				
Labor Summary					14.9				
					1,192.99				
III. Additional Costs					Amount	IV. Adjustments			Amount
Taxable Costs					138.00	Insurance Deductible			0.00
Sales Tax					@ 8.250% 11.39	Customer Responsibility			0.00
Non-Taxable Costs					3.00				
Total Additional Costs					152.39				
						I. Total Labor:			1,192.99
						II. Total Replacement Parts:			1,285.58
						III. Total Additional Costs:			152.39
						Gross Total:			2,630.96
						IV. Total Adjustments:			0.00
						Net Total:			2,630.96

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE PARTS, RATHER THAN BY THE ORIGINAL MANUFACTURER OF YOUR VEHICLE.

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Insurance Co: CASH
 ESTIMATE RECALL NUMBER: 6/28/2005 12:15:10 465
 Mitchell Data Version: MAY_05_A
 UltraMate Version: 5.0.206
 UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 2003 Mitchell International
 All Rights Reserved

Date: 6/28/2005 12:22 PM
Estimate ID: 1
Estimate Version: 0
Preliminary
Profile ID: CSAA FOR

"New" parts (OEM) unless otherwise specified. Parts described as Rechromed, Recored, or Remanufactured are either "Reconditioned" parts or "Rebuilt" parts. Crash parts described as "Qual Repl Part" are non-OEM aftermarket parts.**

ESTIMATE RECALL NUMBER: 6/28/2005 12:22:41 1

Mitchell Data Version:
UltraMate Version:

MAY_05_A
5.0.206

UltraMate is a Trademark of Mitchell International
Copyright (C) 1994 - 2003 Mitchell International
All Rights Reserved

Page 3 of 3

ATTACHMENT TR 836192 'A+B'

Date: 6/28/2005 11:36 AM
 Estimate ID: 46
 Estimate Version: 0
 Preliminary
 Profile ID: MIKE'S AUTO BODY

Mike's Auto Body

1610 West 10th Street Antioch, CA 94509
 (925) 778-1330
 Fax: (925) 754-5426
 Tax ID: 942621349 EPA #: EPACAR000004317

Damage Assessed By: DONNY HERBERT

Condition Code: Good
 Deductible: UNKNOWN

Insured: [REDACTED]
 Address: [REDACTED] ANTIOCH, CA [REDACTED]
 Telephone: Work Phone: [REDACTED] Home Phone: [REDACTED]

Mitchell Service: 914624

Description: 2001 Ford Pickup F250 XLT
 Body Style: 2D PkUpXCb 8' Bed 158" WB
 VIN: 1FTNX21F91E [REDACTED]
 Mileage: 39,852
 Color: GREEN MET
 Options: 4WD OR AWD, ALUM/ALLOY WHEELS, AIR CONDITIONING, POWER STEERING, POWER BRAKES
 POWER WINDOWS, POWER DOOR LOCKS, CRUISE CONTROL, AUTOMATIC TRANSMISSION
 XLT (F PICKUP), POWER DRIVER SEAT, AM-FM STEREO/CDPLAYER(SINGLE)
 POWER REMOTE MIRROR, POWER SEATS

Vehicle Production Date: 12/00
 Drive Train: 7.3L Turbo Inj 8 Cyl Dsl 4WD
 License: [REDACTED]

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	402683	BDY	REMOVE/REPLACE	FRT LWR BUMPER VALANCE PANEL	3C3Z 17626 AAA	68.12	0.3
2	402395	BDY	REMOVE/REPLACE	L FRT BUMPER SUPPORT	F81Z 17752 AD	46.45	
3	402688	BDY	REMOVE/REPLACE	L FRT BUMPER BRACKET	1C3Z 17B750 AA	41.18	
4	400265	BDY	REPAIR	L FENDER PANEL	Existing		3.5*#
5	AUTO	REF	REFINISH	L FENDER OUTSIDE			C 2.3
6	400267	BDY	REMOVE/REPLACE	L FENDER LINER	5C7Z 16055 AA	72.10	0.4
7	402409	BDY	REMOVE/REPLACE	L FENDER INSULATOR	2C3Z 16E555 AA	81.88	
8	400281	BDY	REMOVE/REPLACE	L FENDER ADHESIVE NAMEPLATE	F81Z 16720 RA	23.88	0.2
9	403506	BDY	REMOVE/REPLACE	FRT MUDGUARD SET	**Qual Repl Part	30.00 *	0.2*
10	400323	MCH	REMOVE/REPLACE	L ABS FRT SENSOR -M	F81Z 2C204 BB	138.92	0.5 #
11	403705	BDY	REMOVE/REPLACE	WHEEL	2C3Z 1007 AA	297.63	0.3
12	401477	BDY	REPAIR	L PICKUP BED SIDE PANEL	Existing		8.0*#
13	AUTO	REF	REFINISH	L BED OUTER PANEL			C 3.4
14	401521	BDY	REMOVE/REPLACE	L FRT PICKUP BED SPLASH SHIELD	F81Z 9928370 AA	26.25	0.2
15	401515	BDY	REMOVE/REPLACE	L REAR PICKUP BED SPLASH SHIELD	F81Z 9928370 CA	34.43	0.2
16	401503	BDY	REMOVE/REPLACE	L FRT PICKUP BED BRACE	F81Z 9928260 AA	12.20	0.1
17	403154	BDY	REMOVE/REPLACE	L PICKUP BED DECAL	YC3Z 9925622 AAA	28.05	0.2
18	900500	BDY*	REMOVE/REPLACE	A/M TAPE STRIPES.	**Qual Repl Part	15.00 *	0.3*
19	403306	BDY	REMOVE/REPLACE	L PICKUP BED STONE SHIELD	F81Z 25292A22 AA	23.35	0.2
20	900500	BDY*	ADD'L LABOR OP	LT BED TIE DOWN HOOKS & STEP BAR.	Existing		1.0*

ESTIMATE RECALL NUMBER: 6/28/2005 11:36:08 46

Mitchell Data Version:
 UltraMate Version:

JUN_05_A
 5.0.206

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 2003 Mitchell International
 All Rights Reserved

Page 1 of 3

Date: 6/28/2005 11:36 AM
 Estimate ID: 46
 Estimate Version: 0
 Preliminary
 Profile ID: MIKE'S AUTO BODY

21	900500	BDY *	REMOVE/INSTALL	CAMPER SHELL	Existing		1.0*
22	401689	BDY	REMOVE/INSTALL	L REAR COMBINATION LAMP			0.2
23	401737	BDY	REMOVE/INSTALL	REAR BUMPER ASSY			0.6
24	900500	MCH*	ADD'L LABOR OP	ALIGNMENT - FOUR WHEEL	Sublet	90.00 *	0.0*
25	900500	BDY *	ADD'L LABOR OP	COVER CAR FOR OVERSPRAY	**Qual Repl Part	10.00 *	0.2*
26	900500	BDY *	ADD'L LABOR OP	MOUNT/BALANCE (OVER 16")	Sublet	20.00 *	0.0*
27	900500	BDY *	REMOVE/REPLACE	LT SIDE STEP BAR (CHROME)	New	318.31 *	1.0*
28	AUTO	REF	ADD'L OPR	CLEAR COAT			1.6
29	933003	REF	ADD'L OPR	TINT COLOR			0.5*
30	AUTO		ADD'L COST	PAINT/MATERIALS		249.60 *	
31	AUTO		ADD'L COST	HAZARDOUS WASTE DISPOSAL		3.50 *	

* - Judgement Item

- Labor Note Applies

C - Included in Clear Coat Calc

I. Labor Subtotals						II. Part Replacement Summary				Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	Taxable Parts				
Body	18.1	75.00	0.00	20.00	1,377.50	Sales Tax	@	8.250%	1,267.75	
Refinish	7.8	75.00	0.00	0.00	585.00				104.59	
Mechanical	0.5	75.00	0.00	90.00	127.50					
Non-Taxable Labor					2,090.00	Total Replacement Parts Amount				1,372.34
Labor Summary	26.4				2,090.00					
III. Additional Costs					Amount	IV. Adjustments				Amount
Taxable Costs					249.60	Customer Responsibility				0.00
Sales Tax					@ 8.250% 20.59					
Non-Taxable Costs					3.50					
Total Additional Costs					273.69					
						I. Total Labor:				2,090.00
						II. Total Replacement Parts:				1,372.34
						III. Total Additional Costs:				273.69
						Gross Total:				3,736.03
						IV. Total Adjustments:				0.00
						Net Total:				3,736.03

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

10 Left Front Side (P), 8 Left Rear Side (S)

ESTIMATE RECALL NUMBER: 6/28/2005 11:36:08 46

Mitchell Data Version:
 UltraMate Version:

JUN_05_A
 5.0.206

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 2003 Mitchell International
 All Rights Reserved

Page 2 of 3

I hereby authorize the above repair work to be done along with the necessary materials. The body shop may operate the above vehicle for purposes of testing, inspection or delivery. Glenn's auto body will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. Glenn's Auto Body unconditionally guarantee all workmanship including refinishing performed on your vehicle for as long as you own your car. This work order does not include any hidden or additional damage. All parts subject to invoice. If your vehicle is not picked up within 4 days of completion, there will be a storage fee of \$25.00 per day. Unless arrangements are made when vehicle is dropped off for repairs.

POWER OF ATTORNEY

That the undersigned does hereby constitute and appoint Glenn's Auto Body to sign my name, place and stead of the undersigned on any Insurance Checks or Drafts issued by (insurance co) _____ covering any repairs to my (or our) automobile authorized by myself (or ourselves) in whatever manner is necessary to place check or draft in a cashable position.

SIGNED _____ DATED _____



B

Time and Place	Date of Incident 6/27/05	Time 11:25 ^{AM} PM	Exact Location Where Incident Occurred HWY 99 STOCKTON NORTH	
Customer Vehicle	Vehicle Make FORD	Year 2001	Model F250	Mileage 39,879
	Owner of Auto			
	Address		City ANTIOCH	State CA.
	Drive		Minor Yes ☐ No ☒	
	Address		City ANTIOCH	State CA.
	Passenger (List All)		Minor Yes ☐ No ☐	Telephone Number
	Address		City	State Zip Code
	Vin Number 1FTNX21F91E		Trailer Hitch? Yes ☒ No ☐	
	Vehicle Usage: Recreational ☐ Personal ☒ Commercial ☐		What is towed? YES	
	Is this a motorhome or conversion van? Yes ☐ No ☒ Has the vehicle been modified? Yes ☐ No ☒ If Yes? What is Model? If so, how?			
Property Damage to Customer's Car	Did the vehicle rollover? Yes ☐ No ☒		Was the vehicle involved in a crash? Yes ☐ No ☒	
	Damage to Customer Vehicle SEE ATTACHED ESTIMATES			Estimated Cost \$1,703.22
	Have you submitted this to your insurance company? Yes ☒ No ☐			
	Are you planning to submit this claim to insurance company? Yes ☒ No ☐			
	Has your vehicle been repaired? Yes ☐ No ☒ DEDUCTIBLE AMOUNT \$ 50.00			
	Customer Insurance Co. (Please include telephone number) AAA 888-582-3008 EXT. 7179			
Property Damage to Other Car (If applicable)	Was another Vehicle involved? Yes ☐ No ☒		Name and Address	
	Damage			Estimated Cost
	Does Owner of Vehicle Have Insurance? Yes ☐ No ☐	Covering Damages to Car? Yes ☐ No ☐	Covering Damages to Other Car? Yes ☐ No ☐	
	Other Property Damage			
Injury?	Was Anyone Injured? Yes ☐ No ☒		If Yes, Nature of Injury	
Tire Data (If Available)	Tire Size LT265/75R16		Pattern Name STEECTEX RADIAL A/T	Position Mounted LEFT REAR
	DOT Number (10 or 11 digit # located on sidewall) VNW8 1XL 4900			Mileage on Tire 39,879
Description Of Incident	SEE ATTACHMENT 1 + PICTURES			
Signature of Customer CUSTOMER			Date Signed 7/7/05	

PROCESSING

Date: 6/28/2005 12:22 PM
 Estimate ID: 1
 Estimate Version: 0
 Preliminary
 Profile ID: CSAA FOR

Antioch Auto Body, Inc.

1401 Verne Roberts Circle EMAIL: bodytech@sbcglobal.net Antioch, CA 94509-7915
 (925) 757-3586

Fax: (925) 757-5246

Tax ID: 68-0336031 BAR #: AK236169 EPA #: CAR000004440

Damage Assessed By: Sergio Gonzalez

Deductible: 0.00
 Claim Number: 1

Insured: [REDACTED]
 Address: [REDACTED] ANTIOCH, CA [REDACTED]
 Telephone: [REDACTED] Work Phone: [REDACTED] Home Phone: [REDACTED]

Mitchell Service: 914624

Description: 2001 Ford Pickup F250 XLT
 Body Style: 2D PkUpXCb 8' Bed 158" WB
 VIN: 1FTNX21F91E [REDACTED]
 Mileage: 39,853
 OEM/ALT: A
 Color: DK GREEN
 Options: 4WD OR AWD, ALUM/ALLOY WHEELS, AIR CONDITIONING, POWER WINDOWS, POWER DOOR LOCKS
 CRUISE CONTROL, AUTOMATIC TRANSMISSION, XLT (F PICKUP)
 AM-FM STEREO/CDPLAYER(SINGLE)

Drive Train: 7.3L Turbo Inj 8 Cyl Dsl 4WD
 License: [REDACTED]

Search Code: C316475

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	401473	BDY	REMOVE/INSTALL	BED ASSEMBLY			2.5
2	401477	BDY	REPAIR	L PICKUP BED SIDE PANEL	Existing		10.0* #
3	AUTO	REF	REFINISH	L BED OUTER PANEL			C 3.6
4	401480	BDY	REMOVE/INSTALL	L PICKUP BED FUEL DOOR	Existing		0.2*
5	401521	BDY	REMOVE/REPLACE	L FRT PICKUP BED SPLASH SHIELD	F81Z 9928370 AA	26.25	0.2
6	401515	BDY	REMOVE/REPLACE	L REAR PICKUP BED SPLASH SHIELD	F81Z 9928370 CA	34.43	0.2
7	900500	BDY *	REMOVE/REPLACE	MUDGUARD	**Qual Repl Part	50.00 *	0.3*
8	405570	BDY	REMOVE/REPLACE	L PICKUP BED DECAL	3C3Z 16720 AAB	44.35	0.2
9	402667	BDY	REMOVE/REPLACE	L PICKUP BED RAIL MOULDING	1C3Z 99291A41 AAA	83.07	0.4
10	403306	BDY	REMOVE/REPLACE	L PICKUP BED STONE SHIELD	F81Z 25292A22 AA	23.35	0.2
11	401689	BDY	REMOVE/INSTALL	L REAR COMBINATION LAMP			0.2
12	900500	BDY *	REMOVE/INSTALL	CAMPER SHELL	Existing		1.0*
13	900500	BDY *	REMOVE/INSTALL	TIE DOWNS	Existing		1.0*
14	900500	BDY *	REMOVE/INSTALL	BEDLINER	Existing		0.5*
15	900500	BDY *	REPAIR	DECAL PINSTRIPES	Sublet	45.00 *	0.0*
16	900500	BDY *	REMOVE/REPLACE	MASK FOR OVERSPRAY	**Qual Repl Part	5.00 *	0.1*
17	401737	BDY	REMOVE/INSTALL	REAR BUMPER ASSY			INC
18	936012		ADD'L COST	HAZARDOUS WASTE DISPOSAL		3.00 *	
19	AUTO	REF	ADD'L OPR	CLEAR COAT			1.4
20	933003	BDS *	ADD'L OPR	TINT COLOR			0.5*
21	AUTO		ADD'L COST	PAINT		130.00 *	

ESTIMATE RECALL NUMBER: 6/28/2005 12:22:41 1

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 2003 Mitchell International
 All Rights Reserved

Mitchell Data Version: MAY_05_A
 UltraMate Version: 5.0.206

Page 1 of 3

* - Judgement Item
- Labor Note Applies
C - Included in Clear Coat Calc

I. Labor Subtotals						II. Part Replacement Summary			
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				Amount
Body	17.0	55.00	0.00	45.00	980.00	Taxable Parts			266.45
Bdy-S	0.5	55.00	0.00	0.00	27.50	Parts Adjustments			10.57-
Refinish	5.0	55.00	0.00	0.00	275.00	Sales Tax	@	8.250%	21.11
Non-Taxable Labor					1,282.50	Total Replacement Parts Amount			276.99
Labor Summary	22.5				1,282.50				
III. Additional Costs					Amount	IV. Adjustments			
Taxable Costs					130.00	Insurance Deductible			
Sales Tax					10.73	Customer Responsibility			
Non-Taxable Costs					3.00				
Total Additional Costs					143.73				
						I.	Total Labor:		1,282.50
						II.	Total Replacement Parts:		276.99
						III.	Total Additional Costs:		143.73
							Gross Total:		1,703.22
						IV.	Total Adjustments:		0.00
							Net Total:		1,703.22

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE PARTS, RATHER THAN BY THE ORIGINAL MANUFACTURER OF YOUR VEHICLE.

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Insurance Co: CASH

Body Shop: ANTIOCH AUTO BODY INC.
1401 VERNE ROBERTS CIRCLE
ANTIOCH, CA 94509
Telephone: (925) 757-3586
Fax Phone: (925) 757-5246

****Special Parts Note:** All crash parts on this estimate are

ESTIMATE RECALL NUMBER: 6/28/2005 12:22:41 1

Mitchell Data Version:
UltraMate Version:

MAY_05_A
5.0.206

UltraMate is a Trademark of Mitchell International
Copyright (C) 1994 - 2003 Mitchell International
All Rights Reserved

Date: 6/28/2005 12:22 PM
Estimate ID: 1
Estimate Version: 0
Preliminary
Profile ID: CSAA FOR

"New" parts (OEM) unless otherwise specified. Parts described
as Rechromed, Recored, or Remanufactured are either
"Reconditioned" parts or "Rebuilt" parts. Crash parts described
as "Qual Repl Part" are non-OEM aftermarket parts.**

ESTIMATE RECALL NUMBER: 6/28/2005 12:22:41 1

Mitchell Data Version:
UltraMate Version:

MAY_05_A
5.0.206

UltraMate is a Trademark of Mitchell International
Copyright (C) 1994 - 2003 Mitchell International
All Rights Reserved

Page 3 of 3

Date: 6/28/2005 11:36 AM
Estimate ID: 46
Estimate Version: 0
Preliminary
Profile ID: MIKE'S AUTO BODY

Mike's Auto Body

1610 West 10th Street Antioch, CA 94509
(925) 778-1330
Fax: (925) 754-5426
Tax ID: 942621349 EPA #: EPACAR000004317

Damage Assessed By: DONNY HERBERT

Condition Code: Good
Deductible: UNKNOWN

Insured: [REDACTED]
Address: [REDACTED] ANTIOCH, CA [REDACTED]
Telephone: Work Phone: [REDACTED] Home Phone: [REDACTED]

Mitchell Service: 914624

Description: 2001 Ford Pickup F250 XLT
Body Style: 2D PkUpXCb 8' Bed 158" WB
VIN: 1FTNX21F91E [REDACTED]
Mileage: 39,852
Color: GREEN MET
Options: 4WD OR AWD, ALUM/ALLOY WHEELS, AIR CONDITIONING, POWER STEERING, POWER BRAKES
POWER WINDOWS, POWER DOOR LOCKS, CRUISE CONTROL, AUTOMATIC TRANSMISSION
XLT (F PICKUP), POWER DRIVER SEAT, AM-FM STEREO/CDPLAYER(SINGLE)
POWER REMOTE MIRROR, POWER SEATS

Vehicle Production Date: 12/00
Drive Train: 7.3L Turbo Inj 8 Cyl Dsl 4WD
License: [REDACTED]

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	402683	BDY	REMOVE/REPLACE	FRT LWR BUMPER VALANCE PANEL	3C3Z 17626 AAA	68.12	0.3
2	402395	BDY	REMOVE/REPLACE	L FRT BUMPER SUPPORT	F81Z 17752 AD	46.45	
3	402688	BDY	REMOVE/REPLACE	L FRT BUMPER BRACKET	1C3Z 178750 AA	41.18	
4	400265	BDY	REPAIR	L FENDER PANEL	Existing		3.5*#
5	AUTO	REF	REFINISH	L FENDER OUTSIDE			C 2.3
6	400267	BDY	REMOVE/REPLACE	L FENDER LINER	5C7Z 16055 AA	72.10	0.4
7	402409	BDY	REMOVE/REPLACE	L FENDER INSULATOR	2C3Z 16E555 AA	81.88	
8	400281	BDY	REMOVE/REPLACE	L FENDER ADHESIVE NAMEPLATE	F81Z 16720 RA	23.88	0.2
9	403508	BDY	REMOVE/REPLACE	FRT MUDGUARD SET	**Qual Repl Part	30.00 *	0.2*
10	400323	MCH	REMOVE/REPLACE	L ABS FRT SENSOR -M	F81Z 2C204 BB	138.92	0.5 #
11	403705	BDY	REMOVE/REPLACE	WHEEL	2C3Z 1007 AA	297.63	0.3
12	401477	BDY	REPAIR	L PICKUP BED SIDE PANEL	Existing		8.0*#
13	AUTO	REF	REFINISH	L BED OUTER PANEL			C 3.4
14	401521	BDY	REMOVE/REPLACE	L FRT PICKUP BED SPLASH SHIELD	F81Z 9928370 AA	26.25	0.2
15	401515	BDY	REMOVE/REPLACE	L REAR PICKUP BED SPLASH SHIELD	F81Z 9928370 CA	34.43	0.2
16	401503	BDY	REMOVE/REPLACE	L FRT PICKUP BED BRACE	F81Z 9928260 AA	12.20	0.1
17	403154	BDY	REMOVE/REPLACE	L PICKUP BED DECAL	YC3Z 9925622 AAA	28.05	0.2
18	900500	BDY*	REMOVE/REPLACE	A/M TAPE STRIPES.	**Qual Repl Part	15.00 *	0.3*
19	403306	BDY	REMOVE/REPLACE	L PICKUP BED STONE SHIELD	F81Z 25292A22 AA	23.35	0.2
20	900500	BDY*	ADD'L LABOR OP	LT BED TIE DOWN HOOKS & STEP BAR.	Existing		1.0*

ESTIMATE RECALL NUMBER: 6/28/2005 11:36:08 46

UltraMate is a Trademark of Mitchell International
Copyright (C) 1994 - 2003 Mitchell International
All Rights Reserved

Mitchell Data Version: JUN_05_A
UltraMate Version: 5.0.206

Page 1 of 3

Date: 6/28/2005 11:36 AM
 Estimate ID: 46
 Estimate Version: 0
 Preliminary
 Profile ID: MIKE'S AUTO BODY

21	900500	BDY *	REMOVE/INSTALL	CAMPER SHELL	Existing	1.0*
22	401689	BDY	REMOVE/INSTALL	L REAR COMBINATION LAMP		0.2
23	401737	BDY	REMOVE/INSTALL	REAR BUMPER ASSY		0.6
24	900500	MCH*	ADD'L LABOR OP	ALIGNMENT - FOUR WHEEL	Sublet	90.00 * 0.0*
25	900500	BDY *	ADD'L LABOR OP	COVER CAR FOR OVERSPRAY	**Qual Repl Part	10.00 * 0.2*
26	900500	BDY *	ADD'L LABOR OP	MOUNT/BALANCE (OVER 16")	Sublet	20.00 * 0.0*
27	900500	BDY *	REMOVE/REPLACE	LT SIDE STEP BAR (CHROME)	New	318.31 * 1.0*
28	AUTO	REF	ADD'L OPR	CLEAR COAT		1.6
29	933003	REF	ADD'L OPR	TINT COLOR		0.5*
30	AUTO		ADD'L COST	PAINT/MATERIALS		249.60 *
31	AUTO		ADD'L COST	HAZARDOUS WASTE DISPOSAL		3.50 *

* - Judgement Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

I. Labor Subtotals						II. Part Replacement Summary				Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	Taxable Parts			1,267.75	
	Body	18.1	75.00	0.00	20.00	Sales Tax @ 8.250%			104.59	
	Refinish	7.8	75.00	0.00	0.00					
	Mechanical	0.5	75.00	0.00	90.00					
Non-Taxable Labor					2,090.00	Total Replacement Parts Amount			1,372.34	
Labor Summary					26.4					
					2,090.00					
III. Additional Costs					Amount	IV. Adjustments				Amount
Taxable Costs					249.60	Customer Responsibility				0.00
Sales Tax @ 8.250%					20.59					
Non-Taxable Costs					3.50					
Total Additional Costs					273.69					
						I. Total Labor:				2,090.00
						II. Total Replacement Parts:				1,372.34
						III. Total Additional Costs:				273.69
						Gross Total:			3,736.03	
						IV. Total Adjustments:				0.00
						Net Total:			3,736.03	

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

10 Left Front Side (P), 8 Left Rear Side (S)

ESTIMATE RECALL NUMBER: 6/28/2005 11:36:08 46

Mitchell Data Version:
 UltraMate Version:

JUN_05_A
 5.0.206

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 2003 Mitchell International
 All Rights Reserved

I hereby authorize the above repair work to be done along with the necessary materials. The body shop may operate the above vehicle for purposes of testing, inspection or delivery. Glenn's auto body will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. Glenn's Auto Body unconditionally guarantee all workmanship including refinishing performed on your vehicle for as long as you own your car. This work order does not include any hidden or additional damage. All parts subject to invoice. If your vehicle is not picked up within 4 days of completion, there will be a storage fee of \$25.00 per day. Unless arrangements are made when vehicle is dropped off for repairs.

POWER OF ATTORNEY

That the undersigned does hereby constitute and appoint Glenn's Auto Body to sign my name, place and stead of the undersigned on any Insurance Checks or Drafts issued by (insurance co) _____ covering any repairs to my (or our) automobile authorized by myself (or ourselves) in whatever manner is necessary to place check or draft in a cashable position.

SIGNED _____ DATED _____



836192

A

ANTIOCH, CA

BFNT, LLC
1102 Appleton
Nashville, TN 37210



836192

B

ANTIOCH, CA

BFNT, LLC
1102 Appleton
Nashville, TN 37210

