

Kingwood, TX

SECRET

JUN 22 2006

June 15, 2006

Daewoo Motor America, Inc
Attn.: Daewoo Customer Relations Department
1055 W. Victoria St.
Compton, CA 90220-9709

Copy to RMD

JUN 27 AM 03

10161581

Dear Daewoo:

In accordance with the directions contained in your Safety Recall Notice dated May 2006 regarding problems with the Camshaft Position Sensor (CMP) in Daewoo vehicles, I made an appointment to have my Daewoo Leganza inspected at Gullo Mazda/Daewoo at 500 I-45 S., Conroe, Texas 77304. I was advised by the management, that the problems I had been having were indeed as a result of a malfunctioning Camshaft Position Sensor, but that my car was not covered under the Safety Recall Notice, as the serial number on my CMP (8056) did not match the serial numbers which they were to replace at no charge.

Needless to say, I was extremely upset at this refusal to have a faulty CMP replaced at no charge as Daewoo had indicated. I called the Daewoo office at 877-362-1234 (option 6), and left a message, but as of this time have received no response. Before I could get my car repaired, I had to pay a total of \$257.68 for replacement of the faulty CMP.

I am enclosing a copy of the invoice from Gullo, and would appreciate your refunding me the cost of this malfunctioning Camshaft Position Sensor.

Yours sincerely,

[Redacted Signature]

Unhappy Customer

cc: Administrator
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

NHX
6/24/06

**THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).**