

Department of Transportation
 National Highway Traffic Safety Administration

Reference No.
 10170170

OWNER INFORMATION (Type or Print)

Name: [Redacted]
 Apt. No.: [Redacted]
 City: St Petersburg State: FL Zip Code: [Redacted]
 Daytime Telephone Number: [Redacted]
 Evening Telephone Number: [Redacted]
 E-mail: [Redacted]

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
 In the absence of authorization, NHTSA will provide a copy of this report to the vehicle manufacturer only during a defect investigation or when you make a complaint about recall performance on [Redacted]
 Signature of Owner: [Redacted] Date: 11/08/06

VEHICLE INFORMATION

17 digit Vehicle Identification number located at bottom of windshield on driver's side: 2ME4M744WJ558 [Redacted]
 Make: Mercury Model: GRAND MARQUIS Year: 1995 Current Mileage: 148571
 Date Purchased: 2/25/99 Dealer's Name and Telephone Number: Autobay Lincoln Mercury
 Original Owner Dealer's City: Clearwater State: FL Zip Code: 33765
 Engine: [Redacted] Fuel Type: Gas Diesel Hybrid
 Manual Automatic Powertrain: All-Wheel Drive Front-Wheel Drive Rear-Wheel Drive Four-Wheel Drive
 Antilock Brakes Cruise Control No. Cylinders: 6

FAILED COMPONENT(S)/PART(S) INFORMATION

Component Name: Window Regulator Incident Date(s): 08/15/06 Failure Mileage: [Redacted] Failure Speed: [Redacted] Failure Location: Driver Passenger Front Rear

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make/Brand: [Redacted] Tire Model/Line: [Redacted] Tire Name: [Redacted] Tire Size (Example: P215/65R1105): [Redacted]
 Failed Structure: Tread Sidewall Bead DOT No. (Example: DOT MAL9ABC036 on sidewall): [Redacted] Original Equipment Prior Repair
 Failure Type: Blowout Blister Crack Torn Tread Separation Road Hazard Out of Round

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: [Redacted] Date Manufactured: [Redacted] Model Number and Name: [Redacted]
 Seat Type: Infant Booster Integrated Convertible Other
 Failed Part. Describe Failure Below: Base Harness/Buckle LATCH Connector Shell Handle Other
 Installed in Vehicle using the: Vehicle safety belt LATCH system*
 *Vehicle info required

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the Incident(s), Failure(s), Crash(es), and Injury(ies).)

Crash: Yes No Fire: Yes No Number of Persons Injured: 0 Number of Deaths: 0 Police Report No: N/A

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies).
 Unable to close window, took vehicle to JC Auto 6101 9th Ave South St Petersburg, 727 866-0044. On hearing the problem the owner didn't have to ask the model of the vehicle. He said in the last month or so he had repaired at least 100 Grand Marquis

Continue on back.

The Privacy Act of 1974 - Public Law 93-579 This information is requested pursuant to a49 U.S.C. Chapter 301. You are under no obligation to respond to this questionnaire. Your response may be used to assist NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If NHTSA proceeds with administration enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.