



U.S. Department of Transportation

National Highway Traffic Safety Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

307 JUN 10 AM 9:40
30-OCT-2006

Repository []

Reference No.
10172187

OWNER INFORMATION (Type or Print)

Name [redacted]
Address [redacted]
City ATLANTA State GA Zip Code [redacted]

Daytime Telephone Number [redacted]

E-mail Address

Evening Telephone Number

Signature of Owner [redacted] Date 12/27/06

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
1GCGK13U61F [redacted]
Make CHEVROLET
Model CHEVROLET TRUCK
Model Year 2001

Date Purchased 19-MAR-01
Dealer's Name and Telephone Number Tom Jumper Chevrolet
Engine: No: Cylinders 8
Fuel Type: Gas

Original Owner [X]
Dealer's City Atlanta GA
State GA Zip Code 30328

Transmission Type AUTOMATIC
[X] Antilock Brakes
[X] Cruise Control
Powertrain 4 WHEEL DRIVE
Vehicle Component Code 070000 FUEL SYSTEM, GASOLINE
Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) 30-JUN-2006
Failure Mileage 27,074
Failure Speed All speeds

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make
Tire Model (Name or Number)
Tire Size (Example P215/65R15)
DOT No. (Example: DOTM1A9ABC036)
Original Equipment []
Prior Repair []
Failure Location:
Tire Component Code
Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:
Date Manufactured:
Model No./Name:
Seat Type:
Installation System:
Child Seat Component Code:
Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash [] Yes [X] No
Fire [] Yes [X] No
Number of Persons Injured
Number of Deaths
Reported to Police N

Narrative Description of Incident(s), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

DT*: THE CONTACT STATED THAT WHILE TURNING THE VEHICLE THE FUEL LINE CONSTANTLY SPEWED GAS FROM THE REAR OF THE VEHICLE. THIS OCCURRED AT VARIOUS SPEEDS. THE VEHICLE WAS TAKEN TO THE DEALER WHO DETERMINED THE CAUSE OF THE PROBLEM WAS DUE TO RATS CHEWING ON THE FUEL LINE. THE VEHICLE WAS TAKEN TO A COUPLE OTHER INDEPENDENT MECHANICS WHO DETERMINED THAT IT WAS CAUSED BY A STRESS FRACTURE. THE DEALER REPLACED THE FUEL LINE.

Old part is available. Part # 15126980

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.