



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

207 JAN 31 AM 9:40
04-JAN-2007

Repository ☐

Reference No.
10177784

OWNER INFORMATION (Type or Print)

Name
Address
City CLEMENTON State NJ Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Signature of Owner Date 1/12/2007

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
114G158K83W

Make

JEEP

Model

LIBERTY

Model Year

2003

Date Purchased

01-SEP-02

Dealer's Name and Telephone Number

MARTIN CHRYSLER SEEP 800-926-9734

Engine:

No: Cylinders 6

Fuel Type:

Gas

Original Owner

☒

Dealer's City

SICKLERVILLE

State

MS

Zip Code

08081

Transmission Type

☒

Antilock Brakes

Powertrain

4 WHEEL DRIVE

Vehicle Component Code

021540 SUSPENSION:FRONT:CONTROL ARM:LOWER BALL JOINT

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)
04-JAN-2007

Failure Mileage
20000

Failure Speed
0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make Tire Model (Name or Number) Tire Size (Example P215/65R15)

DOT No. (Example: DOTM9ABC036)

☐ Original Equipment
☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name:

Seat Type: Installation System:

Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash ☐ Yes ☒ No Fire ☐ Yes ☒ No Number of Persons Injured 0 Number of Deaths 0 Reported to Police N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

TL*- THE CONTACT RECEIVED RECALL 06V28800 REGARDING LOWER BALL JOINTS. THE CONTACT CALLED A DEALERSHIP IN HER AREA, AND THEY STATED THAT IT COULD TAKE UP TO 7 MONTHS IN ORDER FOR THEM TO SET UP SERVICE. SINCE NOVEMBER 1, 2006 THE DEALERSHIP RECEIVED 10 REPLACEMENT PARTS. *AK

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.