



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

207 FEB 27 AM 9:40
29-JAN-2007

Repository ☐

Reference No.
10181041

OWNER INFORMATION (Type or Print)

Name [REDACTED]

Address [REDACTED]

City SOUTH HAVEN

State MS

Zip Code [REDACTED]

Daytime Telephone Number [REDACTED]

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☐ YES ☒ NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.
Signature of Owner _____ Date 1/1/

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

1FDXE4554YH [REDACTED]

Make
UNKNOWN
Ford

Model
UNKNOWN E450

Model Year
9999 2000

Date Purchased
July-2000

Dealer's Name and Telephone Number
American RV

Engine:
No: Cylinders
10

Fuel Type:
Gas

Original Owner
☒

Dealer's City
Oliver Branch

State MS Zip Code

Transmission Type Automatic
☒ Antilock Brakes
☒ Cruise Control

Powertrain

Vehicle Component Code
351000 EQUIPMENT: RECREATIONAL VEHICLE

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)
03-MAY-2006

Failure Mileage

Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

☐ Original Equipment
☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured
0

Number of Deaths
0

Reported to Police
N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL* - THE CONTACT EXPLAINED SHE HAD A DOMETIC REFRIGERATOR, AND SHE SMELLED GAS FUMES. SHE CALLED A REPAIRMAN TWICE TO FIX THE PROBLEM, BUT THE SMELL CONTINUED. SHE READ IN A MAGAZINE ABOUT THE DOMETIC REFRIGERATOR RECALL, SO SHE CHECKED UNDER HER REFRIGERATOR AND WAS OVER COME BY THE FUMES. THE COOLANT WAS LEAKING OUT OF THE REFRIGERATOR. SHE CALLED THE NUMBER THAT WAS IN THE BOOK, AND THEY INFORMED HER IT WOULD NOT BE REPAIRED UNTIL APRIL 2006. *AK

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.


Don't Miss the Pre-Rally Fun

Experience the dramatic splendor of Oregon's breathtaking coastline on this three-night precursor to the 2007 Rally in scenic Redmond, Ore.

Our pre-Rally event will be held July 13-16 in Florence, Ore. Highlights include: three nights of camping with water and electricity, catered welcome dinner on July 13, scenic drive up the Oregon coast by motorcoach on July 14, which includes visit and lunch at the Oregon Coast Aquarium, tour of Heceta Head Lighthouse and admission to Sea Lion Caves. Enjoy a free day to explore Florence on July 15.

The most important feature of the pre-Rally is that participants receive priority preferential parking at The Rally beginning Tuesday, July 16 — a full day prior to standard early-bird parking. Pre-Rally participants must be registered for both Rally early-bird days July 17 and 18 in order to attend. Sign up today by calling 877-749-7122.

For more information about The Rally, July 19-22, or to register online, please visit www.therally.com or call 877-749-7122.



RV Confident?

We know how important it is to set out on the road feeling totally confident that a mechanical problem won't leave you stranded and strapped for cash. That's why the Good Sam Club created the Continued Service Plan (CSP), a mechanical breakdown insurance that protects you from paying the high costs associated with unexpected breakdowns or repairs.



Here's how CSP works: If your RV breaks down or needs sudden repairs, take it to any service center in the United States or Canada. Call us toll free, we'll talk to the service technician on your behalf and approve work to start immediately. The CSP plan pays the service center directly for all covered repairs including labor. You pay only your deductible and for any noncovered items. Additionally, CSP helps cover your travel expenses such as food, lodging and in some cases, rental car, while your RV is in the shop.

Get a quote by visiting www.goodsamcsp.com or by calling 888-787-7683.

Why Consider the Good Sam Continued Service Plan?

- 100% endorsed by the Good Sam Club, the world's largest RV organization
- Talk to real RV experts, not recordings.
- Pay one deductible per occurrence, even if several repairs are needed
- The cost of labor is included for all covered repairs
- Selling your RV privately? Transfer CSP's extended coverage to the new owner at no cost
- You can always cancel for a full refund within 30 days

*Part
of
the
Rally*

Dometic Recalls Refrigerators

Models affected: NDR1062 9999, RM2652 9999, RM2662 9999, RM2663 9999, RM2852 9999, RM2862 9999, RM3662 9999, RM3663 9999, RM3862 9999, RM3863 9999

Dometic Corp. has recalled 926,877 faulty refrigerators manufactured between April 1997 and May 2003, NHTSA Recall No. 06E076000.

A fatigue crack may develop in the boiler tube, which may release a sufficient amount of pressurized coolant solution into an area where an ignition source (gas flame) is present. The release of coolant under certain conditions could ignite and result in a fire.

Owners may contact Dometic at 888-446-5157, or the National Highway Traffic Safety Administration's Vehicle Safety Hotline at 888-327-4236 (TTY: 800-424-9153), or visit www.safercar.gov

Visit the Good Sam Club's website at www.goodsamclub.com and register your vehicles through our SamAlert program. We monitor recall notices and alert you if your vehicle is included.

Be safer with Good Sam.