

CL-10181589-8931

Riverhead, New York
Cell phone

EXECUTIVE SECRETARIAT

2007 JAN 23 P 12:45

To Whom It May Concern,

January 10, 2007

NATIONAL HIGHWAY
TRAFFIC SAFETY ADM.

We presently own a 2006 Mercury Marque - We have had this same model for the last 7 years. We purchased this car in May of 2006 and have had a problem with the brake pedal on several occasions. The last time causing an accident. It seems in this model that the gas pedal and the brake pedal are in different positions than in our previous cars, causing my foot to get caught on the gas and the brake pedal at the same time.

It seems this problem has not only caused us a problem but 2 of our friends as well. One of our friends has a 2006 and the other a 2007, they have experienced the same problem but fortunately has not caused an accident as of yet.

I have been in contact with the dealership and it seems there has been reported similar incidents.

Included in this letter are signatures and addresses of the two people that have the same problem.

[Redacted signature]

[Redacted signature]

I would like to know if the company has received any other complaints and if so how the problem can be resolved. Thank god this time it was only a fender bender, but it could have been much worse.

Please advise what recommendation and actions will be taken to rectify this problem.

Sincerely,

[Redacted signature]

cc: Safety Council

2007 JAN 24 AM 9:40

LB
1/24/07
CC