



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

Repository ☐

13 FEB 2007 30 11 7:41
Reference No.
10182444

OWNER INFORMATION (Type or Print)

Name

Daytime Telephone Number

E-mail Address

Address

Evening Telephone Number

City

TUSTIN

State

MI

Zip Code

Do you authorize NHTSA to contact you regarding your vehicle? ☒ YES ☒ NO
In the absence of an authorized representative, please provide your address to the vehicle manufacturer.
Signature of Owner _____ Date 3/10/07

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
3D7KA26C3

Make

DODGE

Model

RAM 2500

Model Year

2004

Date Purchased

Dealer's Name and Telephone Number
DON'S AUTO CLINIC INC 231-775-2413

Engine:

No: Cylinders 6

Fuel Type:

Diesel

Original Owner

☒

Dealer's City
CADILLAC

State

NE

Zip Code

49601

Transmission Type

AUTOMATIC

☒ Antilock Brakes

☒ Cruise Control

Powertrain

REAR WHEEL DRIVE

Vehicle Component Code

021600 SUSPENSION:FRONT:WHEEL BEARING

Multiple Failure: 3

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)
10-DEC-2006

Failure Mileage

Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM9ABC036)

☐ Original Equipment
☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

TL*- THE CONTACT STATED THAT THE 2004 DODGE RAM 2500 HAD A RECALL LISTED IN THE LOCAL NEWSPAPER FOR FRONT WHEEL HUB AND BEARING UNIT REPLACEMENT. THE CONTACT STATED THE RECALL IN THE NEWSPAPER WAS FOR YEAR 2006 DODGE RAM. HIS HAD REPAIRS DONE FOR LOWER BALL JOINTS, TIRE ROD ENDS REPLACED, WHEEL BEARINGS REPLACED FOR THE RIGHT FRONT WHEEL, AND A WHEEL ALIGNMENT. THE CONTACT FELT THAT THIS VEHICLE SHOULD BE PART OF THE RECALL DUE TO THE REPAIRS HE HAD DONE FOR THE FRONT END OF HIS VEHICLE. THE CURRENT MILEAGE WAS 96318. *AK

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

ly in the U.S.

Recall affects 86,333 Dodge Ram pickups

WASHINGTON — DaimlerChrysler AG's Chrysler Group said Friday it would recall 86,333 Dodge Ram 1500 pickups to resolve front-end vibration that could lead to the failure of the front wheel bearing. The automaker said it would replace the front wheel hub and bearing units in the 2006 pickups.

FX sells one third

Dodge Ram pickups recalled

ASSOCIATED PRESS

WASHINGTON

DaimlerChrysler AG's Chrysler Group said Friday it would recall 86,333 Dodge Ram 1500 pickups to resolve front-end vibration that could lead to the failure of the front wheel bearing.

The automaker said it would replace the front wheel hub and bearing units in the 2006 pickups. DaimlerChrysler spokesman Max Gates said the company had received a "couple hundred" warranty claims, which led it to review the bearings.

There have been no injuries

linked to the issue, the company said.

Chrysler advised owners who experience front-end vibration or bearing noise to take their vehicles to a dealer for inspection. The work will be completed at no cost to owners.

Carmike Cinemas
GKC BIG RAPIDS CINEMAS
213 SOUTH MICHIGAN AVE • 796-1452
*SAT & SUN ONLY

NORBIT PG13 1:30* 4:15* 7:00 9:30	STOMP THE YARD PG13 1:20* 4:00* 7:15 9:40
EPIC MOVIE PG13 1:00* 3:05* 5:15* 7:20 9:30	NIGHT AT THE MUSEUM PG 1:30* 4:30* 7:00 9:20

*ALL SHOWTIMES INCLUDE PRE-FEATURE CONTENT • www.carmike.com

THE ATTACHMENTS TO THIS
DOCUMENT HAVE BEEN REMOVED
TO PROTECT UNWARRANTED
INVASION OF PERSONAL PRIVACY
PURSUANT TO EXEMPTION 6 OF
THE FREEDOM OF INFORMATION
ACT (FOIA), 5 U.S.C. 552(b)(6).