



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236) 2008 FEB - 1
INTERNET: www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

Repository ☐

26-JUL-2007
PM 12:24

Reference No.
10197533

OWNER INFORMATION (Type or Print)

Name

Daytime Telephone Number

E-mail Address

Address

Evening Telephone Number

City

MONTEVIDEO

State

MN

Zip Code

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☒ YES ☐ NO
In the absence of an authorized signature, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.
Signature of Owner [Redacted] Date 8/6/07

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

1GNCU06D2M [Redacted]

Make

CHEVROLET

Model

LUMINA APV

Model Year

1991

Date Purchased
01-MAY-07

Dealer's Name and Telephone Number

Engine:

No: Cylinders 6

Fuel Type:

Gas

Original Owner
☐

Dealer's City

State

Zip Code

Transmission Type
AUTOMATIC

☐ Antilock Brakes
☒ Cruise Control

Powertrain

FRONT WHEEL DRIVE

Vehicle Component Code

061000 ENGINE AND ENGINE COOLING:ENGINE

Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)
18-JUL-2007

Failure Mileage
168000

Failure Speed
15

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

☐ Original Equipment
☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

N

Narrative Description of Incident(s), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A 1991 CHEVROLET LUMINA APV. WHILE DRIVING 15 MPH, THE CONTACT LOST STEERING ABILITY. THE VEHICLE WAS TOWED TO THE DEALER AND THEY STATED THAT THE REAR TWO BOLTS THAT HOLD THE ENGINE FAILED, WHICH CAUSED THE STEERING COLUMN TO DISCONNECT. AS OF JULY 26, 2007, THE DEALER HAS NOT REPAIRED THE VEHICLE. THE CURRENT AND FAILURE MILEAGES WERE 168,000.

the manufacturer acknowledges this type of failure will disconnect the steering and that can happen at any speed!

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.