

CL-10203784-7203

2007 SEP 17 AM 7:40

2007-7-20

August 24, 2007

National Highway Traffic Safety Administration  
U.S. Department of Transportation  
Washington, D.C. 20590

Toyota Camry, Sedan 1998  
Vin Number: 4T1BG22K1WU [REDACTED]

Purchased August 5, 1999 at Faulkner Toyota Dealer, 2425 Lincoln Highway,  
Trevose, PA Meter Reading 6000 miles. At time of purchase, my home address  
was [REDACTED] Meadowbrook, PA [REDACTED]  
My name is [REDACTED]

Moved to [REDACTED] Elgin, SC [REDACTED], June 30, 2007  
Telephone # [REDACTED]

On Sunday afternoon, August 5, 2007, driving on RT.26, NC, - busy highway -  
was turning into rest stop when engine suddenly cut off. Our concern is what  
could have happened if we were not leaving road for rest stop.

Firestone Complete Auto Care, Two Notch Road, Columbia, SC 29223 did a  
Engine diagnostic service - car needed ignition coils.

Reported incident to Toyota Motor Sales, U.S.A. Inc. 1-800-331-4331, today/  
Service Representative was very courteous and took all information .  
Mileage on car, at time of repair, 08/06/07 was 40,325. No previous problems.

Sincerely,

[REDACTED]