



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects

1-888-DASH-2-DOT

(1-888-327-4236)

INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received

2007 DEC 12 PM 1:48

02-OCT-2007

Repository ☐

Reference No.

10204722

OWNER INFORMATION (Type or Print)

Name

Address

City

LAKE JACKSON

State TX

Zip Code

Daytime Telephone Number

E-mail Address

Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☒ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side

3FCNF53S2

Make

FLEETWOOD

Model

BOUNDER

Model Year

1999

Date Purchased

01-DEC-99

Dealer's Name and Telephone Number

DEMONTROND RV

Engine:

No: Cylinders 10

Fuel Type:

Gas

Original Owner

☒

Dealer's City

HOUSTON

State

TX

Zip Code

Transmission Type

AUTOMATIC

☒ Antilock Brakes

☒ Cruise Control

Powertrain

REAR WHEEL DRIVE

Vehicle Component Code

180000 VEHICLE SPEED CONTROL

Multiple Failure: 0

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)
01-SEP-2007

Failure Mileage

Failure Speed

0

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make

Tire Model (Name or Number)

Tire Size (Example P215/65R15)

DOT No. (Example: DOTM19ABC036)

☐ Original Equipment
☐ Prior Repair

Failure Location:

Tire Component Code

Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:

Date Manufactured:

Model No./Name:

Seat Type:

Installation System:

Child Seat Component Code:

Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies).)

Crash

☐ Yes ☒ No

Fire

☐ Yes ☒ No

Number of Persons Injured

0

Number of Deaths

0

Reported to Police

N

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A 1999 FLEETWOOD BOUNDER. THE CONTACT RECEIVED A RECALL NOTICE REGARDING THE VEHICLE SPEED CONTROL IN SEPTEMBER OF 2007. THE DEALER AND MANUFACTURER STATED THAT THE PARTS WERE UNAVAILABLE AND THEY DID NOT KNOW WHEN THEY WOULD ARRIVE. THE CONTACT DID NOT GET THE SPEED CONTROL DEACTIVATED. THERE HAD BEEN NO FAILURE TO DATE. THE RECALL NUMBER WAS UNKNOWN. THE CURRENT MILEAGE WAS 72,120.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Frank M. Ligon
Ford Motor Company
P.O. Box 1904
Dearborn, Michigan 48121



Recall
888-828-7200
888-828-7600

10704722

September 2007

[Signature]



F0022617

0069

LAKE JACKSON, TX

1999 Motorhome

Vehicle ID #: 3FCNF53S2X

05S28

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 1992-2004 vehicles equipped with speed control. We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support.

What is the issue?

Ford cannot be confident that over many years in service, the type of Speed Control Deactivation Switch (SCDS) equipped on your vehicle will not leak, posing the risk of an underhood fire. This condition may occur either when the vehicle is parked or when it is being operated, even if the speed control is not in use.

What will Ford and your dealer do?

Ford Motor Company has authorized your dealer to install a fused wiring harness into the speed control system of your vehicle free of charge (parts and labor).

How long will it take?

Your dealer may be able to perform this repair while you wait; however, due to scheduling requirements, your dealer may need your vehicle for a longer period of time.

What are we asking you to do?

Please call your dealer without delay and request a service date to have the fused wiring harness installed (Recall 05S28). Provide the dealer with the Vehicle Identification Number (VIN) of your vehicle. The VIN is printed near your name at the beginning of this letter.

Until you have the recall service performed, park your vehicle away from structures to prevent a potential underhood fire from spreading.

The vehicle owner is responsible for having this service action performed. Ford Motor Company reserves the right to deny coverage for any vehicle damage that may result from failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

RETAIL OWNERS: If you do not already have a servicing dealer, you can access <http://www.genuineservice.com> for dealer addresses, maps, and driving instructions.

FLEET OWNERS: If you do not already have a servicing dealer, you may access our Dealer Locator on <https://www.fleet.ford.com> for dealer addresses, maps, and driving instructions.

MOTORHOME OWNERS: To locate a dealer that services Motorhomes, call the Motorhome Customer Assistance Center toll free at 1-800-444-3311. Ford representatives are available 24 hours a day.

Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

L00Z/6/01

Have you previously paid for this repair?

If you paid to remedy the issue addressed in this notice, you may be eligible for a refund.

To verify eligibility and expedite reimbursement, give your paid original receipt to your dealer.

Refund requests may be sent directly to Ford Motor Company. To request your refund from Ford, send the refund request with all required documentation, including your original repair receipt (no photocopies), to Ford Motor Company at P.O. Box 6251, Dearborn, Michigan 48121-6251. Refund requests mailed to this address may take up to 60 days to process. Your original receipt will be returned to you.

Detailed information regarding eligibility for Ford's reimbursement program and documentation requirements may be obtained by contacting the Ford Customer Relationship Center at 1-888-222-2751.

Owners who have previously paid for this repair still need to have the recall described in this letter performed.

What if you no longer own this vehicle?

If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.

You received this notice because government regulations require that notification be sent to the last known owner of record. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

Can we assist you further?

If you have difficulties getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance.

RETAIL OWNERS: If you still have concerns, please contact the Ford Motor Company Customer Relationship Center at 1-888-222-2751 and one of our representatives will be happy to assist you. For the hearing impaired call 1-800-232-5952 (TDD). Office Hours are Monday through Friday: 8AM – 5PM (Your Local Time).

If you wish to contact us through the Internet, our address is:
www.ownerconnection.com

FLEET OWNERS: If you still have concerns, please contact the Fleet Customer Information Center at 1-800-34-FLEET, Option #3 and one of our representatives will be happy to assist you. Representatives are available 8:30AM to 5:00PM Monday through Friday (Eastern Time Zone).

Or you may contact us through the internet at www.fleet.ford.com.

MOTORHOME OWNERS: If you still have concerns, please contact the Motorhome Customer Assistance Center toll free at 1-800-444-3311. Ford representatives are available 24-hours a day.

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, D. C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

Thank you for your attention to this important matter.

The Wal-Mart Digital Photo Center Team
<http://www.walmart.com>

Sincerely,

Frank M. Ligon

If you have questions or want to contact us, please visit Photo Help.

Frank M. Ligon

Director

Service Engineering Operations

This order is already being processed and cannot be canceled. Remember, you can return an item if you are not satisfied with it, in accordance with our Returns Policy.

Canceling an Order