



Fax Cover Sheet

Date March 16, 2008Number of pages 3 (including cover page)

To:

Name Auto Recalls/DefectsCompany NHTSA

Telephone _____

Fax (202) 366-1767

From:

Name [REDACTED]

Company _____

Telephone [REDACTED]Comments Information request on a 1993 Buick driver's seat front
recliner assembly NHTSA ODI ID # 813444

7 90363 00711 1

Fax - Local Send



7 90363 00714 2

Fax - Domestic Send



7 90363 01476 8

DOMESTIC Send Addl Pages



7 90363 00720 3

Fax - International Send

fedexkinkos.com 1.800.GoFedEx 1.800.463.3339

© 2008 FedEx Kinko's Office and Print Services, Inc. All rights reserved. Products, services and hours vary by location. fms185 1.08

22705

2008 MAR 18 AM 9:24

CL 10221712-0597

4A
03/18/08
KB

[REDACTED]
Midvale, UT [REDACTED]
March 16, 2008

**Re: Defective driver's seat front recliner assembly
for a 1993 Buick Skylark NHTSA ODI ID
Number 813444.**

**NHTSA Headquarters
1200 New Jersey Avenue, SW
West Building
Washington, DC 20590
Fax: (202) 366-1767**

NHTSA:

I am enclosing a copy of a 1993 Buick Skylark recall, which involved the Driver front seat recliner assembly. I was involved in a auto rear-end accident on October 12, 2005, that involve's NHTSA ODI ID Number 813444. See copy of this recall that is enclosed, and where could I obtain schematics / technical drawings, etc, of this seat and the assembly? Also, do any other reports, or other data concerning this seat and the assembly? How many different Buicks had similar, or the same recliner front assembly? Your help would be most appreciated

Sincerely,

[REDACTED]

1993 BUICK SKYLARK

NHTSA ODI ID Number: 813444

Manufacturer: GENERAL MOTORS CORP.

Date of Failure: //

Crash: Y

Fire: N

Number of Injuries: 1

Number of Deaths:

Vin: 1G4NJ54N3PC

Component: SEATS:FRONT ASSEMBLY:RECLINER

**Summary: THE VEHICLE'S DEFECTIVE DRIVER'S SEATBACK COLLAPSED
BACKWARDS AFTER BEING REARENDED BY ANOTHER VEHICLE GOING ABOUT
40+MPH. DRIVER SUSTAINED INJURIES. *AK**