

CL-10223936-5871

March 24, 2008

Attention 2008 APR -3 AM 8:19

I have had my 1993 Ford
Crown Vic #10
2FAZP74WXPX [REDACTED]
[REDACTED]

Speed Control Deactivation
Switch replaced in Feb 2008
at Herb Chamber Dealership
in Westboro Mass 01581.
The service was excellent.
Thank you for writing me
about this problem.

Sincerely,

[REDACTED]
Westboro, Mass.
[REDACTED]

MC
6/10/08
KB