



**INFORMATION Redacted PURSUANT TO THE FREEDOM OF  
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)**

- [Home](#)
- [Vehicle Shoppers](#)
- [Vehicle Owners](#)
- [Vehicle Manufacturers](#)
- [About NHTSA](#)

1. [File a Complaint](#)
2. [Search Complaints](#)
3. [Safety Recalls](#)
4. [Defect Investigations](#)
5. [Service Bulletins](#)
6. [Resources](#)

Frequently Asked Questions

[Get answers to the most frequently asked questions about Safety Ratings](#)



## Complaints - Search Results

You are here: [Home](#) / [Vehicle Owners](#) / [Search Complaints](#) / Results List

### Search Results

Report Date : October 26, 2010 at 08:27  
PM

ODI Numbers 10301981  
Searched:

Results : 1 | **All** records displayed

Make : VAN HOOL	Model : T2140	Year : 2007
Manufacturer : VAN HOOL N.V.		
Crash : No	Fire : No	Number of Injuries: 0
ODI ID Number : 10301981		Number of Deaths: 0
Date of Failure: December 5, 2009		
VIN : YE2TA15B672...		

Component: ENGINE AND ENGINE COOLING:EXHAUST SYSTEM

Summary:

VAN HOOL T2140 2006 THERE ARE POSSIBILITY TO HAVE TURBO FAILURE BY INSTALLING DEFECTIVE TURBO INTAKE PIPE BY MANUFACTURE. THERE ARE INSTALLATION DIFFICULTIES WHEN CONNECTING TURBO CHARGER AND TURBO PIPE BECAUSE OF LIMITED SPACE IN ENGINE COMPARTMENT. THE WALL OF VEHICLE WAS INTERRUPTED TO LOCATE THE TURBO PIPE. VAN HOOL MANUFACTURE TRIM(CUT) THE PIPE TO INSTALLED. BECAUSE OF THAT ,PIPE LOST 90% OF THICKNESS. ORIGINALLY ABOUT 7MM IN DIAMETER OF THE PIPE BECAME 1MM IN DIAMETER. IT HAS BEEN COVERED BY RUBBER ATTACHED ON THE WALL TO BE HIDDEN. IT CAN NOT SEE BY REGULAR INSPECTION UNLESS YOU TAKE OUT PIPE. THE MANUFACTURE MUST RECALL THIS PIPE TO REPLACE. WE HAD TURBO FAILURE IN ONLY 90,000MILES OF VEHICLE OPERATION CAUSED BY THE INTAKE PIPE LEAK.  
\*TR

Check to Request Research. Submit below.

- [NHTSA.GOV](#) |

- [STOPIMPAIREDDRIVING.ORG](http://STOPIMPAIREDDRIVING.ORG) |
- [TRAFFICSAFETYMARKETING.GOV](http://TRAFFICSAFETYMARKETING.GOV) |
- [EMS.GOV](http://EMS.GOV)

- [Policies](#) |
- [Terms of Use](#) |
- [USA.gov](#) |
- [FOIA](#) |
- [Privacy Policy](#) |
- [Accessibility](#) |
- [Careers](#) |
- [Site Map](#) |
- [Contact NHTSA](#)

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA 1.888.327.4236 TTY  
1.800.424.9153



111

