

INFORMATION Redacted PURSUANT TO THE FREEDOM OF

INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

 U.S. Department of Transportation National Highway Traffic Safety Administration		DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 100148	
Date Received JUL 30 2010 18-MAY-2010		Repository ☐ Reference No. 10331003			
OWNER INFORMATION (Type or Print)					
Name [REDACTED]		Daytime Telephone Number [REDACTED]		E-mail Address	
Address [REDACTED]		Evening Telephone Number SAME			
City VENICE	State FL	Zip Code [REDACTED]			
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 4T1BE32KX3L [REDACTED]		Make TOYOTA	Model CAMRY	Model Year 2003	
Date Purchased 5/3/03	Dealer's Name and Telephone Number Bought in Arizona - but always service at		Engine: No: Cylinders 4	Fuel Type: REG. GAS	
Original Owner ☒	Dealer's City Cummins Toyota	State FL	Zip Code		
Transmission Type Auto.	☒ Antilock Brakes ☒ Cruise Control	Powertrain	Multiple Failure:	Incident Date(s) 01-JAN-2006	
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Component Code: 063000 ENGINE AND ENGINE COOLING: EXHAUST SYSTEM INTAKE MANIFOLD - MAKES LOTS OF NOISE			Failure Mileage	Failure Speed	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make	Tire Model (Name or Number)		Tire Size (Example P215/65R15)		
DOT No. (Example: DOTM9ABC036)	☐ Original Equipment ☐ Prior Repair	Failure Location:			
Tire Component Code			Tire Failure Type:		
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:	Date Manufactured:		Model No./Name:		
Seat Type:	Installation System:				
Child Seat Component Code:		Failed Part:			
APPLICABLE INCIDENT INFORMATION (Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)					
Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Deaths	Reported to Police N	
Narrative Description of Incident(s), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).					
TL* THE CONTACT OWNS A 2003 TOYOTA CAMRY. THE CONTACT STATED THE VEHICLE WAS AT THE DEALER FOR AN UNRELATED REPAIR. WHEN HE RECEIVED THE VEHICLE BACK, THERE WAS AN UNUSUAL GRINDING NOISE FROM THE EXHAUST SYSTEM. THE VEHICLE WAS TAKEN BACK TO THE DEALER WHERE HE WAS INFORMED THAT THE VEHICLE COULD NOT BE REPAIRED. THE FAILURE PERSISTED. THE FAILURE MILEAGE WAS UNKNOWN AND THE CURRENT MILEAGE WAS 43,000. <i>I'm an 82 year old lady, I love this car, but its so noisy! Its not my fault!! Warranty was changed on June 03/2004, I was never notified!! Took Car back to service, many times</i>					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY					
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					

*to be checked. no good answer was given to
took car in for 45000. check up - but*

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

they did everything first before I got a
oil change. Filter & wipers else they
do. Now they say they will replace the
intake manifold for a mere \$584.00 &
replace the serpentine belt for 40.00 plus tax.
I don't have this kind of money and
I would like my car fixed correctly!
Can you people please help me?
I thank you kindly - [REDACTED]

ATTACH ADDITIONAL SHEETS IF NECESSARY

P.S. Almost forgot I've been back to Toyota
at least 3 times, my brakes still squeak!!

U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382

Official Business
Penalty for Private Use \$300



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES



BUSINESS REPLY MAIL

FIRST-CLASS MAIL

PERMIT NO. 1888

WASHINGTON, DC

POSTAGE WILL BE PAID BY ADDRESSEE

**US Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NVS-210
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382**



safecar.gov

**Think your vehicle
has a safety defect?**



If so:

**Use the enclosed
form to file a report.**

or visit:

www.safecar.gov

or call:

**Vehicle Safety Hotline
888-327-4236**



Vehicle Owner's Questionnaire (VOQ)
U.S. Department of Transportation
National Highway Traffic Safety Administration

July 17, 2010

Sirs

I had been complain-
ing about the grinding
noise under the hood
for several years. Since
2006. It's been a long
time & I'm very
upset over it all!!

I think the manufac-
ing or should take action
to the dealer for all
of this misery!

I do hope I can get
something done for my
car.

Thank you



900 U.S. HWY. 41 BYPASS S. • VENICE, FLORIDA 34285
(941) 484-9000

OR
TOLL FREE FROM CHARLOTTE OR MANATEE COUNTIES
(800) 748-1469

www.cramertoyota.com
www.cramerscion.com
State of Florida Registration
Number MV - 00482



CUSTOMER NO. 13604	ADVISOR BEN LITKE	TAG NO. 377	INVOICE DATE 07/14/10	INVOICE NO. TOCS387583
	LABOR RATE	LICENSE NO. 329	COLOR	STOCK NO.
	YEAR / MAKE / MODEL 03/TOYOTA/CAMRY/4DR SDN LE AUTO	MILEAGE 45,129	DELIVERY DATE	DELIVERY MILES
VENICE, FL	VEHICLE I.D. NO. 4T1BE32KX3U		SELLING DEALER NO.	PRODUCTION DATE
	F.T.E. NO.	P.O.	R.O. DATE 07/14/10	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS		

TOTALS-----
Disposal Fee: The State of Florida requires a \$1.00 fee to be collected for each new tire and a \$1.50 fee to be collected for each new or remanufactured battery sold in the state.

National limited lifetime repair warranty for workmanship, including refinishing, for all completed repairs for as long as the customer owns the vehicle. Bodyshop Only.

* [] VISA [] MASTERCARD [] AMEX [] DISCOVER *
* I FULLY UNDERSTAND THE TERMS, CONDITIONS, AND *
* WARRANTIES AND AUTHORIZE CRAMER TOYOTA OF *
* VENICE TO CHARGE MY CREDIT CARD. *

TOTAL LABOR.... 10.29
TOTAL PARTS.... 15.70
TOTAL SUBLET.... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 2.82
TOTAL MISC DISC 0.00
TOTAL TAX..... 2.02

TOTAL INVOICE \$ 30.83

MO: 45131
DISCLAIMER OF WARRANTIES
THE ONLY WARRANTIES, IF ANY, APPLYING TO THESE PARTS, AND FOR SERVICES ARE THOSE OFFERED BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THESE PARTS AND/OR SERVICES. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM SELLER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFITS OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

CUSTOMER SIGNATURE

PAID

JUL 14 2010

VISA

**Next time you're in a CRUNCH,
please visit our Body Shop.
FREE ESTIMATES and we
repair ALL makes and models.**

CUSTOMER SIGNATURE CUSTOMER ACKNOWLEDGES RECEIPT OF COPY
* Your repair cost may include a charge for miscellaneous shop supplies and/or hazardous waste disposal. The charge will be calculated at 8% of the total labor; with a maximum of \$20.00 per customer visit. This charge can be found on the miscellaneous charge line of totals column. This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. [s. 559.904(4)] The State of Florida requires a \$1.00 fee to be collected for each new tire sold in the state [s. 403.718], and a \$1.50 fee to be collected for each new or remanufactured battery sold in the state. [s. 403.7185].

HOURS OF OPERATION
M - F 7:15 AM - 5:30 PM
SAT 8:00 AM - 4:00 PM

**ALL PARTS ARE NEW UNLESS
OTHERWISE INDICATED**



900 U.S. HWY. 41 BYPASS S. • VENICE, FLORIDA 34285

(941) 484-9000

OR

TOLL FREE FROM CHARLOTTE OR MANATEE COUNTIES

(800) 748-1469

www.cramertoyota.com

www.cramerscion.com

State of Florida Registration

Number MV - 00482



SCION

CUSTOMER NO.	13604	ADVISOR	BEN LITKE	TAG NO.	329	INVOICE DATE	07/14/10	INVOICE NO.	TOCS387583
		LABOR RATE		LICENSE NO.	377	COLOR		STOCK NO.	
		YEAR / MAKE / MODEL	45,129 /			DELIVERY DATE		DELIVERY MILES	
VENICE, FL		VEHICLE I.D. NO.	03/TOYOTA/CAMRY/4DR SDN LE AUTO			SELLING DEALER NO.		PRODUCTION DATE	
		F.T.E. NO.	4 T 1 B E 3 2 K X 3 U			R.O. DATE	07/14/10		
RESIDENCE PHONE		BUSINESS PHONE				COMMENTS			

LABOR & PARTS-----
J# 1 05TOZ5CAR 5K/10K SERVICE-CAR TECH(S):319 10.29
CUSTOMER REQUESTS 5,000 MILE INTERVAL SERVICE.
SERVICE DUE BY TIME AND OR MILES.
PERFORMED OIL & FILTER CHANGE, ROTATE 4 TIRES, COMPLETE 30
POINT INSPECTION AND FILL FLUIDS TO PROPER LEVELS.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-
JOB # 1	1	PKCEL4		15.70
JOB # 1	1	90915-YZZF1	FILTER S/A, OIL	****
JOB # 1	1	90430-12031	GASKET	****
JOB # 1	5	OIL1	5W30 CASTROL GT	****
JOB # 1 TOTAL PARTS				15.70
JOB # 1 TOTAL LABOR & PARTS				25.99

J# 2 00TOZ COMPLIM. INSPECTION TECH(S):319 INTERNAL
CUSTOMER REQUESTS COMPLIMENTARY MAINTENANCE AND SAFETY
INSPECTION
COMPLETED INSPECTION

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-
JOB # 2 TOTAL PARTS				0.00
JOB # 2 TOTAL LABOR & PARTS				0.00

J# 3 00TOZ201 -201 (4 WHEEL ALIGN) TECH(S):319 INTERNAL
CUSTOMER REQUESTS 4 WHEEL ALIGNMENT
COMPLETED 4 WHEEL ALIGNMENT

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-
JOB # 3 TOTAL PARTS				0.00
JOB # 3 TOTAL LABOR & PARTS				0.00

MISC-----	CODE-----	DESCRIPTION-----	CONTROL NO-----
JOB # A	100	SHOP SUPPLIES	
JOB # 1	101	WASTE OIL DISPOSAL	
TOTAL - MISC			0.82 2.00 2.82

COMMENTS-----
BEN

RECOMMENDATIONS-----
TECH NOTES...RECOMMENDATIONS BEN
REPLACE INTAKE AMNIFOLD \$ 584.00 PLUS TAXES.
REPLACE SERPENTINE BELT \$ 140.00 PLUS TAXES.

DISCLAIMER OF WARRANTIES

THE ONLY WARRANTIES, IF ANY, APPLYING TO THESE PARTS, AND FOR SERVICES ARE THOSE OFFERED BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THESE PARTS AND/OR SERVICES. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM SELLER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFITS OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

CUSTOMER SIGNATURE _____ CUSTOMER ACKNOWLEDGES RECEIPT OF COPY

* Your repair cost may include a charge for miscellaneous shop supplies and/or hazardous waste disposal. The charge will be calculated at 8% of the total labor; with a maximum of \$20.00 per customer visit. This charge can be found on the miscellaneous charge line of totals column. This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. [s. 559.904(4)] The State of Florida requires a \$1.00 fee to be collected for each new tire sold in the state [s. 403.718], and a \$1.50 fee to be collected for each new or remanufactured battery sold in the state. [s. 403.7185].

HOURS OF OPERATION

M - F 7:15 AM - 5:30 PM

SAT 8:00 AM - 4:00 PM

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED

753801

116791

Germain

INVOICE

of Sarasota
7435 Tamiami Trail - Sarasota, Florida 34231
www.germaintoyota.com
State of Florida Registration MV-39061

VENICE, FL
HOME: BUS:

PAGE 1

SERVICE ADVISOR: 8704 KELLY GREER

SERVICE ADVISOR: 8704 KELLY GREER

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
WHITE	03	TOYOTA CAMRY	4T1BE32KX3U		1539/1539	T861	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
26MAR2003			17:00 13JUN03		0.00	CASH	13JUN2003
R.O. OPENED		READY	OPTIONS: STK:V31216 DLR:09207				

11:19 13JUN03 11:55 13JUN03

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

A SOMETIMES THE VEHICLE WILL NOT WANT START.VEHICLE HAS NO POWER

02 CK CHARGING PER CUST REQUEST NO REPAIRS AT
THIS TIME.

7015 ISP 0.00 (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

Your repair costs will include a charge for miscellaneous shop supplies and/or hazardous waste disposal. The charge will be calculated at 8% of the total labor; with a maximum of \$20.00 per customer visit. This charge can be found on the miscellaneous charge line of totals column.

"There may be a charge that represents costs and profits to the motor vehicle repair facility for items such as miscellaneous shop supplies and/or waste disposal expenses."

HOURS OF OPERATION
M - F 7:30 AM - 6:00 PM
SAT 8:00 AM - 4:00 PM

DISCLAIMER OF WARRANTIES

THE ONLY WARRANTIES, IF ANY APPLYING TO THESE PARTS, AND FOR SERVICES ARE THOSE OFFERED BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THESE PARTS AND/OR SERVICES. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM SELLER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFITS OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

CUSTOMER COPY

753801

115460

Germain

INVOICE

of Sarasota
7435 Tamiami Trail · Sarasota, Florida 34231
www.germaintoyota.com
State of Florida Registration MV-39061

VENICE, FL 33595
HOME: [REDACTED] BUS:

PAGE 1

SERVICE ADVISOR: 4235 MARK ENGELHARDT

SERVICE ADVISOR: 4235 MARK ENGELHARDT

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
WHITE	03	TOYOTA CAMRY	4T1BE32KX3U [REDACTED]		1163/1163	TY971	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
26MAR2003			WAIT 23MAY03		0.00	CASH	23MAY2003
R.O. OPENED		READY	OPTIONS: STK:V31216 DLR:09207				

09:59 23MAY03 10:59 23MAY03

LINE OPCODE TECH TYPE HOURS

A CUSTOMER NEEDS BOTH REMOTES TO SOUND ALARM WHEN ARMING

LIST NET TOTAL

CAUSE: REPROGRAMM ALARMS

862991 REPROGRAM ALARMS

3894 W 0.50

1 89747-51010 BUZZER, WIRELESS DOO

(N/C)

FC: T99/99 PART#: COUNT:

(N/C)

CLAIM TYPE:

AUTH CODE:

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

REPLACE ALARM HORN REPROGRAM REMOTES

B PROGRAM REMOTES TO BEEP WHEN USING REMOTE

CAUSE: ALARM HORN

862991 REPLACE ALARM HORN

3894 W 0.50

FC: T95/93 PART#: COUNT:

(N/C)

CLAIM TYPE:

AUTH CODE:

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

C CUST REQUEST COPY OF LAST VISIT

00TOZ QUICK SERVICE

3894 ISP 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

Your repair costs will include a charge for miscellaneous shop supplies and/or hazardous waste disposal. The charge will be calculated at 8% of the total labor; with a maximum of \$20.00 per customer visit. This charge can be found on the miscellaneous charge line of totals column.

"There may be a charge that represents costs and profits to the motor vehicle repair facility for items such as miscellaneous shop supplies and/or waste disposal expenses."

HOURS OF OPERATION
M - F 7:30 AM - 6:00 PM
SAT 8:00 AM - 4:00 PM

DISCLAIMER OF WARRANTIES

THE ONLY WARRANTIES, IF ANY APPLYING TO THESE PARTS, AND FOR SERVICES ARE THOSE OFFERED BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THESE PARTS AND/OR SERVICES. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM SELLER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFITS OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

DESCRIPTION

TOTALS

LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

PLEASE PAY THIS AMOUNT

0.00

CUSTOMER COPY

CarComplaints.com
on Facebook
CarComplaints.com
on Twitter
Got an iPhone?
m.carcomplaints.com

You are not logged in. [Log in](#) | [Sign up](#)

© 2000-2010, AutoBeef LLC

[« back to Overview](#)
[Lemon Law](#)

[Owner Complaints](#)

[Toyota Recalls](#)

[Defect Investigations](#)

[TSBs](#)

[switch models]

[switch years]

« search for something else

2003 Toyota Camry

CAMRY ENGINE PROBLEMS



Click on the graphs below to read more.

10

4

4

2

1

1

1

1

Toyota Recall
Toyota takes care of its customers Read the FAQs at Toyota.com
[Toyota.com/Recall](#)

Ads by Google

[engine died](#)

[knocking noise from intake manifold](#)

[sudden unintended acceleration](#)

[runs roughly](#)

[car won't start](#)

[engine sludge and blown engine](#)

[low idle heavy vibrating](#)

[stripped head bolts](#)

[share this on Facebook](#)

[bookmark on Delicious](#)

[share this on StumbleUpon](#)

[add this page to Digo](#)

0 tweets

tweet

[SHOW MORE SHARE OPTIONS »](#)

Fuel System Treatment

Remove Varnish & Carbon Deposits
RESTORE Engine Power & Performance
[www.restoreusa.com](#)

Blown Head Gasket Repair

The Strongest Repair Available Watch A Repair in Real Time
[www.Rxauto.com](#)

Engines

Engines Up To 50% Off, 3yr Warr, Free Shipp
[www.EverDrive.com](#)

Ads by Google

DON'T SEE WHAT YOU ARE LOOKING FOR? TRY OUR SITE-WIDE SEARCH!

powered by

Is GMC Terrain right for you?
Click here to find out »

GMC MAY THE BEST CAR WIN.

Rollover for disclaimer

CarComplaints.com
on Facebook

CarComplaints.com
on Twitter

Got an iPhone?
[m.carcomplaints.com](#)

CarComplaints.com

What's wrong with YOUR car?™

[ADVERTISE](#) | [PRIVACY](#) | [TERMS/DISCLAIMER](#) | [CONTACT US](#)

copyright © 2000 - 2010

CarComplaints.com
on Facebook
CarComplaints.com
on Twitter
Got an iPhone?
m.carcomplaints.com

You are not logged in. [Log in](#) | [Sign up](#)

© 2000-2010, AutoBeef LLC

[« back to engine](#)

[Complaints](#)

[Recalls](#)

[Investigations](#)

[TSBs](#)

[Lemon Law](#)

[switch models]

[switch years]

[« search for something else](#)

2003 Toyota Camry

KNOCKING NOISE FROM INTAKE MANIFOLD



Be notified about new defects, investigations, recalls & lawsuits for the 2003 Toyota Camry:

TYPICAL REPAIR COST:

\$1,000.00

AVERAGE MILEAGE:

63,425 MILES

TOTAL COMPLAINTS:

4 COMPLAINTS

6.0

FAIRLY SIGNIFICANT

MOST COMMON SOLUTIONS:

1. replace intake manifold (4 reports)



ENGINE PROBLEM

[share this on Facebook](#)

[share this on Digg](#)

[share this on Twitter](#)

[share this on StumbleUpon](#)

0
tweets

tweet

[SHOW MORE SHARE OPTIONS »](#)

This problem may be covered under warranty. Ask your Toyota dealer.

[Toyota Recall](#)

Toyota takes care of its customers Read the FAQs at [Toyota.com](#)
[Toyota.com/Recall](#)

[Ask a Toyota Mechanic Now](#)

14 Toyota Mechanics Are Online! Ask a Question, Get an Answer ASAP.
[JustAnswer.com/Toyota/Camry](#)

Ads by Google

4

2009
JUL 08

Camry LE 4 cyl

[Automatic transmission](#) 71,000 MILES

I thought Toyotas were supposed to last forever!!!!!!!!!!!!

Elaine L.
Commack, NY, USA

[SEND A COMMENT »](#)

ADVERTISEMENTS

[Toyota Recall](#)

Toyota takes care of its customers Read the FAQs at [Toyota.com](#)
[Toyota.com/Recall](#)

[Ask a Toyota Mechanic Now](#)

14 Toyota Mechanics Are Online! Ask a Question, Get an Answer ASAP.
[JustAnswer.com/Toyota/4Runner](#)

[Fuel System Treatment](#)

Remove Varnish & Carbon Deposits
RESTORE Engine Power & Performance
[www.restoreusa.com](#)

Ads by Google

2009
JAN 21

Camry LX V6

AUTOMATIC TRANSMISSION 53,000 MILES

TSB #00205 -- BRAKE PEDAL VIBRATION FEELING. *SC (NHTSA ID #10015961, JANUARY 11 2006)

TSB #00602 -- FRONT BRAKE VIBRATION. *TT (NHTSA ID #10000647, DECEMBER 24 2002)

SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS

TSB #000404 -- FRONT BRAKE COMPONENT IDENTIFICATION. *TT (NHTSA ID #10007667, MAY 07 2004)

SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:DISC:ROTOR

TSB #02802 -- WHEEL FILM FOR BRAKE ROTOR RUST PREVENTION. *TT (NHTSA ID #10000652, DECEMBER 17 2002)

ENGINE AND ENGINE COOLING

TSB #00203 -- PART NUMBERS FOR THE INTAKE AIR SURGE TANK HAVE BEEN UPDATED. THIS SERVICE BULLETIN REPLACES EG00202 FOR THE 2003 CAMRY. *EH (NHTSA ID #10011481, FEBRUARY 20 2003)

ENGINE AND ENGINE COOLING:ENGINE

TSB #01507 -- 2AZ-FE ENGINE BLOCK. *KB (NHTSA ID #10021542, APRIL 06 2007)

TSB #02206 -- M.I.L. ON DTC P0440, P0441, P0442, P0446, AND/OR P0456 - FUEL FILLER TUBE IMPROVEMENT. *TT (NHTSA ID #10020014, APRIL 11 2006)

TSB #05104 -- MALFUNCTION INDICATOR LAMP ON DIAGNOSTIC TROUBLE CODE P0604, P0606 AND/OR P0607. *TT (NHTSA ID #10011863, DECEMBER 21 2004)

TSB #04004 -- ACCESSORY DRIVE BELT SQUEAL/ BELT TENSIONER RATTLE. *NM (NHTSA ID #10010160, SEPTEMBER 08 2004)

TSB #03704 -- ENGINE BANK 1 AND BANK 2 A/F AND 02 IDENTIFICATION. VARIOUS TOYOTA MODELS. *TT (NHTSA ID #10010021, SEPTEMBER 03 2004)

TSB #02404 -- MALFUNCTION INDICATOR LAMP ON WITH DIAGNOSTIC TROUBLE CODE P0420. *TT (NHTSA ID #10009703, JULY 01 2004)

TSB #01304 -- EXCESSIVE SULFUR DIOXIDE ODOR ON VEHICLES EQUIPPED WITH THE 2AZ-FE ENGINE WHEN STOP AND GO DRIVING AND/OR HEAVY ACCELERATION. *TT (NHTSA ID #10015807, MAY 24 2004)

TSB #01104 -- EXCESSIVE SULFUR DIOXIDE ODOR. *TT UPDATE. *TT (NHTSA ID #10007648, MAY 13 2004)

TSB #01603 -- ENGINE CONTROL MODULE (ECM) CALIBRATION UPDATE - MALFUNCTION INDICATOR LAMP (MIL) ON WITH DIAGNOSTIC TROUBLE CODE P0142. *TT (NHTSA ID #10005251, NOVEMBER 07 2003)

TSB #01503 -- MALFUNCTION INDICATOR LAMP (MIL) ON WITH DIAGNOSTIC TROUBLE CODE (DTC) P0031, P0051, P2238 OR P2241. *TT (NHTSA ID #10004499, OCTOBER 28 2003)

TSB #EG01303 -- MALFUNCTION INDICATOR LAMP ON WITH DIAGNOSTIC TROUBLE CODE P0440, P0441 AND/OR P0446 STORED. *TT (NHTSA ID #10003965, SEPTEMBER 29 2003)

TSB #EG01303R -- MALFUNCTION INDICATOR LAMP ON WITH DIAGNOSTIC TROUBLE CODE P0440, P0441 AND/OR P0446 STORED. *TT (NHTSA ID #10004636, SEPTEMBER 29 2003)

TSB #00803 -- SURGING DURING LIGHT THROTTLE INPUT AT SPEEDS BETWEEN 38-42 MPH WITH LOCK-UP (L/U) ON. *TT *JB (NHTSA ID #10001996, MAY 16 2003)

TSB #00203 -- MALFUNCTION INDICATOR LAMP ON CONDITION WITH DIAGNOSTIC TROUBLE CODE P2102, P2103, P2111, P2112 OR P2119 STORED IN THE ENGINE CONTROL MODULE. *TT (NHTSA ID #10001354, FEBRUARY 20 2003)

TSB #02202 -- TRIPLE SHOCK (SHUDDER) DURING THE 2-3 UP SHIFT UNDER LIGHT THROTTLE ACCELERATION. *TT (NHTSA ID #10000659, DECEMBER 23 2002)



ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:MANIFOLD/HEADER/MUFFLER/TAIL PIPE

TSB #01804 -- INTAKE MANIFOLD NOISE. *MJ WARRANTY INFORMATION CHANGE. *TT (NHTSA ID #10008384, JUNE 03 2004)

FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY:FILLER PIPE AND CAP

TSB #01504 -- FUEL DOOR IMPROVEMENT. *TT (NHTSA ID #10009704, JULY 05 2004)

POWER TRAIN

TSB #00204 -- THE PROPER IDENTIFICATION OF THE 7 SOLENOIDS USED IN THE U151E/U151F TRANSMISSIONS. *TT (NHTSA ID #10007125, APRIL 06 2004)

TSB #00803 -- ENGINE CONTROL MODULE (ECM) CALIBRATION - SHIFTING ENHANCEMENT. *TT (NHTSA ID #10005245, NOVEMBER 14 2003)

POWER TRAIN:AUTOMATIC TRANSMISSION

TSB #00504 -- PROPER IDENTIFICATION OF THE 5 SOLENOIDS USED IN THE U240E/U241E AUTOMATIC TRANSAXLES. *TT (NHTSA ID #10009397, AUGUST 26 2004)