

June 8, 2011

This is to inform you that another incident happened with the 2005 Cobalt since February 2011. This incident happened on June 5, 2011. My daughter was traveling down Lasher Rd in Detroit at approximately 40 miles an hour, and hit a pot hole. The steering column went out, she was able to pull to the side of the road and restart the car. Again, it does not appear that the recall solution by General Motors is effective.

Detroit, MI


ET
062111
TW

CERTIFIED MAIL



1001 6060 4044

6/14/2011 12:37:03 PM



U.S. POSTAGE
PAID
DETROIT, MI
48219
JUN 08
AMOUNT

\$5.59

1090

20590

DOT Mailroom

TO: W48- 226

Building: DOT

Mailstop: 4 West

Route Sym: NVS-200,210,300,010

external carrier: Certified

Sender:

Manufacturer:

Purchase Order:

Item 1 of 1



70100780000160604044

U.S. Department of Transportation
National Hwy Traffic Safety Admin.
Office of Defect Division (NVS-210)
200 New Jersey Avenue, S.E.
West Building
Washington, DC 20590
W48-226