

MEMEMO

MEMO

MEMO


MEMO

3

PLEASE FIND ENCLOSED DATA THAT MAILED TO TO STUDY AND
BRING TO THE REQUESTED COMPLETION. THE TRUCK IS IN MY
GARAGE AT OUR RETIREMENT HOUSE IN STUARTS DRAFT, VA.

THE KEYS WERE LOST AND IT HAS NOT BEEN DRIVEN FOR QUITE
SOME TIME - - PERFECT SHAPE BUT NEEDING YOUR REQUESTED
'UP TO FORD' MODIFICATIONS ADVICE. NEEDED! ! !

SEP 20 2011


ENCL. +
TAKOMA PARK, MDTEL. 

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121



COPY

May 2011



44933/000123022/000000440



TAKOMA PARK, MD

2005 F-150 Ford Truck

Vehicle ID #: 1FTRF14W75N

11S18

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the Vehicle Identification Number shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue?

On your vehicle, it may be possible for the clockspring to driver side frontal air bag wire harness to chafe on the horn mounting plate. Chafing of this wiring harness may cause the driver side frontal air bag to inadvertently deploy which presents a risk of injury from the deployment of the air bag and/or a loss of vehicle control. This chafing may also cause the air bag warning lamp to illuminate in the instrument panel indicating service is required immediately. The air bag warning lamp should never be ignored - it can indicate that the airbag may deploy inadvertently or that it may not deploy in a crash.

What will Ford and your dealer do?

Ford Motor Company has authorized your dealer to replace the clockspring to driver side frontal air bag wire harness with a service part that incorporates additional chafe protection free of charge (parts and labor).

How long will it take?

The time needed for this repair is less than one half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What should you do?

Please call your dealer without delay and request a service date for Recall 11S18. Provide the dealer with the Vehicle Identification Number (VIN) of your vehicle. The VIN is printed near your name at the beginning of this letter.

If you do not already have a servicing dealer, you can access www.Fordowner.com for dealer addresses, maps, and driving instructions.

over.
OVER.

**What should
you do?
(Continued)**

Ford Motor Company wants you to have this safety recall completed on your vehicle. The vehicle owner is responsible for making arrangements to have the work completed. Ford Motor Company can deny coverage for any vehicle damage that may result from the failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

**Have you
previously
paid for this
repair?**

If you have previously paid for a repair that addresses the issue described in this letter, you still need to have this recall performed to ensure the correct parts and procedures were used.

You may be eligible for a refund of previously paid repairs. Refunds will only be provided for service related to the replacement of a clockspring that caused air bag warning lamp illumination or a driver side frontal air bag that inadvertently deployed (not in a crash). To verify eligibility and expedite reimbursement, give your paid original receipt to your dealer.

Refund requests may also be sent directly to Ford Motor Company. To request your refund from Ford, send the refund request with all required documentation, including your original repair receipt (no photocopies), to Ford Motor Company at P.O. Box 6251, Dearborn, Michigan 48121-6251. Refund requests mailed to this address may take up to 60 days to process. Your original receipt will be returned to you.

Detailed information regarding eligibility for Ford's reimbursement program and documentation requirements may be obtained by contacting the Ford Customer Relationship Center at 1-866-436-7332.

**What if you no
longer own this
vehicle?**

If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.

You received this notice because government regulations require that notification be sent to the last known owner of record. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

**Can we assist
you further?**

If you have difficulties getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance.

RETAIL OWNERS: If you still have concerns, please contact the Ford Motor Company Customer Relationship Center at 1-866-436-7332 and one of our representatives will be happy to assist you. For the hearing impaired call 1-800-232-5952 (TDD). Representatives are available Monday through Friday: 8:00AM - 5:00PM (Your Local Time).

If you wish to contact us through the Internet, our address is: www.Fordowner.com.

FLEET OWNERS: If you still have concerns, please contact the Fleet Customer Information Center at 1-800-34-FLEET, select option #3 and one of our representatives will be happy to assist you. Representatives are available Monday through Friday: 8:00AM - 5:00PM (Your Local Time).

Or you may contact us through the Internet at www.fleet.ford.com.

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to www.safercar.gov.


Thank you for your attention to this important matter.

Ford Customer Service Division

TAKOMA PARK, MD

CAPITAL CITY

24 SEP 2011 PM 4:11



ADMINISTRATOR,
NATIONAL HIGHWAY TRAFFIC SAFETY ADM.
1200 NEW JERSEY AVE. S.E.
WASHINGTON, D.C. 20590

