

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)


NVS - 200

4

SEP 20 2011

September 9, 2011

CL-10429911-9961


The Woodlands, Texas

National Highway Traffic Safety Administration
400 Seventh Street, SW
Washington, DC 20590


Reference: 2000 Buick Century - ABS Control Module - Braking Issue

To: Administrator,

I would like for someone to visit the 2000 Buick Century - ABS Control Module System, back in 1999 you had a recall on this very thing, I have enclosed a copy of the recall. We purchase our 2000 Buick Century brand new, and then on October 23, 2007 our ABS light came on and we had it looked at and our mechanic got a trouble code of C1218 and at that time we had him replace the Electronic Brake Control Module, he at that time also purged and flushed the Hydraulic Braking System, cleared the trouble code. The ABS light came on again in December 2007 intermittently, this time the code came up with B0041, this time they replaced the ABS Computer Module, purged and flushed Hydraulic Braking System, and cleared the code. Now again in July of 2010 it came back on intermittently and as of August 2011 it is on all the time, the mechanic is getting a trouble code of C1218 again. I feel like we should not have to replace these parts for a second time. I have enclosed copies of our repairs. We have been told this is a safety issue! I don't want to hurt myself, my family or anyone else. So, can someone please let me know about this issue!

My question is why has this not be looked into as a recall notice, I know I can't be the only person having this issue.

2000 Century Buick - mileage 85,280



NAM
101211
TGW

Description of Recall:

CERTAIN DELPHI FUEL PRESSURE REGULATORS, P/NOS. FP10020-11B1, FP10026-11B1, AND FP10027-11B1, SOLD AFTER JANUARY 9, 2007, AS AFTERMARKET EQUIPMENT FOR VARIOUS PASSENGER VEHICLES LISTED ABOVE. THE UNIVERSAL PRESSURE REGULATORS (UPR) WERE PRODUCED WITHOUT AN O-RING AND RETAINER.

Action Needed To Fix It:

DELPHI WILL NOTIFY OWNERS AND REPLACE THE UPR FREE OF CHARGE. THE RECALL BEGAN ON APRIL 23, 2007. OWNERS CAN CONTACT DELPHI AT 877-411-8770.

Find your local **Buick Dealer**.

1999 Buick CENTURY Recall

Item Affected: FUEL SYSTEM, OTHER:STORAGE:TANK ASSEMBLY:PRESSURE RELIEF DEVICES

Date Announced: 3/12/2007

Description of Recall:

CERTAIN DELPHI FUEL PRESSURE REGULATORS, P/NOS. FP10020-11B1, FP10026-11B1, AND FP10027-11B1, SOLD AFTER JANUARY 9, 2007, AS AFTERMARKET EQUIPMENT FOR VARIOUS PASSENGER VEHICLES LISTED ABOVE. THE UNIVERSAL PRESSURE REGULATORS (UPR) WERE PRODUCED WITHOUT AN O-RING AND RETAINER.

Action Needed To Fix It:

DELPHI WILL NOTIFY OWNERS AND REPLACE THE UPR FREE OF CHARGE. THE RECALL BEGAN ON APRIL 23, 2007. OWNERS CAN CONTACT DELPHI AT 877-411-8770.

Find your local **Buick Dealer**.

1999 Buick CENTURY Recall

Item Affected: SERVICE BRAKES, HYDRAULIC:ANTILOCK

Date Announced: 7/13/1999

Description of Recall:

SOME OF THESE VEHICLES WITH THE KEY IN THE "ON" POSITION, EXHIBIT A CONDITION IN WHICH THE ANTILOCK BRAKE SYSTEM (ABS) MOTOR SHORTS TO ITS CASE AND GROUNDS THROUGH A FLEXIBLE BRAKE FLUID PIPE.

Action Needed To Fix It:

DEALERS WILL INSTALL A GROUND CABLE FROM THE ELECTRONIC BRAKE CONTROL MODULE (EBCM) TO THE ENGINE COMPARTMENT BODY RAIL.

Find your local **Buick Dealer**.

1999 Buick CENTURY Recall

Item Affected: EXTERIOR LIGHTING:HEADLIGHTS

Date Announced: 1/10/2000

Description of Recall:

VEHICLE DESCRIPTION: PASSENGER VEHICLES. THESE VEHICLES DO NOT CONFORM TO THE REQUIREMENTS OF FMVSS NO. 108, "LAMPS, REFLECTIVE DEVICES, AND ASSOCIATED EQUIPMENT." THE VERTICAL HEAD LAMP ADJUSTING DEVICE MAY NOT BE CALIBRATED PROPERLY.

Action Needed To Fix It:

OWNERS WILL BE PROVIDED WITH AN OWNER'S MANUAL INSERT CONTAINING INSTRUCTIONS FOR OPTICALLY AIMING THE HEADLAMPS.

Find your local **Buick Dealer**.

1999 Buick CENTURY Recall

Item Affected: EXTERIOR LIGHTING:HEADLIGHTS

Date Announced: 8/11/2004

Description of Recall:

CERTAIN PASSENGER VEHICLES DO NOT CONFORM TO THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 108, "LAMPS, REFLECTIVE DEVICES, AND ASSOCIATED EQUIPMENT." SOME OF THESE VEHICLES DO NOT MEET THE OVERHEAD SIGN ILLUMINATION REQUIREMENTS.

Action Needed To Fix It:

DEALERS WILL INSTALL NEW LOW BEAM HEADLAMP BULBS IN BOTH OF THE HEADLAMP ASSEMBLIES. THE RECALL BEGAN ON SEPTEMBER 8, 2004. OWNERS SHOULD CONTACT BUICK AT 1-866-608-8080. NOTE: IF THE BULB NEEDS REPLACEMENT IN THE FUTURE, GM BULB NUMBER 89024715 IS AVAILABLE FROM A DEALER, OR THE EQUIVALENT SYLVANIA BULB IS 9006HP, WITH ORANGE LETTERING ON THE BULB.

Find your local **Buick Dealer**.

1999 Buick CENTURY Recall

Item Affected: STEERING

Date Announced: 2/17/2009

Description of Recall:

DORMAN IS RECALLING 979 STEERING KNUCKLES, DORMAN P/NOS. 697-902 AND 697-903, SOLD UNDER DORMAN'S "OE SOLUTIONS™" BRAND NAME, AND NAPA P/NOS. 7-8502 AND 7-8503 WHICH WERE SOLD FOR REPLACEMENT USE ON THE VARIOUS VEHICLES LISTED ABOVE. A POTENTIAL MATERIAL OR DESIGN DEFECT COULD RESULT IN THE STEERING KNUCKLE BREAKING IN THE HUB AREA.



YOUR CAR CARE PARTNERS

2445 High Timbers
The Woodlands, Texas 77380
(281) 363-0667
www.byrdautomotive.com

REPAIR ORDER #: 0102832

DATE: 10/23/07

PAGE: 1

SERVICE ADVISOR: 2

CUSTOMER: [REDACTED]	VEHICLE: 2000 BUIC CENTURY FWD
ADDRESS: [REDACTED]	LICENSE: [REDACTED] 05/00
CITY: THE WOODLANDS, TX	V.I.N.: 2G4WY55J3Y1 [REDACTED]
PHONE 1: [REDACTED]	ENGINE: V6-191 3.1L
PHONE 2: [REDACTED]	TRANS: AUTO
WORK CELL	MILEAGE: 59950
	SILVER

PARTS		LABOR	
QUANTITY	PRICE	DESCRIPTION	PRICE
1.00	28.75 CR 00 JL	CUSTOMER REQUEST: 1. THE ABS LIGHT CAME ON & STAYED ON FOR ABOUT A WEEK AND WENT OFF THIS WEEKEND. CUSTOMER REQUESTS SCAN FOR CODES & REPORT. 2. STATE INSPECTION	0.00
	BR 00 CW	ABS SCAN TEST: CONNECT SCANNER TO COMPUTER AND CHECK FOR CODES. REFER TO APPROPRIATE DIAGNOSTIC CHARTS FOR TESTING SENSORS IN SYSTEM WITH VOLT METER AND SCANNER. RESULTS: THE TECHNICIAN RECOVERED TROUBLE CODE C1218 FROM THE CONTROL MODULE WHICH IS DETECTING A SHORT IN THE PUMP MOTOR. HE REPORTS THE ABS LIGHT COMES BACK ON WHEN THE ABS SYSTEM IS ACTIVATED.	94.65
	SI OB RGG	OB-2 STATE INSPECTION INCLUDES SAFETY INSPECTION AND OBD EMISSION INSPECTION.	11.00

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. NOT RESPONSIBLE FOR DAMAGE OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL.

X

LABOR:	\$105.65
PARTS:	\$28.75
SUBLET:	\$0.00
OTHER FEES:	\$0.00
SUPPLIES:	\$0.00
SUB-TOTAL:	\$134.40
TAX:	\$0.00
TOTAL:	\$134.40
PAID:	\$0.00
DUE:	\$134.40

NOTICE PURSUANT TO §70.001, TEXAS PROPERTY CODE
I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON WHO IS OBLIGATED TO PAY FOR THE REPAIRS OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR CONTRACT. I UNDERSTAND THAT THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.503 TEXAS BUSINESS AND COMMERCE CODE, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE DRAWER OR MAKER OF THE ORDER OR CREDIT CARD HOLDER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

Signature of Person Responsible or Agent for Person Responsible



YOUR CAR CARE PARTNERS

2445 High Timbers
The Woodlands, Texas 77380
(281) 363-0667
www.byrdautomotive.com

REPAIR ORDER #0002724

Date Printed : 10/23/07

Page : 1

Center : 2

Customer : [REDACTED]
Address : [REDACTED]
City : THE WOODLANDS, TX [REDACTED]
Work : [REDACTED] Ext : WORK
Cellular : [REDACTED] Ext : CELL

VEHICLE : 2000 BUIC CENTURY FWD

LICENSE : [REDACTED]

P/D : 05/00

V.I.N. : 2G4WY55J3Y1 [REDACTED]

ENGINE : V6-191 3.1L

TRANS : AUTO

MILEAGE : 59950

COLOR : SILVER

Parts

Labor

Quan	Part Number	Description	Price
1	EBCM		785.68

Op	Tech	Description	Time	Charge
BR 00	JL	REMOVE AND REPLACE ELECTRONIC BRAKE CONTROL MODULE - PURGED AND FLUSHED HYDRAULIC BRAKING SYSTEM, CLEARED TROUBLE CODES AND ROAD TESTED FOR PROPER BRAKING ABS AND/OR TRACTION CONTROL FUNCTIONS	1.70	217.70

OK Bad

Recomendation

OK Bad

Recomendation

OK Bad

Recomendation

Labor :	\$217.70
Parts :	\$785.68
Sublet :	\$0.00
Other Fees :	\$0.00
EPA FEE:	\$41.71
Subtotal :	\$1,045.09
Sales Tax :	\$56.96
Total :	\$1,102.05



YOUR CAR CARE PARTNERS

2445 High Timbers
The Woodlands, Texas 77380
(281) 363-0667
www.byrdautomotive.com

REPAIR ORDER #: 0103589

DATE: 12/28/07

PAGE: 1

SERVICE ADVISOR: 2

CUSTOMER: [REDACTED]	VEHICLE: 2000 BUIC CENTURY FWD
ADDRESS: [REDACTED]	LICENSE: [REDACTED] 05/00
CITY: THE WOODLANDS, TX [REDACTED]	V.I.N.: 2G4WY55J3Y1 [REDACTED]
PHONE 1: [REDACTED] WORK	ENGINE: V6-191 3.1L TRANS: AUTO
PHONE 2: [REDACTED] CELL	MILEAGE: 61084 SILVER

PARTS

LABOR

QUANTITY	PRICE	DESCRIPTION	PRICE
1.00	785.68	CC 00 JL CUSTOMER STATES:	0.00
		1. THE ABS LIGHT IS STILL COMING ON AND GOING OFF INTERMITTENTLY...CW/RW	
		2. THE AIRBAG LIGHT CAME ON & IS STAYING ON	
		DG 01 CW AIRBAG ELECTRICAL SYSTEM TEST AND INSPECT	94.65
		RESULTS:	
		THE TECHNICIAN RECOVERED A DIAGNOSTIC TROUBLE CODE B0041 FROM THE COMPUTER... LEFT SIDE DEPLOY LOOP RESISTANCE OPEN CIRCUIT DETECTED. THE TECHNICIAN TRACED AND CHECKED RELATED ELECTRICAL CIRCUITS, CONNECTIONS, RELAYS, FUSES. NO PROBLEM IS FOUND AND NO OPEN CIRCUIT IS DETECTED. HE CLEARED THE CODE AND THE LIGHT DID NOT COME BACK ON DURING ROAD TESTING	
		BR 00 CW REMOVE AND REPLACE ABS COMPUTER MODULE. PURGED AND FLUSHED HYDRAULIC BRAKING SYSTEM. CLEARED TROUBLE CODES AND ROAD TESTED FOR PROPER BRAKING ABS FUNCTIONS	217.70

WARRANTY

12 MONTHS OR 18,000 MILES
WHICHEVER OCCURS FIRST

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. NOT RESPONSIBLE FOR DAMAGE OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL.

X

NOTICE PURSUANT TO §70.001, TEXAS PROPERTY CODE

I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON WHO IS OBLIGATED TO PAY FOR THE REPAIRS OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR CONTRACT. I UNDERSTAND THAT THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.503 TEXAS BUSINESS AND COMMERCE CODE, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE DRAWER OR MAKER OF THE ORDER OR CREDIT CARD HOLDER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

LABOR: \$312.35
PARTS: \$785.68
SUBLET: \$0.00
OTHER FEES: \$0.00
SUPPLIES: \$19.49
SUB-TOTAL: \$1,117.52
TAX: \$56.96

TOTAL: \$1,174.48

PAID: \$0.00
DUE: \$1,174.48

Signature of Person Responsible or Agent for Person Responsible



YOUR CAR CARE PARTNERS

2445 High Timbers
The Woodlands, Texas 77380
(281) 363-0667
www.byrdautomotive.com

REPAIR ORDER #: 0118877
DATE: 9/6/11
PAGE: 1
SERVICE ADVISOR: 2

CUSTOMER:		VEHICLE:	2000 BUIC CENTURY FWD	
ADDRESS:		LICENSE:		05/00
CITY:	THE WOODLANDS, TX	V.I.N.:	2G4WY55J3Y1	
PHONE 1:		ENGINE:	V6-191 3.1L	TRANS: AUTO
PHONE 2:		MILEAGE:	85280	SILVER
	WORK			
	CELL			

PARTS

LABOR

QUANTITY	PRICE	DESCRIPTION	PRICE
1.00	WINDOW REGULATOR 193.12	Service Requests:	
1.00	BG 84032 BRAKE FLUID Decline	CUSTOMER REQUEST: DROP-OFF	
1.00	BRAKE/PARTS CLEANER Decline	1. THE PASSENGER SIDE FRONT WINDOW HAS	
2.00	ANTIFREEZE GLOBAL Decline	FALL IN	
1.00	BG 5901 CLNG SYS K Decline	DOWN AND DOES NOT WORK.	
15.00	DEXRON TRANS. FLUID 88.35	2. THE ABS LIGHT HAS COME BACK ON.	
1.00	BG 6600 TRANS KIT 51.87 BR 00 AC	ABS-SCAN TEST: CONNECT SCANNER TO	99.31
1.00	ECBM Decline	COMPUTER AND CHECK FOR CODES. REFER TO	
		APPROPRIATE DIAGNOSTIC CHARTS FOR	
		TESTING SENSORS IN SYSTEM WITH VOLT	
		METER AND SCANNER.	
		RESULTS:	
		RECOVERED TROUBLE CODE C1218 FROM THE	
		COMPUTER... PUMP MOTOR SHORT OR OPEN	
		CIRCUIT DETECTED. THE ECBM HAS AN	
		INTERNAL FAILURE AND NEEDS REPLACED	
	BR 00 AC	REMOVE AND REPLACE ABS COMPUTER MODULE.	Declined
		PURGED AND FLUSHED HYDRAULIC BRAKING	
		SYSTEM, CLEARED TROUBLE CODES AND ROAD	
		TESTED FOR PROPER BRAKING ABS FUNCTIONS	
	OP 00 AC	DISASSEMBLE PASSENGER FRONT DOOR PANEL &	148.96
		SKIN TO INSPECT WINDOW TRACK AND GEAR	

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. NOT RESPONSIBLE FOR DAMAGE OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL.

X

NOTICE PURSUANT TO §70.001, TEXAS PROPERTY CODE

I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON WHO IS OBLIGATED TO PAY FOR THE REPAIRS OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR CONTRACT. I UNDERSTAND THAT THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.503 TEXAS BUSINESS AND COMMERCE CODE, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE DRAWER OR MAKER OF THE ORDER OR CREDIT CARD HOLDER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

Signature of Person Responsible or Agent for Person Responsible

LABOR: \$376.62
PARTS: \$333.34
SUBLET: \$0.00
OTHER FEES: \$29.07
SUPPLIES: \$739.03
SUB-TOTAL: \$27.50
TAX:
TOTAL: \$766.53
PAID: \$0.00
DUE: \$766.53



YOUR CAR CARE PARTNERS

2445 High Timbers
The Woodlands, Texas 77380
(281) 363-0667
www.byrdautomotive.com

REPAIR ORDER #: 0118877

DATE: 9/6/11

PAGE: 2

SERVICE ADVISOR: 2

CUSTOMER:		VEHICLE:	2000 BUIC CENTURY FWD	
ADDRESS:		LICENSE:		05/00
CITY:	THE WOODLANDS, TX	V.I.N.:	2G4WY55J3Y1	
PHONE 1:		ENGINE:	V6-191 3.1L	TRANS: AUTO
PHONE 2:		MILEAGE:	85280	SILVER
		WORK		
		CELL		

PARTS

LABOR

QUANTITY	PRICE	DESCRIPTION	PRICE
		ASSEMBLY. TEST & INSPECT FOR INOPERATIVE ELECTRICAL OR MECHANICAL COMPONENTS.	
		RESULTS:	
		THE TECHNICIAN FINDS THAT THE WINDOW REGULATOR IS BAD & NEEDS REPLACED	
OP WR AC		REPLACE POWER WINDOW REGULATOR ASSEMBLY IN THE PASSENGER FRONT DOOR. REASSEMBLE DOOR PANEL & TEST FOR PROPER WINDOW OPERATION.	54.16
PM TN AC		TECHNICIAN COMMENTS	0.00
		1. THE BRAKE FLUID IS DUE TO BE FLUSHED AGAIN	
		2. THE REAR BRAKES NEED CLEANED & ADJUSTED	
		3. THE ENGINE COOLANT IS WEAK & ACIDIC	
		4. THE TRANSMISSION FLUID IS DARK & WORN & STILL NEEDS FLUSHED	
BG BS AC		BG BRAKE SYSTEM FLUSH SERVICE	Declined
		SUCTION OLD BRAKE FLUID OUT OF BRAKE MASTER CYLINDER AND REFILL WITH BG BRAKE FLUID. INSTALL PRESSURE BLEEDER ONTO MASTER CYLINDER IN ORDER TO FLUSH THE	

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. NOT RESPONSIBLE FOR DAMAGE OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL.

X

NOTICE PURSUANT TO §70.001, TEXAS PROPERTY CODE

I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON WHO IS OBLIGATED TO PAY FOR THE REPAIRS OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR CONTRACT. I UNDERSTAND THAT THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.503 TEXAS BUSINESS AND COMMERCE CODE, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE DRAWER OR MAKER OF THE ORDER OR CREDIT CARD HOLDER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

Signature of Person Responsible or Agent for Person Responsible

LABOR:	\$376.62
PARTS:	\$333.34
SUBLET:	\$0.00
OTHER FEES:	\$29.07
SUPPLIES:	\$739.03
SUB-TOTAL:	\$27.50
TAX:	
TOTAL:	\$766.53
PAID:	\$0.00
DUE:	\$766.53



YOUR CAR CARE PARTNERS

2445 High Timbers
The Woodlands, Texas 77380
(281) 363-0667
www.byrdautomotive.com

REPAIR ORDER #: 0118877

DATE: 9/6/11

PAGE: 3

SERVICE ADVISOR: 2

CUSTOMER:		VEHICLE:	2000 BUIC CENTURY FWD	
ADDRESS:		LICENSE:		05/00
CITY:	THE WOODLANDS, TX	V.I.N.:	2G4WY55J3Y1	
PHONE 1:		ENGINE:	V6-191 3.1L	TRANS: AUTO
PHONE 2:		MILEAGE:	85280	SILVER
		WORK		
		CELL		

PARTS

LABOR

QUANTITY	PRICE	DESCRIPTION	PRICE
		SYSTEM OF THE REMAINING CONTAMINANTS IN THE BRAKE LINES AND HYDRAULIC COMPONENTS. TOP MASTER CYLINDER OFF WITH BG BRAKE FLUID.	
BR CA AC		REMOVE REAR BRAKE DRUMS. CLEAN ENTIRE BRAKE ASSEMBLY WITH NON-CHLORINATED SOLVENT. DE-GLAZE BRAKE SHOES AND BRAKE DRUMS. LUBRICATE SELF-ADJUSTING MECHANISMS. MANUALLY ADJUST BRAKE SHOES AND RE-ASSEMBLE.	Declined
BG CS AC		BG COOLING SYSTEM FLUSH SERVICE TECHNICIAN ADDED COOLING SYSTEM CLEANSER TO THE VEHICLE COOLING SYSTEM FLUID. OPERATED ENGINE FOR 25-MINUTES WITH HEATER IN MAX SETTING. DRAINED RADIATOR FLUID, ATTACHED COOLANT FLUSH MACHINE, FLUSHED COOLING SYSTEM, FILLED WITH APPROVED COOLANT AND ADDED BG COOLANT CONDITIONER ADDITIVE.	Declined
BG TR AC		BG TRANSMISSION FLUSH SERVICE TECHNICIAN ADDED TRANSMISSION CLEANSER WITH THE OLD TRANSMISSION FLUID,	111.56

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. NOT RESPONSIBLE FOR DAMAGE OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL.

X

LABOR:	\$376.62
PARTS:	\$333.34
SUBLET:	\$0.00
OTHER FEES:	\$0.00
SUPPLIES:	\$29.07
SUB-TOTAL:	\$739.03
TAX:	\$27.50
TOTAL:	\$766.53
PAID:	\$0.00
DUE:	\$766.53

NOTICE PURSUANT TO §70.001, TEXAS PROPERTY CODE

I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON WHO IS OBLIGATED TO PAY FOR THE REPAIRS OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR CONTRACT. I UNDERSTAND THAT THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.503 TEXAS BUSINESS AND COMMERCE CODE, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE DRAWER OR MAKER OF THE ORDER OR CREDIT CARD HOLDER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

Signature of Person Responsible or Agent for Person Responsible



YOUR CAR CARE PARTNERS

2445 High Timbers
The Woodlands, Texas 77380
(281) 363-0667
www.byrdautomotive.com

REPAIR ORDER #: 0118877

DATE: 9/6/11

PAGE: 4

SERVICE ADVISOR: 2

CUSTOMER: [REDACTED]
ADDRESS: [REDACTED]
CITY: THE WOODLANDS, TX [REDACTED]
PHONE 1: [REDACTED] WORK
PHONE 2: [REDACTED] CELL

VEHICLE: 2000 BUIC CENTURY FWD
LICENSE: [REDACTED] 05/00
V.I.N.: 2G4WY55J3Y1 [REDACTED]
ENGINE: V6-191 3.1L
MILEAGE: 85280
TRANS: AUTO
SILVER

PARTS

LABOR

QUANTITY	PRICE	DESCRIPTION	PRICE
		OPERATED VEHICLE AT 1200 RPM FOR 20-MINUTES, ATTACHED TRANSMISSION FLUSH MACHINE TO VEHICLE TRANSMISSION OIL COOLER LINES, FLUSHED OUT OLD TRANSMISSION FLUID AND REPLACED WITH APPROVED TYPE TRANSMISSION FLUID, ADDED BG TRANSMISSION SHIFT ADDITIVE TO NEW FLUID.	
		LABOR DISCOUNT	-37.37

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. NOT RESPONSIBLE FOR DAMAGE OR ARTICLES LEFT IN CAR IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL.

X


NOTICE PURSUANT TO §70.001, TEXAS PROPERTY CODE

I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON WHO IS OBLIGATED TO PAY FOR THE REPAIRS OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR CONTRACT. I UNDERSTAND THAT THIS VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.503 TEXAS BUSINESS AND COMMERCE CODE, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE DRAWER OR MAKER OF THE ORDER OR CREDIT CARD HOLDER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

Signature of Person Responsible or Agent for Person Responsible

LABOR:	\$376.62
PARTS:	\$333.34
SUBLET:	\$0.00
OTHER FEES:	\$29.07
SUPPLIES:	\$739.03
SUB-TOTAL:	\$27.50
TAX:	
TOTAL:	\$766.53
PAID:	\$0.00
DUE:	\$766.53

[REDACTED]
The Woodlands, Texas



National Highway Traffic Safety Administration
400 Seventh Street, SW
Washington, DC 20590
Attn: Administrator

SAFETY ISSUE