

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C . 552(B)(6)

From: [Wells, Cynthia CTR \(NHTSA\)](#)
To: [Fogle, Brenda CTR \(NHTSA\)](#)
Subject: FW: Correction to ODI Complaint - 10456854
Date: Thursday, May 17, 2012 8:34:05 AM
Attachments: [ODI Complaint - 10456854.PDF](#)

EQ-10456854-6800

From: Williams, Maritza CTR (NHTSA) **On Behalf Of** DataQuality, DataQuality (NHTSA)
Sent: Wednesday, May 16, 2012 10:56 AM
To: Wells, Cynthia CTR (NHTSA)
Subject: FW: Correction to ODI Complaint - 10456854

From: [REDACTED]
Sent: Wednesday, May 16, 2012 10:45 AM
To: DataQuality, DataQuality (NHTSA)
Subject: Correction to ODI Complaint - 10456854

I have reviewed the attached document. I made corrections to my contact telephone number which is [REDACTED] Everything else is correct.

Thank you,

[REDACTED]



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received	Repository <input type="checkbox"/>
30-APR-2012	Reference No. 10456854

OWNER INFORMATION (Type or Print)

Name		Daytime Telephone Number		E-mail Address	
Address					
City	State	Zip Code	Evening Telephone Number		
ROUND ROCK	TX				

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 1GKFK66U74J		Make GMC	Model YUKON DENALI XL	Model Year 2004
Date Purchased	Dealer's Name and Telephone Number		Engine: No: Cylinders	Fuel Type:
Original Owner <input type="checkbox"/>	Dealer's City	State	Zip Code	
Transmission Type	<input type="checkbox"/> Antilock Brakes <input type="checkbox"/> Cruise Control	Powertrain	Multiple Failure:	Incident Date(s) 15-APR-2012

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 030000 SERVICE BRAKES, HYDRAULIC	Failure Mileage 189000	Failure Speed 0
--	---------------------------	--------------------

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTM19ABC036)	<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair	Failure Location:
Tire Component Code	Tire Failure Type:	

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured	Number of Deaths	Reported to Police N
--	---	---------------------------	------------------	-------------------------

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL* THE CONTACT OWNS A 2004 YUKON DENALI XL. THE CONTACT STATED THAT FLUID WAS LEAKING FROM THE HYDRAULIC BRAKE BOOSTER AND THE RELEASE VALVE. THE VEHICLE ALSO EMITTED A LOUD NOISE WHEN IT WAS STARTED. THE CONTACT TOOK THE VEHICLE TO AN INDEPENDENT MECHANIC, WHO INSPECTED THE BRAKES AND INFORMED THE CONTACT THAT THE HYDRAULIC BRAKE BOOSTER AND THE RELEASE VALVE NEEDED TO BE REPLACED. THE DEALER WAS NOTIFIED AND STATED THAT THERE WAS A RECALL ASSOCIATED WITH NHTSA CAMPAIGN ID NUMBER 05V043000 (SERVICE BRAKES, HYDRAULIC). THE VIN WAS NOT INCLUDED IN THE RECALL. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED. THE FAILURE MILEAGE WAS 189,000.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.

ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.