

C1-10486703-5965

[REDACTED]
Fenton, MI

Oct 11, 2012

OCT 16 2012

✓ NHTSA
US Department of Transportation
Washington DC 20590

GMC Customer Assistance Center
PO Box 33172
Detroit MI 48232-5172


INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

RE: Headlight Connector 2004 GMC Envoy


I have had the headlight connector (Replacement part # AC Delco PT2079, GM# 88988700) MELT, apparently from over heating. I'm not sure if this would be considered a fire hazard but it is certainly a hazard to have an inoperative headlamp.


In trying to find a replacement part it appears this is a common problem. I ran into two other people that told me it had happened to them. Also in searching for this part a two junk yards none were available, they had already been removed from the scraped vehicles. I have located and purchased a replacement part from a GMC dealer.

I hope you will look into this mater. If you would like the melted part sent to you please let me know.



NM
10/16/12
TRW






Fenton, MI

METROPLEX MI 450

11 OCT 2012 PM 5 L



NHTSA
US Department of Transportation
Washington DC 20590

20590

