

Date: March 27, 2013

CL-10503469-1302

National Highway Traffic Safety Administration
Office of Defects Investigations
NVS-210
1200 New Jersey Avenue, SE
West Building
Washington, DC 20590

APR - 3 2013

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Re: NHTSA Confirmation No. 10503469

Please be advised that my wife and I have both experienced events that I believe represent a serious safety issue with this automobile.

On Thursday, March 28 wife reported to me that she experience an unintended acceleration event on this day. List below is a summary of the event.

SUMMARY OF UNITENDED ACCELERATION EVENT:

1. Started car, shifted into drive.
2. With foot still firmly on the brake, the engine accelerated dramatically to what my wife characterized as full throttle.
3. Pressed hard on brake pedal and immediately shifted into park.
4. Engine speed immediately returned to normal speed.
5. Car was picked up immediately thereafter for delivery to the dealer, Jaguar of Tulsa.

Submitted by:



03/28/2013
Date


Address:



Broken Arrow, Oklahoma

cc:
Allstate Insurance
Jaguar Land Rover of Tulsa
Jaguar Land Rover North America, LLC


ET
41013
SMD



Broken Arrow, OK

TULSA OK 741

28 MAR 2013 PM 56 L



National Highway Traffic Safety Admin
Office of Defects Investigations
NVS-210
1200 New Jersey Avenue, SE West Building
Washington, DC 20590

