

INFORMATION Redacted PURSUANT TO THE FREEDOM OF

 U.S. Department of Transportation National Highway Traffic Safety Administration		DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline		INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6) FOR AGENCY USE ONLY 100148	
		Date Received 21-AUG-2013		Repository ☐ Reference No. 10536522	
OWNER INFORMATION (Type or Print)					
Name		Address		Daytime Telephone Number	
City		State		Evening Telephone Number	
AURORA		MO			
Zip Code					
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).					
VEHICLE INFORMATION					
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side		Make		Model	
1G1ZT51F06F		CHEVROLET		MALIBU	
Model Year		Engine:		Fuel Type:	
2006		No: Cylinders 4		Gas	
Date Purchased		Dealer's Name and Telephone Number		State	
10-OCT-07		MAYSE AUTOMOTIVE		MO	
Original Owner		Dealer's City		Zip Code	
		AURORA		65605	
Transmission Type		Powertrain		Multiple Failure:	
AUTOMATIC		FRONT WHEEL DRIVE		1 - 3 recalls	
☒ Antilock Brakes ☐ Cruise Control				Incident Date(s)	
				16-AUG-2013	
FAILED COMPONENT(S)/PART(S) INFORMATION					
Vehicle Component Code: 010000 STEERING				Failure Mileage	
				156000	
				Failure Speed	
				20	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE					
Tire Make		Tire Model (Name or Number)		Tire Size (Example P215/65R15)	
DOT No. (Example: DOTM9ABC036)		☐ Original Equipment ☐ Prior Repair		Failure Location:	
Tire Component Code				Tire Failure Type:	
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE					
Make:		Date Manufactured:		Model No./Name:	
Seat Type:		Installation System:			
Child Seat Component Code:		Failed Part:			
APPLICABLE INCIDENT INFORMATION					
(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)					
Crash		Fire		Number of Persons Injured	
☐ Yes ☒ No		☐ Yes ☒ No		0	
				Number of Deaths	
				0	
				Reported to Police	
				N	
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).					
TL* THE CONTACT OWNS A 2006 CHEVROLET MALIBU. THE CONTACT STATED THAT THE STEERING WHEEL FAILED WHILE DRIVING 20 MPH. THE STEERING WHEEL BECAME HARD TO TURN AS THE POWER STEERING LIGHT ILLUMINATED. THE CONTACT TURNED THE ENGINE OFF FOR A MOMENT AND THE STEERING WHEEL BRIEFLY RETURNED TO NORMAL FUNCTION BEFORE THE FAILURE RECURRED. THE VEHICLE WAS TAKEN TO THE MECHANIC AND A DIAGNOSTIC WAS PERFORMED, WHICH LOCATED THE FAILURE AT THE POWER STEERING MOTOR. THE MANUFACTURER DENIED ASSISTANCE WITH THE REPAIR, BECAUSE THE VEHICLE HAD EXCEEDED THE POWER STEERING MOTOR REPLACEMENT MILEAGE. THE VEHICLE WAS NOT REPAIRED. THE FAILURE AND CURRENT MILEAGE WAS 156,000. UPDATED 10/24/13*CN					
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.					
ATTACH ADDITIONAL SHEETS IF NECESSARY					
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					