



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**

1200 New Jersey Avenue, SE  
Washington, DC 20590

November 27, 2013

████████████████████  
████████████████████  
Philadelphia, PA ██████████

NVS-216 am  
Ref. No. 10537655

Dear ██████████

Thank you for your correspondence concerning a model year (MY) 1984 American Motors Jeep Eagle vehicle. The National Highway Traffic Safety Administration's (NHTSA) Office of Defects Investigation received your correspondence. We regret any inconvenience our delay in responding may have caused you.

NHTSA is the Federal agency responsible for improving safety on our Nation's highways. We are authorized to order manufacturers to recall and repair motor vehicles or motor vehicle equipment when our investigations indicate that they contain safety defects in their design, construction, or performance. We also monitor the adequacy of manufacturers' recall campaigns. In order for the agency to initiate an investigation, we look carefully at the body of consumer complaints and other available data to determine whether a defect trend may exist. We do not have authority to act on isolated problems or resolve disputes between individual owners, dealers, or manufacturers.

You want to know if American Motors or Chrysler initiated recalls on the MY 1984 Jeep Eagle vehicle. Also, you want to know if NHTSA initiated recalls. If so, you request copies of the owner notifications. Also you want to know if NHTSA issued technical service bulletins (TSB) for the vehicle.

Our research revealed three recalls that may be of interest to you. We enclose copies of the owner notifications for NHTSA Safety Recall Campaigns No. 09E-021 and No. 07E-064. However, due to the age of recall 83V-119, we do not have a copy of the owner notification. The recall addresses a problem with missing front wheel bearings. All the recalls were initiated by the manufacturer or a supplier. Also, the recalls are available for your review on our web site at [www.safercar.gov](http://www.safercar.gov)

Please note that NHTSA does not issue TSB's. Manufacturers issue TSB's to assist dealers in repairing vehicles with a known problem and to restore customer satisfaction. The issuance of a TSB does not necessarily reflect the existence of a safety-related defect in accordance with the National Traffic and Motor Vehicle Safety Act. Manufacturers are required to send their TSB's to NHTSA which we review and display on [www.safercar.gov](http://www.safercar.gov). Unfortunately, due to the age of this vehicle the TSB's are in a format and media that we cannot display on our web site or economically send to you. We recommend that you contact a local Chrysler dealer regarding the TSB's associated with this vehicle. Also, another resource for TSB information is on the Internet at [www.alldatapro.com](http://www.alldatapro.com).

Should you encounter a safety-related problem with a motor vehicle or motor vehicle equipment in the future, we would appreciate it if you would complete an electronic Vehicle Owner's Questionnaire online at [www.nhtsa.gov](http://www.nhtsa.gov) or call the Auto Safety Hotline at 1-888-327-4236. Also, a summary listing of vehicle owners' complaints, safety recalls, manufacturers' service bulletins, etc. can be obtained at our web site.

Sincerely,

A handwritten signature in cursive script that reads "Randy Reid".

Randy Reid, Chief  
Correspondence Research Division  
Office of Defects Investigation  
Enforcement

Enclosures



Claim # 07E064

October 15, 2007

Dear Valued Customer

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Federal-Mogul has determined that a defect which relates to motor vehicle safety exists in certain mechanical, replacement fuel pumps. Therefore, Federal-Mogul is recalling these specific fuel pumps manufactured by our supplier, Pierce.

1. Identification of equipment affected:

Federal-Mogul packaged and sold the recalled fuel pumps between August 2006 and July 2007 under the following brand names: Carter, Accu-Flow, Parts Depot and Parts Master. These mechanical fuel pumps are limited to 37 base part numbers. The specific part numbers being recalled, affected packaging date codes and vehicle application information is listed in the attachment to this letter.

2. Description of possible malfunction and safety evaluation:

The fuel pump diaphragm in certain production runs may have been improperly installed. Incorrectly installed, the pump diaphragm does not seal properly which could go undetected in the quality control process and may cause the pump to leak. A leaking fuel pump could create a vehicle fire hazard.

3. Vehicle owner precautions:

The subject fuel pumps were manufactured for aftermarket use. Owners of these parts should have them removed and replaced as soon as possible.

4. Owner remedy measures:

Federal-Mogul wishes to recover as many of these parts as possible. Therefore, we respectfully request that you quarantine the subject part numbers containing the affected date codes (per attachment). Dates codes are located on the part number label in the lower left corner. Recalled fuel pumps from your customers also should be returned to Federal-Mogul. For reference, we have included a complete record of these recalled part numbers and our sales records which reflect the parts sales to you.

Once product is quarantined, please notify your local Federal-Mogul sales representative to come in to verify the product return and handle the RGA process. The subject defective part(s) must be written-up by a Federal-Mogul sales representative.

The return of the part(s) will be at no cost to you. Upon return of this part(s), your account will be credited for the part(s). For replacement of recalled product, you will need to order the appropriate stock number from Federal-Mogul customer service.

Parts stores who purchased these items should return them to their servicing warehouse distributor for credit.

If the part is suspected of having been installed on a vehicle, Federal-Mogul will pay for inspection and, if the part is covered by the recall, replacement, as well as shipping charges. In order to qualify for this reimbursement, the subject recalled part(s) must be written-up and routed through the normal labor claim procedure including appropriate receipts.

No recalled fuel pumps currently in your inventory may be sold as it is a violation of federal law for a dealer to sell a recalled item of motor vehicle equipment.

5. Owner complaint process

The owner of a vehicle with a recalled fuel pump may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-429-9153), or go to <http://www.safercar.gov>, if the owner believes that Federal-Mogul has failed or is unable to remedy without charge the condition outlined above within a reasonable time.

Please review the above information and contact your sales representative or call 1-877-489-6659 with any questions. Although this recall will be continuing, please process returns of product currently in your inventory by November 30, 2007.

Our commitment to product quality is at the forefront of all we do at Federal-Mogul. We apologize for any inconvenience this voluntary recall may cause. We know, however, that you share our concern for vehicle safety. We appreciate your continuing assistance in this matter.

Sincerely,

Raymond King  
Marketing Director  
Global Engine Products



Enclosure

# Mechanical Fuel Pump Recall October 2007

## RGA Request Form

To assure timely processing, please follow these steps:

- **FM Sales Representatives:** Use this form to request an RGA# for the return of the recalled mechanical fuel pumps.
- Fax this request form to our FM Customer Service Department @ 314-977-0963
- Questions: Call 1-877-489-6659.

*RGA (return goods authorization) will be faxed back to the number provided*

**RGA Fax Back Number** \_\_\_\_\_

**Sold-to Name:** \_\_\_\_\_

**Ship-to Name:**

**Address** \_\_\_\_\_

**Address**

**City/State/Zip** \_\_\_\_\_

**City/State/Zip**

**FM Account No.:** \_\_\_\_\_

**Phone Number**

**Contact Name**

**Customer Reference Number:** \_\_\_\_\_

## Mechanical Fuel Pump Recalled Part Numbers Claim # 07E064

Part Number	Return Qty	Packaging Date Codes Affected	Part Number	Return Qty	Packaging Date Codes Affected
2M60205		06213 -07212	M60253		06213 -07212
2M60318		06213 -07212	M60265		06213 -07212
2M60331		06213 -07212	M60277		06213 -07212
2M60415		06213 -07212	M60318		06213 -07212
2M60578		06213 -07212	M60331		06213 -07212
2M6748		06213 -07212	M60415		06213 -07212
2M6807		06213 -07212	M60578		06213 -07212
2M6962		06213 -07212	M6445		06213 -07212
2M70214		06213 -07212	M6748		06213 -07212
M60002		06213 -07212	M6753		06213 -07212
M60029		06213 -07212	M6807		06213 -07212
M60045		06213 -07212	M6865		06213 -07212
M60048		06213 -07212	M6962		06213 -07212
M60049		06213 -07212	M6981		06213 -07212
M60081		06213 -07212	M70045		06213 -07212
M60123		06213 -07212	M70111		06213 -07212
M60167		06213 -07212	M70194		06213 -07212
M60205		06213 -07212	M70214		06213 -07212



Claim # 09E-021

May 12, 2009

Dear Valued Customer

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Federal-Mogul has determined that a defect which relates to motor vehicle safety exists in certain mechanical, replacement fuel pumps. Therefore, Federal-Mogul is recalling these specific mechanical fuel pumps manufactured by our supplier.

1. Identification of equipment affected:

Federal-Mogul packaged and sold the recalled fuel pumps between August 2008 and March 2009 under the following brand names: Carter, Accu-Flow, Tru-Flow and NAPA. These mechanical fuel pumps are limited to two base part numbers. The specific part numbers being recalled, affected packaging date codes and vehicle application information are listed in the attachment to this letter.

2. Description of possible malfunction and safety evaluation:

The fuel pump diaphragm in certain production runs may have been improperly manufactured. Improperly manufactured pump diaphragm rods could cause excessive fuel pressure. With excessive fuel pressure, carburetors could flood and create a vehicle fire hazard.

3. Vehicle owner precautions:

The subject fuel pumps were manufactured for aftermarket use. Owners of these pumps should have them removed and replaced as soon as possible.

4. Owner remedy measures:

Federal-Mogul wishes to recover as many of these parts as possible. Therefore, we respectfully request that you quarantine the subject part numbers containing the affected date codes (per attachment). Date codes are located on the part number label in the lower left corner. Recalled fuel pumps from your customers also should be returned to Federal-Mogul. For reference, we have included a complete record of this recalled part number and our sales records which reflect the parts sales to you.

Once product is quarantined, please notify your local Federal-Mogul sales representative to come in to verify the product return and handle the RGA process. The subject defective part(s) must be written-up by a Federal-Mogul sales representative.

The return of the part(s) will be at no cost to you. Upon return of this part(s), your account will be credited for the part(s). For replacement of recalled product, you will need to order the appropriate stock number from Federal-Mogul customer service.

Parts stores that purchased these items should return them to their servicing warehouse distributor for credit.

If the part is suspected of having been installed on a vehicle, Federal-Mogul will pay for inspection and, if the part is covered by the recall, replacement, as well as shipping charges. In order to qualify for this reimbursement, the subject recalled part(s) must be written-up and routed through the normal labor claim procedure including appropriate receipts.

No recalled fuel pumps currently in your inventory may be sold as it is a violation of federal law for a dealer to sell a recalled item of motor vehicle equipment.

5. Owner complaint process

The owner of a vehicle with a recalled fuel pump may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-429-9153), or go to <http://www.safercar.gov>, if the owner believes that Federal-Mogul has failed or is unable to remedy without charge the condition outlined above within a reasonable time.

Please review the above information and contact your sales representative or call 1-877-489-6659 with any questions. Although this recall will be continuing, please process returns of product currently in your inventory by June 15, 2009.

Our commitment to product quality is at the forefront of all we do at Federal-Mogul. We apologize for any inconvenience this voluntary recall may cause. We know, however, that you share our concern for vehicle safety. We appreciate your continuing assistance in this matter.

Sincerely,



Raymond King  
Director, Marketing, Global Aftermarket Underhood Products  
Federal-Mogul

Enclosure