



CL-10673117-2228



Oak Harbor, WA



INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C . 552(B)(6)

January 7, 2015

U.S. Department of Transportation  
National Highway Traffic Safety Administration  
Office of Defects Investigation (NVS- 210)  
1200 New Jersey Avenue SE  
Washington, DC 20590

JAN 13 2015

Re: Incident Report


Dear Sir/Madam:

Yesterday while driving our 2013 Toyota Sienna (VIN number 5TDZK3DC3DS [redacted] 15,200 miles on the odometer) there was an occurrence, wherein the accelerator momentarily stuck in the open position. After starting the car and driving 3 miles, the throttle did not release when I removed my foot from the accelerator pedal and pressed on the brake. Aside from the momentary scare, there was no damage and I was able to stop in time. I was not using the cruise control at the time. There was nothing holding down the accelerator pedal and the floor mat was secured in its proper position.

This is our company vehicle. I will be contacting the nearby Toyota dealer soon to have the problem investigated.

Please don't hesitate to contact me if you require additional information related to this matter.

Sincerely,




cc. Toyota Motor Sales, U.S.A., Inc.  
Foothills Toyota Scion, 1881 Bouslog Road, Burlington, WA 98233

ET  
11315  
SMD



Oak Harbor, WA



January 7, 2015

**96 COPY**

Toyota Motor Sales, U.S.A., Inc.  
19001 South Western Avenue  
Dept. WC11  
Torrance, CA 90501

Re: Incident Report


Dear Sir/Madam:

Yesterday while driving our 2013 Toyota Sienna (VIN number 5TDZK3DC3DS [REDACTED] 15,200 miles on the odometer) there was an occurrence, wherein the accelerator momentarily stuck in the open position. After starting the car and driving 3 miles, the throttle did not release when I removed my foot from the accelerator pedal and pressed on the brake. Aside from the momentary scare, there was no damage and I was able to stop in time. I was not using the cruise control at the time. There was nothing holding down the accelerator pedal and the floor mat was secured in its proper position.

This is our company vehicle. I will be contacting the nearby Toyota dealer soon to have the problem investigated.

Please don't hesitate to contact me if you require additional information related to this matter.


Sincerely,




cc. Foothills Toyota Scion, 1881 Bouslog Road, Burlington, WA 98233  
✓ U.S. Department of Transportation, National Highway Traffic Safety Administration

[Redacted]  
Oak Harbor, WA

**CERTIFIED MAIL**



7014 1820 0002 0615 0139



U.S. POSTAGE  
PAID  
OAK HARBOR, WA  
98277  
JAN 07, 15  
AMOUNT  
**\$6.49**  
00023067-08

U.S. Department of Transportation  
National Highway Traffic Safety Administration  
Office of Defects Investigation (NVS-210)  
1200 New Jersey Avenue SE  
Washington, DC 20590

W48-226

RETURN RECEIPT  
REQUESTED

20590

