

CL-10689361-7182

1-28-15

NHTSA  
1200 New Jersey Ave SE  
West Building  
Washington DC 20590

INFORMATION Redacted PURSUANT TO THE FREEDOM OF  
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

FEB 12 2015

Dear NHTSA,

I recently purchased my first Subaru a 2015 Outback Limited (VIN 4S4BSBJC3F3 [REDACTED]) and I have a concern with the car which I believe to be safety related.

Recently while driving in a snow storm I noticed that the heat from the tail lights (which were on) is not sufficient enough to keep snow from accumulating on the tail lamp. This obviously makes it harder for cars in back to see the tail lamp. This would be even more of a concern at night. I am of the position that something should be done to correct this as it is unsafe to drive in the snow, especially at night.

Sincerely

[REDACTED]

Traverse City, MI [REDACTED]

ET  
2/18/15  
SMD

Traverse City, MI

TRAVERSE CITY MI 49783

23 JAN 2015 PM 1 1



N. H. T. S. A.  
1200 New Jersey Ave SE  
West Building  
Washington DC 20580

