

NVS-200
CL-10806937-6275

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

[REDACTED]
Lyndhurst, OH [REDACTED]
October 22, 2015

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
1200 NEW JERSEY AVE. S.E.
WASHINGTON, DC 20590

OCT 29 2015

Dear Sir:

My Dodge Journey VIN# 3D4PG4FB1BT [REDACTED] wiring harness shorted out internally, and caused my cruise control switch to short out. I feel that it is a serious safety problem. Other Dodge products with steering wheel wiring harness problems have been addressed. I contacted FCA about this matter, and felt that their response was inadequate.

I would like to submit a formal complaint to the National Highway Traffic Safety Administration.

Sincerely


[REDACTED]

NAM
11415
SMD

Cleveland, OH

CLEVELAND OH 440

23 OCT 2015 PM 2 L



NATIONAL HIGHWAY TRAFFIC SAFETY
ADMINISTRATION
1200 NEW JERSEY AVE. S.E.
WASHINGTON, DC 20590

20590

