

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C . 552(B)(6)

CL-10864049-2825

US Dept TRAN
NHTSA ODI [NVS-210]
2100 n Jersey north Ave west bldg
Washington, DC 20590

OCT - 3 2013

In May I wrote that I believed that the deterioration of the visual presentation of the speedometer in my 2007 Prius is a safety hazard. Toyota recognizes that there is a problem but they will not correct it unless it has failed completely. My visual presentation in usable at night but is not when driving during daylight [with the control turned to maximum]. 10864049.


I believe that if I had a schematic I [even Toyota] could design a means to increase the voltage and correct the problem.

Has anything happened?

My assigned tracking number is 10864049.


[REDACTED]
Sunnyvale CA [REDACTED]

NM
107160
SMD



SAN FRANCISCO CA 9410

27 SEP 2016 PM 2 L



US Dept TRAN
NHTSA ODI [NVS-210]
2100 n Jersey north Ave west bldg
Washington, DC 20590

20590-

