

INFORMATION Redacted PURSUANT TO THE FREEDOM OF



U.S. Department of Transportation

National Highway Traffic Safety Administration

INFORMATION ACT (FOIA) 5 U.S.C. 552(B)(6) FOR AGENCY USE ONLY 100148

Vehicle Owner's Questionnaire
 To Report Vehicle Safety Defects
 1-888-DASH-2-DOT
 (1-888-327-4236)
 INTERNET: www.nhtsa.dot.gov/hotline

| | |
|---------------|-------------------------------------|
| Date Received | Repository <input type="checkbox"/> |
| 04-OCT-2016 | Reference No. 10913638 |
| JAN - 6 2017 | |

OWNER INFORMATION (Type or Print)

| | | | | | |
|-------------|------------|------------|--|--------------------------|----------------|
| Name | [REDACTED] | | | Daytime Telephone Number | E-mail Address |
| Address | [REDACTED] | | | [REDACTED] | |
| City | State | Zip Code | | Evening Telephone Number | |
| SAN GABRIEL | CA | [REDACTED] | | | |

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

| | | | | |
|---|---|----------------|--------------------------|---------------------------------|
| 17 digit Vehicle Identification Number Located at bottom of windshield on driver's side JYARP09Y75A [REDACTED] | | Make YAMAHA | Model FJR1300 | Model Year 2005 |
| Date Purchased | Dealer's Name and Telephone Number N/A | | Engine: No: Cylinders | Fuel Type: |
| Original Owner <input type="checkbox"/> | Dealer's City | State | Zip Code | |
| Transmission Type | <input type="checkbox"/> Anti-lock Brakes | Powertrain | Multiple Failure: | Incident Date(s) 01-SEP-2016 |
| | <input type="checkbox"/> Cruise Control | | | |

FAILED COMPONENT(S)/PART(S) INFORMATION

| | | |
|---|--------------------------|---------------------|
| Vehicle Component Codes: 110000 ELECTRICAL SYSTEM, 116100 ELECTRICAL SYSTEM: IGNITION: SWITCH | Failure Mileage 36500 | Failure Speed 20 |
|---|--------------------------|---------------------|

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

| | | |
|---------------------------------|--|---------------------------------|
| Tire Make | Tire Model (Name or Number) | Tire Size (Example: P215/65R15) |
| DOT No. (Example: DOTM19ABC036) | <input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair | Failure Location: |
| Tire Component Code | Tire Failure Type: | |

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

| | | |
|----------------------------|----------------------|-----------------|
| Make: | Date Manufactured: | Model No./Name: |
| Seat Type: | Installation System: | |
| Child Seat Component Code: | Failed Part: | |

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

| | | | | |
|--|---|--------------------------------|-----------------------|-------------------------|
| Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Number of Persons Injured 0 | Number of Deaths 0 | Reported to Police N |
|--|---|--------------------------------|-----------------------|-------------------------|

Narrative Description of Incident(S), Crash(es), and Injury(ies).

Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

TL* THE CONTACT OWNS A 2005 YAMAHA FJR1300A. WHILE DRIVING APPROXIMATELY 20 MPH, THE VEHICLE SUDDENLY STALLED AND FAILED TO RESTART. UPON INSPECTION, THE CONTACT DETERMINED THAT THE FAILURE WAS CAUSED BY A FAILED SOLDER CONNECTING WIRE FOR THE IGNITION SWITCH. THE VEHICLE WAS REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 36,500.

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY.

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.