


INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

 DOT Auto Safety Hotline Vehicle Owner's Questionnaire To Report Vehicle Safety Defects 1-888-DASH-2-DOT (1-888-327-4236) INTERNET: www.nhtsa.dot.gov/hotline			FOR AGENCY USE ONLY 100148 Date Received 13-MAR-2017 MAY 16 2017			Repository <input type="checkbox"/> Reference No. 10965763			
OWNER INFORMATION (Type or Print)									
Name			Daytime Telephone Number			E-mail Address			
Address			Evening Telephone Number						
City		State		Zip Code					
ALVARADO		TX							
<i>The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).</i>									
VEHICLE INFORMATION									
17 Vehicle Identification Number			Registered at bottom or windshield driver's side			IS TVN		Model	Model Year
4S3BG6852W7			SUBARU			LEGACY		1998	
Date Purchased		Dealer's Name and Telephone Number				Engine:		Fuel Type:	
12/2016		BRAD DERRY Honda 319) 754-6000				No: Cylinders 4			
Original Owner <input type="checkbox"/>		Dealer's City		State	Zip Code				
		West Burlington		Iowa	52655				
Transmission Type		<input type="checkbox"/> Antilock Brakes		Powertrain		Multiple Failure:		Incident Date(s)	
Automatic		<input type="checkbox"/> Cruise Control				<input checked="" type="checkbox"/> AUTO TRANSMISSION <input checked="" type="checkbox"/> SENSOR ALSO WENT OUT		02-JAN-2017	
FAILED COMPONENT(S)/PART(S) INFORMATION									
Vehicle Component Code: 100000 POWER TRAIN							Failure Mileage		Failure Speed
							155025		
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE									
Tire Make			Tire Model (Name or Number)			Tire Size (Example P215/65R15)			
DOT No. (Example: DOTM19ABC036)			<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair		Failure Location:				
Tire Component Code						Tire Failure Type:			
ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE									
Make:			Date Manufactured:			Model No./Name:			
Seat Type:			Installation System:						
Child Seat Component Code:			Failed Part:						
APPLICABLE INCIDENT INFORMATION (Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)									
Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Fire <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Number of Persons Injured		Number of Deaths		Reported to Police N	
Narrative Description of Incident(S), Crash(es), and Injury(ies). Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).									
TL* THE CONTACT OWNS A 1998 SUBARU LEGACY. WHILE ATTEMPTING TO DRIVE, THE TRANSMISSION BEGAN TO SMOKE AND THEN UNEXPECTEDLY FAILED. THERE WERE NO WARNING INDICATORS ILLUMINATED. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 155,025.									
✓ Vehicle Sold to me by salesman - Cody FLICKNER Vehicle purchased AS IS - NO WARRANTY.									
Include, if available: Police/Fire Department Report, Photos, and Repair Invoice.					ATTACH ADDITIONAL SHEETS IF NECESSARY				
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.									

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

December 2017 - AFTER Delivery - Found Radio Antenna not there,
And Radio won't work.

4th Day of Ownership - Automatic Transmission blew up - \$871.00 New Trans
- \$697.00 Labor

End of January 2017 - Wire broke, would not start - \$179.00

Jan / February - 2017 - Check Engine came on AFTER I picked up Vehicle at
Trans-shop. Took vehicle to another mech. - \$287.00


MARCH 2017 - Windshield Wiper Blade replaced and need a front wiper pump
\$181.00

ATTACH ADDITIONAL PAGES IF NECESSARY

U.S. Department of Transportation
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382
Official Business
Penalty for Private Use \$300



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES



BUSINESS REPLY MAIL
FIRST CLASS MAIL PERMIT NO. 1888 WASHINGTON, DC

POSTAGE WILL BE PAID BY ADDRESSEE



**US Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NEF-100**
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382



Help stop the Dog & Cat Meat Trade.

