

11 August 2017

[Redacted]
East Alton, IL [Redacted]
[Redacted]

AUG 17 2017

NHTSA
1200 New Jersey Avenue
SE, Building Washington DC 20590

NHTSA,

References:

- a. Complaint No. 11006081, Ford Mustang 20007, sub: Takata Recall
- b. Complaint No. 11006075, Ford Fusion 20008, sub: Takata Recall

Per reference a. – “It has been over a year since this family was notified of this open recall safety issue – we thank your office for the notice. What plan of action does your office recommend? How unsafe does your office believe this vehicle is to drive with other family members as passengers”? Does your office have any plans to recommend too Ford Mo Co to provide replacement transportation to those families that have driven these unsafe vehicles for over a year waiting for the open safety issues to be fixed?

Per reference b. – “Over a year the issue is still unresolved. What does your office recommend? How unsafe does your office believe the vehicle is to drive? How long did your office allow Ford to fix the safety issue? Also, I received the 15S21 Recall (driver side air bag) on the families Ford Mustang 2007; however, a 15S21 Recall was never received on the 2008 Fusion (driver side air bag) why? Does your office have any plans to recommend too Ford Mo Co to provide replacement transportation to those families that have driven these unsafe vehicles for over a year waiting for the open safety issues to be fixed?

Request your office respond to these long open questions and issues in writing via email,

[Redacted] and mailing address, [Redacted] East Alton, IL [Redacted]

[Redacted] 25 August 2017.

[Redacted]



E. Altom, LLC




7006 0810 0000 9531 9485



WHI-306

NHTSA

1200 New Jersey Ave
SE, Building Washington, DC



00590