

OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

From: [REDACTED]
To: [EVOQ \(NHTSA\)](#)
Subject: Re: Follow up to ODI Complaint ----- 11337763-----
Date: Sunday, August 2, 2020 7:57:14 PM
Attachments: [REDACTED]

CAUTION: This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

I am unable to respond.

On Tuesday, July 28, 2020, 03:43:46 PM PDT, EVOQ (NHTSA) <evoq@dot.gov> wrote:

Please see the attached copy of your recent complaint and instructions. Please make any necessary edits and return via email to dataquality@dot.gov or fax to (202) 366-1767. Due to the volume of complaints we receive and our limited resources, we cannot respond to every complaint.
NHTSA/Office of Defects Investigation



U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received	Repository <input type="checkbox"/>
06-JUL-2020	Reference No. 11337763

OWNER INFORMATION (Type or Print)

Name	Daytime Telephone Number	E-mail Address
Address	Evening Telephone Number	
City LAS VEGAS	State NV	Zip Code

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 4X4FCAM23LC	Make FOREST RIVER	Model CARDINAL	Model Year 2020
Date Purchased	Dealer's Name and Telephone Number	Engine: No: Cylinders	Fuel Type:
Original Owner <input type="checkbox"/>	Dealer's City	State	Zip Code
Transmission Type	<input type="checkbox"/> Antilock Brakes <input type="checkbox"/> Cruise Control	Powertrain	Multiple Failure: 4
			Incident Date(s) 22-JUN-2020

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 162000 STRUCTURE: BODY	Failure Mileage 200	Failure Speed
------------------------------------------------	------------------------	---------------

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTMAL9ABC036)	<input type="checkbox"/> Original Equipment <input type="checkbox"/> Prior Repair	Failure Location:
Tire Component Code	Tire Failure Type:	

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured	Number of Deaths	Reported to Police N
------------------------------------------------------------------------------	-----------------------------------------------------------------------------	---------------------------	------------------	-------------------------

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e., parts repaired or replaced (and if old part is available).

TL* THE CONTACT OWNS A 2020 FOREST RIVER CARDINAL. THE CONTACT STATED THAT THE LEFT AND RIGHT ANCHOR LEGS ATTACHED TO THE FRONT END OF THE RV INDEPENDENTLY LOWERED WHILE DRIVING AT HIGH RATES OF SPEEDS WITHOUT WARNING. THE MANUFACTURER HAD BEEN NOTIFIED OF THE FAILURE AND INFORMED THE CONTACT THAT THE FAILURE WAS A DEALER ISSUE. THE CONTACT HAD TAKEN THE VEHICLE TO FINDLAY RV (4530 BOULDER HWY, LAS VEGAS, NV 89121) WHERE THEY HAD THE VEHICLE SERVICED ON THREE SEPARATE OCCASIONS, HOWEVER, THE FAILURE PERSISTED AFTER EACH VISIT. THE VEHICLE HAD YET TO BE REPAIRED. THE FAILURE MILEAGE WAS 200.
VIN PASSED ## 2020 FOREST RIVER CARDINAL ##*DT*JB*DT*JB

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.