

From: [Ambrose, Ann-Marie L](#)
To: [EVOO \(NHTSA\)](#); [Robertson, Faithia \(NHTSA\)](#); [Lewis, Brenton](#)
Cc: [NHTSA ODI CED](#); [Strasser-King, Marion C](#)
Subject: FW: Ref# 11471403
Date: Wednesday, December 6, 2023 11:30:16 AM

CAUTION: This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

From: [REDACTED]
Sent: Monday, December 4, 2023 1:46 PM
To: nhtsa.webmaster@dot.gov
Subject: Ref# 11471403

[External Email]

CAUTION: This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

Hello, my name is [REDACTED]
These files are proof that I paid out of my pocket for new ford transmission . And 6 Mos. Later the transmission had to be replaced and RAYONS dealership mess around for month and a half then they couldn't tell my extended warranty did not reimburse me. And Ford wanted to investigate the problem after telling me that the same problem.
I am asking for my out of pocket expense. To be refunded to me.

THANKS YOU
[REDACTED]

The preceding message (including attachments) is covered by the Electronic Communication Privacy Act, 18 U.S.C. sections 2510-2512, is intended only for the person or entity to which it is addressed, and may contain information that is confidential, protected by attorney-client or other privilege, or otherwise protected from disclosure by law. If you are not the intended recipient, you are hereby notified that any retention, dissemination, distribution, or copying of this communication is strictly prohibited. Please reply to the sender that you have received the message in error and destroy the original message and all copies.



Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121-1904



SAN ANTONIO, TX

Ref # 11471403

November 2022

***** IMPORTANT SAFETY RECALL *****

Safety Recall Notice 22S43 / NHTSA Recall 22V413

2015 Escape

Your Vehicle Identification Number (VIN): 1FMCU0G76FU

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue?

On your vehicle, it may be possible the transmission shifter cable bushing is damaged or missing.

What is the risk?

A damaged or missing bushing could prevent the shifter from moving the transmission into the intended gear position and cause the vehicle to move in an unexpected direction. The transmission may not be in the park position, even though the shifter position indicates that the vehicle was shifted to park. Exiting a vehicle without the transmission in the park position and without the application of the parking brake may allow the vehicle to roll, increasing the risk of injury or crash.

What will Ford and your dealer do?

Parts are now available to repair your vehicle. Ford Motor Company has authorized your dealer to replace the transmission shifter cable bushing and protective cap free of charge (parts and labor).

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What should you do?

Please call your dealer without delay and request a service date for Recall 22S43. Provide the dealer with your VIN, which is printed near your name at the beginning of this letter.

Ford has not issued instructions to stop driving your vehicle under this safety recall. You should contact your dealer for an appointment to have your vehicle remedied as soon as practicable. Until the vehicle is repaired, when shifting the vehicle into park, check the instrument cluster to see if it indicates the vehicle is in park position, and always apply the parking brake before the shifter is shifted into park.

If you do not already have a servicing dealer, you can access ford.com/support for dealer addresses, maps, and driving instructions.

Ford Motor Company wants you to



3796 NE I-10 Frontage Road
Sealy, Texas 77474
(979) 885-7700

Reg # 11471403

CELL: [REDACTED]

CUSTO [REDACTED]		ADVISOR KEVIN		TAG NO. 8485		INVOICE DATE 11/30/22		STOCK NO. [REDACTED]	
SAN ANTONIO, TX		LABOR RATE		LICENSE NO.		MILEAGE 173,102		COLOR INGOT SILV	
		YEAR / MAKE / MODEL 15/FORD TRUCK/ESCAPE/4DR SE FWD				DELIVERY DATE 11/22/14		DELIVERY MILES 9	
		VEHICLE I.D. NO. 1 F M C U O G 7 6 F U				SELLING DEALER NO. 100		PRODUCTION DATE	
		F.T.E. NO.				R.O. DATE 11/22/22			
JOB# 7 TOTALS		COMMENTS							

TOTALS-----
LABOR 119.95
JOB# 7 JOURNAL PREFIX FOCS JOB# 7 TOTAL 119.95

* [] CASH [] CHECK CK NO. [] *
* [] VISA [] MASTERCARD [] DISCOVER *
* [] AMER XPRESS [] OTHER [] CHARGE *

*****THANK YOU FOR YOUR SERVICE BUSINESS!!!*****

TOTAL LABOR..... 908.85
TOTAL PARTS..... 736.71
TOTAL SUBLET... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 0.00
TOTAL MISC DISC 0.00
TOTAL TAX..... 60.78

TOTAL INVOICE \$ 1706.34

DISCLAIMER OF WARRANTIES

Any warranties on the products sold hereby are made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

CUSTOMER SIGNATURE

DUPLICATE INVOICE *****



3796 NE I-10 Frontage Road
Sealy, Texas 77474
(979) 885-7700

Reference # 11471403

CELL: [REDACTED]

CUSTOMER NO.	ADVISOR GENERAL ADVISOR	8215	TAG NO.	INVOICE DATE 07/14/22	INVOICE NO.
[REDACTED]	LABOR RATE	LICENSE NO.	MILEAGE 155,958	COLOR INGOT SILV	STOCK NO.
[REDACTED]	YEAR / MAKE / MODEL 15/FORD TRUCK/ESCAPE/4DR SE FWD	DELIVERY DATE 11/22/14	DELIVERY MILES 9	SELLING DEALER NO. 100	PRODUCTION DATE
SAN ANTONIO, TX	VEHICLE I.D. NO. 1 F M C U O G 7 6 F U	P.O. NO.	R.O. DATE 06/14/22		
[REDACTED]	F.T.E. NO.	COMMENTS			
[REDACTED]	BUSINESS PHONE				

MO: [REDACTED]

JOB# 1 CHARGES-----

LABOR-----

J# 1 21FOZ DRIVETRAIN TECH(S):5243 8546 2538.20
C/S DOESN'T WANT TO ACCELERATE WHEN IT FINALLY TAKES OFF IT
SHIFTS EXTREMELY HARD
ROAD TEST ,VERIFIED CONCERN TRANSMISSION SLIPPING. TEST FOR
CODES P0766 P2703 MP2704 P0219. PERFORM PINPOINT TESTS TECH
5243
CODES RETURNED NEEDS TRANSMISSION, INTERNAL DAMAGE.
REMOVED OLD TRANSMISSION FOLLOWING WSM, ALSO REPLACED
TRANSMISSION COOLER AND FLUSHED OUT LINES, INSTALLED NEW
TRANSMISSION ALONG WITH AXLE SEALS DOWNLOADED STRATEGY
TOPPED OF WITH TRANSMISSION FLUID TEST DROVE VEHICLE DROVE
FINE AND LEAKS PRESENT AT THIS TIME.

DISCLAIMER OF WARRANTIES

Any warranties on the products sold hereby are made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-----	
	1	EV6Z-7000-ERM	AUTOMAT	4843.96	4843.96
	-1	EV6Z-7000-ERM	CORE RETURN	1000.00	-1000.00
	4	-W715618-S437	NUT	0.64	2.56
	2	-W520102-S442	NUT - L	0.55	1.10
	2	CCPZ-3B477-G	RETAIN	3.11	6.22
	1	CV6Z-7A095-A	OIL COO	101.20	101.20
	1	CV6Z-7A095-B	OIL COO	188.84	188.84
	1	DC9Z-7H322-A	VALVE A	27.80	27.80
	2	VC-13-G	ANTI-FR	22.92	45.84
	2	XT-10-QLVC	OIL - A	10.57	21.14
	1	BV6Z-3A130-E	ROD - T	68.39	68.39
TOTAL - PARTS					4307.05

JOB# 1 TOTALS-----

LABOR 2538.20
PARTS 4307.05

JOB# 2 CHARGES-----

JOB# 1 JOURNAL PREFIX FOCS JOB# 1 TOTAL 6845.25

LABOR-----

J# 2 01FOZ00099P COURTESY INSPECTION TECH(S):7822 0.00
Perform a thorough inspection of your vehicle and provide a
detailed Vehicle Report Card. Check Fluid Levels, Inspect
Wiper Blades, Test Battery, Inspect Tires and Brake Wear,
Inspect safety systems and components for leaks and damage.
Multi point inspection not performed at this visit.

JOB# 2 TOTALS-----

JOB# 3 CHARGES-----

JOB# 2 JOURNAL PREFIX FOCS JOB# 2 TOTAL 0.00

LABOR-----

J# 3+45FOZ007 TOWING TECH(S):7254 0.00
C/R TOW TO RYAN FORD

VEHICLE TOWED INTO RYAN 6/14/21



3796 NE I-10 Frontage Road
Sealy, Texas 77474
(979) 885-7700

Ref # 11471403

CELL

CUSTOMER NO.	ADVISOR	8215	TAG NO.	INVOICE DATE	INVOICE NO.
	GENERAL ADVISOR			07/14/22	
	LABOR RATE	LICENSE NO.	MILEAGE	COLOR	STOCK NO.
			155,958	INGOT SILV	
	YEAR / MAKE / MODEL			DELIVERY DATE	DELIVERY MILES
	15/FORD TRUCK/ESCAPE/4DR SE FWD			11/22/14	
SAN ANTONIO, TX	VEHICLE I.D. NO.			SELLING DEALER NO.	PRODUCTION DATE
	1 F M C U O G 7 6 F U			100	
	F.T.E. NO.	P.O. NO.		R.O. DATE	
				06/14/22	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS			MO:

SUBLET-----	PO#-----	VEND	INV#	INV. DATE	DESCRIPTION-----		
		1714		06/14/22	TOWBILL		275.00
TOTAL - SUBLET							275.00

JOB# 3 TOTALS-----						SUBLET	275.00

JOB# 3 JOURNAL PREFIX FOCs						JOB# 3 TOTAL	275.00

MISC-----	CODE-----	DESCRIPTION-----				CONTROL NO-----	
JOB # A	Z4	DOCUMENTATION FEE					2.19
JOB # A	Z3	ADMINISTRATION FEES					2.25
JOB # A	Z2	ENVIRONMENTAL FEE					18.98
JOB # A	Z1	OTHER SHOP SUPPLIES					29.68
TOTAL - MISC							53.10

TOTALS-----							

* [] CASH [] CHECK CK NO. []							
* [] VISA [] MASTERCARD [] DISCOVER							
* [] AMER XPRESS [] OTHER [] CHARGE							

TOTAL LABOR....							2538.20
TOTAL PARTS....							4307.05
TOTAL SUBLET...							275.00
TOTAL G.O.G....							0.00
TOTAL MISC CHG.							53.10
TOTAL MISC DISC							0.00
TOTAL TAX.....							378.02
TOTAL INVOICE \$							7551.37

DISCLAIMER OF WARRANTY
Any warranties on the products sold hereby are made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume any liability in connection with the sale of said products.

*****THANK YOU FOR YOUR SERVICE BUSINESS!!!*****

CUSTOMER SIGNATURE
***** DUPLICATE INVOICE *****



3796 NE I-10 Frontage Road
Sealy, Texas 77474
(979) 885-7700

Reference # 11471403

CELL: [REDACTED]

CUSTOMER NO.	ADVISOR GENERAL ADVISOR	8215	TAG NO.	INVOICE DATE 07/14/22	INVOICE NO.
[REDACTED]	LABOR RATE	LICENSE NO.	MILEAGE 155,958	COLOR INGOT SILV	STOCK NO.
[REDACTED]	YEAR / MAKE / MODEL 15/FORD TRUCK/ESCAPE/4DR SE FWD	DELIVERY DATE 11/22/14	DELIVERY MILES 9	PRODUCTION DATE	
SAN ANTONIO, TX	VEHICLE I.D. NO. 1 F M C U O G 7 6 F U	SELLING DEALER NO. 100			
[REDACTED]	F.T.E. NO.	P.O. NO.	R.O. DATE 06/14/22		
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS			

MO: [REDACTED]

JOB# 1 CHARGES-----

LABOR-----

J# 1 21FOZ

DRIVETRAIN

TECH(S):5243 8546

2538.20

C/S DOESN'T WANT TO ACCELERATE WHEN IT FINALLY TAKES OFF IT
SHIFTS EXTREMELY HARD
ROAD TEST ,VERIFIED CONCERN TRANSMISSION SLIPPING. TEST FOR
CODES P0766 P2703 MP2704 P0219. PERFORM PINPOINT TESTS TECH
5243
CODES RETURNED NEEDS TRANSMISSION, INTERNAL DAMAGE.
REMOVED OLD TRANSMISSION FOLLOWING WSM, ALSO REPLACED
TRANSMISSION COOLER AND FLUSHED OUT LINES, INSTALLED NEW
TRANSMISSION ALONG WITH AXLE SEALS DOWNLOADED STRATEGY
TOPPED OF WITH TRANSMISSION FLUID TEST DROVE VEHICLE DROVE
FINE AND LEAKS PRESENT AT THIS TIME.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-----	
	1	EV6Z-7000-ERM	AUTOMAT	4843.96	4843.96
	-1	EV6Z-7000-ERM	CORE RETURN	1000.00	-1000.00
	4	-W715618-S437	NUT	0.64	2.56
	2	-W520102-S442	NUT - L	0.55	1.10
	2	CCPZ-3B477-G	RETAIN	3.11	6.22
	1	CV6Z-7A095-A	OIL COO	101.20	101.20
	1	CV6Z-7A095-B	OIL COO	188.84	188.84
	1	DC9Z-7H322-A	VALVE A	27.80	27.80
	2	VC-13-G	ANTI-FR	22.92	45.84
	2	XT-10-QLVC	OIL - A	10.57	21.14
	1	BV6Z-3A130-E	ROD - T	68.39	68.39
TOTAL - PARTS					4307.05

JOB# 1 TOTALS-----

LABOR 2538.20
PARTS 4307.05

JOB# 2 CHARGES-----

JOB# 1 JOURNAL PREFIX FOCS JOB# 1 TOTAL 6845.25

LABOR-----

J# 2 01FOZ00099P

COURTESY INSPECTION

TECH(S):7822

0.00

Perform a thorough inspection of your vehicle and provide a
detailed Vehicle Report Card. Check Fluid Levels, Inspect
Wiper Blades, Test Battery, Inspect Tires and Brake Wear,
Inspect safety systems and components for leaks and damage.
Multi point inspection not performed at this visit.

JOB# 2 TOTALS-----

JOB# 3 CHARGES-----

JOB# 2 JOURNAL PREFIX FOCS JOB# 2 TOTAL 0.00

LABOR-----

J# 3+45FOZ007

TOWING

TECH(S):7254

0.00

C/R TOW TO RYAN FORD

VEHICLE TOWED INTO RYAN 6/14/21



Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121-1904



SAN ANTONIO, TX

Ref # 11471403

November 2022

***** IMPORTANT SAFETY RECALL *****

Safety Recall Notice 22S43 / NHTSA Recall 22V413

2015 Escape

Your Vehicle Identification Number (VIN): 1FMCU0G76FU

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue?

On your vehicle, it may be possible the transmission shifter cable bushing is damaged or missing.

What is the risk?

A damaged or missing bushing could prevent the shifter from moving the transmission into the intended gear position and cause the vehicle to move in an unexpected direction. The transmission may not be in the park position, even though the shifter position indicates that the vehicle was shifted to park. Exiting a vehicle without the transmission in the park position and without the application of the parking brake may allow the vehicle to roll, increasing the risk of injury or crash.

What will Ford and your dealer do?

Parts are now available to repair your vehicle. Ford Motor Company has authorized your dealer to replace the transmission shifter cable bushing and protective cap free of charge (parts and labor).

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What should you do?

Please call your dealer without delay and request a service date for Recall 22S43. Provide the dealer with your VIN, which is printed near your name at the beginning of this letter.

Ford has not issued instructions to stop driving your vehicle under this safety recall. You should contact your dealer for an appointment to have your vehicle remedied as soon as practicable. Until the vehicle is repaired, when shifting the vehicle into park, check the instrument cluster to see if it indicates the vehicle is in park position, and always apply the parking brake before the shifter is shifted into park.

If you do not already have a servicing dealer, you can access ford.com/support for dealer addresses, maps, and driving instructions. Ford Motor Company wants



3796 NE I-10 Frontage Road
Sealy, Texas 77474
(979) 885-7700

Ref # 17471403

CUSTOMER	ADVISOR KEVIN	8485	TAG NO 060	INVOICE DATE 11/30/22	CELL:
LABOR RATE	LICENSE NO	MILEAGE	COLOR 173,102	STOCK NO	
YEAR / MAKE / MODEL 15/FORD TRUCK/ESCAPE/4DR SE FWD	VEHICLE I.D. NO. 1 F M C U O G 7 6 F U	DELIVERY DATE 11/22/14	DELIVERY MILES 9	SALES DEALER NO 100	PRODUCTION DATE 11/22/22
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	P.O. NO	R.O. DATE	

LISARBRAZIL@GMAIL.COM

JOB# 1 CHARGES-----
LABOR-----
J# 1 99F0Z OPEN RECALL TECH(S):7777
22S43 TRANSMISSION SHIFTER CABLE BUSHING
REMOVED AND REPLACED THE SHIFTER BUSHING PER RECALL. DONE. WARRANTY
PARTS-----QTY-----FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
1 KV6Z-7K340-A BUSHING
1 DG9Z-7S004-A CAP
JOB# 1 TOTALS----- TOTAL - PARTS
WARRANTY
WARRANTY
0.00

JOB# 2 CHARGES----- JOB# 1 JOURNAL PREFIX FOCs JOB# 1 TOTAL 0.00

LABOR-----
J# 2 26F0Z ELECTRICAL TECH(S):7021
CUSTOMER STATES THAT BACKUP CAMERA IS INOPERABLE. PLEASE ADVISE. 0.00
VERIFIED CONCERN, PERFORMED PPT, FOUND CAMERA INTERNALLY
FAULTED, NECESSARY TO REMOVE AND REPLACE, CAMERA, CUSTOMER
DECLINED REPAIRS AT THIS TIME.

JOB# 2 TOTALS-----
JOB# 3 CHARGES----- JOB# 2 JOURNAL PREFIX FOCs JOB# 2 TOTAL 0.00

LABOR-----
J# 3 04F0Z EXTERIOR TRIM TECH(S):7021
CUSTOMER STATES THERE IS DAMAGE TO SKID PLATE. WOULD LIKE PRICE TO REPAIR. 0.00
NO PROBLEM FOUND.

JOB# 3 TOTALS-----
JOB# 4 CHARGES----- JOB# 3 JOURNAL PREFIX FOCs JOB# 3 TOTAL 0.00

LABOR-----
J# 4 01F0Z041F *FRONT WIPER BLADES TECH(S):7777
One Pair of dealer-installed Motorcraft Premium Wear Wiper Blades. Taxes extra. See Service Advisor for installation, vehicle applications and details. 2.95
Install one pair of Motorcraft Premium Wear Wiper Blades.

PARTS-----QTY-----FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
2 LU2Z-17V528-K BLADE A
19.37
TOTAL - PARTS 38.74
38.74

MO: [REDACTED]

DISCLAIMER OF WARRANTIES
Any warranties on the products sold hereby are made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.



3796 NE I-10 Frontage Road
Sealy, Texas 77474
(979) 885-7700

CUSTOMER NAME: [REDACTED] Ref # 11471403 CELL: [REDACTED]
ADVISOR: KEVIN TAG NO: 8485 060 INVOICE DATE: 11/30/22
LABOR RATE: [REDACTED] LICENSE NO: [REDACTED] MILEAGE: 173,102 COLOR: INGOT SILV
SAN ANTONIO, TX YEAR / MAKE / MODEL: 15/FORD TRUCK/ESCAPE/4DR SE FWD DELIVERY DATE: 11/22/14 DELIVERY MILES: 9
VEHICLE I.D. NO: 1 F M C U 0 G 7 6 F U [REDACTED] SELLING DEALER NO: 100 PRODUCTION DATE: [REDACTED]
F.T.E. NO: [REDACTED] P.O. NO: [REDACTED] R.O. DATE: 11/22/22
BUSINESS PHONE: [REDACTED] COMMENTS: [REDACTED] MO: [REDACTED]

JOB# 4 TOTALS

LABOR 2.95
PARTS 38.74
JOB# 4 JOURNAL PREFIX FOCs JOB# 4 TOTAL 41.69

JOB# 5 CHARGES

LABOR
J# 5 01FOZ041R *REAR WIPER BLADE TECH(S):7777 2.95
CUSTOMER REQUESTS REAR WIPER BLADE
REPLACED REAR WIPER BLADE
PARTS-----QTY-----FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
1 R1121 R WIPER 26.31
TOTAL - PARTS 26.31

JOB# 5 TOTALS

LABOR 2.95
PARTS 26.31
JOB# 5 JOURNAL PREFIX FOCs JOB# 5 TOTAL 29.26

JOB# 6 CHARGES

LABOR
J# 6 08FOZ SUSPENSION/STEERING TECH(S):7021 783.00
CUSTOMER STATES THAT FRONT END WILL SQUEAK WHEN GOING OVER
PARKING LOT SPEED BUMPS.
PERFORMED INSPECTION, FOUND FRONT LOWER CONTROL ARMS AND
OUTER TIE RODS HAD SLACK, REMOVED AND REPLACED TIE RODS,
REMOVED AND REPLACED LOWER CONTROL ARMS, RETEST SQUEAK PASS
PARTS-----QTY-----FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
1 5CB40505 L CONTR 268.00 268.00
0
1 5CB40510 R CONTR 266.00 266.00
0
1 ES800954 R TIE R 67.40 67.40
0
1 ES800955 L TIE R 70.26 70.26
0
TOTAL - PARTS 671.66

JOB# 6 TOTALS

LABOR 783.00
PARTS 671.66
JOB# 6 JOURNAL PREFIX FOCs JOB# 6 TOTAL 1454.66

JOB# 7 CHARGES

LABOR
J# 7+08FOZ0003 4 WHEEL ALIGNMENT TECH(S):7021 119.95
CUSTOMER REQUESTS TO HAVE THE FRONT END ALIGNED ON THEIR
VEHICLE.
WE HAVE ALIGNED THE FRONT END OF YOUR VEHICLE AS REQUESTED

DISCLAIMER OF WARRANTIES

Any warranties on the products sold hereby are made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.



3796 NE I-10 Frontage Road
Sealy, Texas 77474
(979) 885-7700

Reg # 11471403

CELL: [REDACTED]

CUSTOMER NAME [REDACTED] SAN ANTONIO, TX	ADVISOR KEVIN	TAG NO. 8485	INVOICE DATE 11/30/22
LABOR RATE	LICENSE NO.	MILEAGE 173,102	COLOR INGOT SILV
YEAR / MAKE / MODEL 15/FORD TRUCK/ESCAPE/4DR SE FWD	VEHICLE I.D. NO. 1 F M C U O G 7 6 F U	DELIVERY DATE 11/22/14	STOCK NO.
F.T.E. NO.	COMMENTS	SELLING DEALER NO. 100	DELIVERY MILES 9
		PRODUCTION DATE	
		R.O. DATE 11/22/22	

TOTALS-----
LABOR 119.95
JOB# 7 JOURNAL PREFIX FOCs JOB# 7 TOTAL 119.95

* [] CASH [] CHECK CK NO. [] *
* [] VISA [] MASTERCARD [] DISCOVER *
* [] AMER XPRESS [] OTHER [] CHARGE *

*****THANK YOU FOR YOUR SERVICE BUSINESS!!!*****

TOTAL LABOR..... 908.85
TOTAL PARTS..... 736.71
TOTAL SUBLET... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 0.00
TOTAL MISC DISC 0.00
TOTAL TAX..... 60.78

TOTAL INVOICE \$ 1706.34

DISCLAIMER OF WARRANTIES

Any warranties on the products sold hereby are made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

CUSTOMER SIGNATURE

DUPLICATE INVOICE *****

RA #:
Invoice #:
Invoice Date:
Reservation #:

07/23/2023



1505 HARRY WURZBACH
78209-6001 SAN ANTONIO, UNITED STATES

BILLING DETAIL

Description	Qty	Period	Rate	Amount
Taxable Charges:				
TIME & DISTANCE	4	WK	332.36	1,329.44
ADDITIONAL DRIVER	28	DAY	15.00	420.00
VLF REC	28	DAY	1.29	36.12

Taxable Subtotal: 1,785.56

Non-Taxable Charges:

REFUELING CHARGE	11	VAR	4.32	47.52
BEXAR SPORTS VENUE TAX	1,785.56	%	5.00	89.27
TX MOTOR VEHICLE RENTAL TAX	1,785.56	%	10.00	178.56

Non-Taxable Subtotal: 315.35

Total (USD) 2,100.91

PAYMENTS

Payment 07/24/2023 VI 2,100.91

Total Payments (USD) 2,100.91

Balance Due (USD) 0.00

Individual line item charges such as rental rates for Time and Distance, percentage-based charges (e.g., sales taxes and fees or surcharges), and charges divided between multiple parties may be rounded up or down a whole cent to ensure that the charges equal the actual Total Amount Due and/or to avoid fractional cents.

Tax ID:

BILL TO

SAN ANTONIO, TX, UNITED STATES

RENTAL INFORMATION

Driver:

Check Out:

06/26/2023 08:19

Location:

SAN ANTONIO RIVERWALK

Check In:

07/23/2023 21:55

Location:

SAN ANTONIO RIVERWALK

Charged Car Class:

FCAR / FCAR

Type:

VP

Rate Plan:

ENTERPRISE PLUS / WEB 8 DY WEEKLY MM

RENTAL VEHICLES

#	Year	Make	Model	Series	Class	Reg. Date	Start	End
1	2023	TOYO	TACC	GR52	SPAR		06/26	07/24

#	Lic. Plate	MRP	CO2	Fuel	KM/M	Beg. / End. / Total
1				UL		10613 / 13451 / 2838

#	VIN #	Eng.	HP	KW	Unit
1	3TMAZ5CNXPM		278	204	8DPKH7

Fed Tax Id: 26-4086616

FOR BILLING INQUIRIES

Tel#: 2102833811
STXARADMIN@EHI.com