

OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

National Highway Traffic Safety Administration INTERNET:www.nhtsa.dot.gov/hotline (1-888-327-4236)	FOR AGENCY USE ONLY 100148	
	Date Received 16-FEB-2023 MAY 04 2023	Repository <input type="checkbox"/> Reference No. 11507645
OWNER INFORMATION (Type or Print)		
Name	Daytime Telephone Number	Email Address
Address		
City Princeton	State WV	ZIP Code
The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).		

VEHICLE INFORMATION			
17 digit Vehicle Identification Number Located at bottom of windshield on driver's side 1N6BD0CT6JN	MAKE NISSAN	Model FRONTIER	Model Year 2018
Date Purchased 3/12/2021	Dealer's Name and Telephone Number MOTOR MILE M-S LLC, 2340 ROANOKE ST	Engine: No: Cylinders 4 (Four)	Fuel Type: Unleaded 87 Octane
Original Owner <input type="checkbox"/>	Dealer's City ALEXANDRIA, VA CHRISTIANBURG	STATE VA	ZIP Code 24073
Transmission Type AUTOMATIC	<input checked="" type="checkbox"/> Antilock Brakes <input checked="" type="checkbox"/> Cruise Control	Powertrain 2 Wheel DR.	Multiple Failure: ONLY COMPUTER RESET
Incident Date(s) 12-FEB-2023			

ON INVOICE FAILED COMPONENT(S)/PART(S) INFORMATION		
Vehicle Components Codes: 116100 ELECTRICAL SYSTEM:IGNITION:SWITCH ELECTRICAL HOUSING WITH SWITCH & NISSAN PART 48701EAD08/48701EAD08	Failure Mileage 50260.0	Failure Speed STOPPED AFTER ENTERING PARKING LOT

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE		
Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTMAL 9ABCD36)	<input type="checkbox"/> Original Requirement <input type="checkbox"/> Prior Repair	Failure Location:
Tire Component Code	Tire Failure Type:	

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE		
Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION (Please describe in detail the incident(s), failure(s), crash(es), injury(ies).)				
Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured (2) - LUCKED OUT	Number of Deaths	Reported to Police N N/A

Narrative Description of Incident(s), Crash(es), Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure;
i.e., parts repaired or replaced (and if old part is available).

The contact owns a 2018 Nissan Frontier. The contact stated that upon inserting the key in the ignition switch to start the vehicle, the ignition switch was significantly loose, preventing the vehicle from starting. An independent mechanic diagnosed that the ignition switch plastic body needed to be replaced. The contact related the failure to NHTSA Campaign Number: 18V551000 (Electrical System). An unknown dealer and the manufacturer were notified of the failure, but no assistance was provided. The failure mileage was approximately 50,260.

* OWNERS COMMENTS: WENT OUT (ignition function) ^(FMS) UPON ENTERING PARKING SPACE; tried to start/would not start) → HAD TOWED TO K&M PERFORMANCE, BLUEFIELD, WV/Kenny experienced NISSAN MECHANIC "HAD TOWED ON MON. 2/13/23" (LA)
① MINOR TILT ADJUSTMENT; REST OF MAJOR WORK WAS REMOVING PART AND INSTALLING NEW NISSAN PART. HAVE OLD PART

CONTINUED: (FROM 1A): APPRECIATE INVESTIGATION (SAVE DEATHS)

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies)

TIP OF MODULE AT BOTTOM OF HOUSING BROKE OFF!

I WAS extremely lucky that if ignition function broke while driving 55-60 MPH; I PROBABLY would be dead!!! -> NO control of vehicle!!!

Deb McCarthy: 770-403-9424 is at in on NISSAN CALD
* I am requesting \$9,648.04 TAXI RE-IMBURSEMENT OR whatever law allows. YOU talk to NISSAN; THEY DO NOT WANT TO HEAR FROM ME.

ATTACH ADDITIONAL SHEETS IF NECESSARY


ONLY FOR SUPPORT ONLY!

U.S. Department of Transportation

National Highway Traffic Safety Administration

1200 New Jersey Avenue SE. Washington, D.C. 20077-9382

Official Business Penalty for Private Use \$300




NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

BUSINESS REPLY MAIL
FIRST CLASS MAIL PERMIT NO. 1888 WASHINGTON, DC


POSTAGE WILL BE PAID BY ADDRESSEE

US Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation, NEF-100
1200 New Jersey Avenue SE.
Washington, D.C. 20077-9382



Think your vehicle has a safety defect?

If so:




Use the enclosed form to file a report.

or visit:
www.safercar.gov

or call:
**Vehicle Safety Hotline
888-327-4236**

NHTSA
www.nhtsa.gov

Vehicle Owners Questionnaire (VOQ)
U.S. Department of Transportation
National Highway Traffic Safety Administration



K & M Performance Automotive, LLC

1014 Bluefield Avenue
Bluefield, WV 24701
Phone 304-323-Auto (2886)

DATE
2-17-23
CUSTOMER ORDER NO.

QTY.	PART NO. / DESCRIPTION	PRICE
1	48701EA00B	268.14

Nissan Factory Direct Part.

NAME: [REDACTED] TIME RECEIVED: 2-13-2023 LICENSE NO. [REDACTED]
ADDRESS: [REDACTED] TIME PROMISED: [REDACTED]

CITY: [REDACTED] STATE: [REDACTED] ZIP: [REDACTED] BUS. PHONE: [REDACTED] RES. PHONE: [REDACTED]


YEAR: 18 MAKE / MODEL: NISSAN Frontier COLOR: silver VEHICLE IDENTIFICATION NUMBER (17 Digits): 1N6BA0CT6JN [REDACTED]

Veteran Discount!
Apple - Parts + labor
Thank you!
Kenya -

x90 warranty on the part

MECH OPER NO. REPAIR INSTRUCTIONS LABOR

replaced ignition switch lock housing actuator, necessary to drill housing to get a part 4.5 337.50



No tilt; Int. wipers; No Cruise; Auto Trans.

PARTS TOTAL 268.14

WRECKER CHARGES
SUBLET REPAIRS

SUBLET TOTAL

GAL. FUEL @
QTS. OIL @
LBS. GREASE @

FUEL, OIL & GREASE TOTAL

INSPECT PARTS RETURN PARTS

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. I hereby release you from any responsibility for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any cause beyond your control. All warranties are hereby disclaimed. This disclaimer does not affect the manufacturer's warranty if any. I will pay reasonable attorney's fees and court costs if this account is not paid within terms.

INTERNAL	DESCRIPTION	ACCT.	AMOUNT
	TOTAL LABOR		337.50
	TOTAL PARTS		268.14
	FUEL OIL GREASE		
	SUBLET REPAIRS		
			605.64
	TAX		42.40
	TOTAL AMOUNT		648.04

PRINCETON, WV

CHARLESTON WV 250

3 APR 2023 PM 1 L



U.S. Dept. of Transportation
NATIONAL HIGHWAY TRAFFIC SAFETY
DEFECTS
OFC. OF "DEFECTS INVESTIGATION",
1200 M.I. AVE. S.E., WASHINGTON, DC

20077-9392 20077 9392