


**From:** [Ambrose, Ann-Marie L](#)  
**To:** [EVOO \(NHTSA\)](#); [Robertson, Faithia \(NHTSA\)](#); [Lewis, Brenton](#)  
**Cc:** [NHTSA ODI CED](#); [Strasser-King, Marion C](#); [Rosales, Denise](#)  
**Subject:** ODI-11560244  
**Date:** Thursday, January 18, 2024 9:48:58 AM  
**Attachments:** 


**CAUTION:** This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

  
Jan 16

Subject: ODI ref number 11560244  
To: [nhtsa.webmaster@dot.gov](mailto:nhtsa.webmaster@dot.gov)

CAUTION: This email originated from outside of the Department of Transportation (DOT). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

I would like to point out that the NHSTA representative transposed the wrong mileage when I filed the complaint. Please correct the mileage to 316 below. It was not 3,165. I believe they added a 5 to the end by mistake. The car was brand new. Thanks again.



[Opens a new window](#)

...

[Opens a new window](#)

[December 15, 2023 NHTSA ID NUMBER: 11560244](#)[Opens a new window](#)

[Components: ELECTRICAL SYSTEM](#)[Opens a new window](#)

NHTSA ID Number: 11560244

Incident Date December 5, 2023

Consumer Location NEW HARTFORD, NY

Vehicle Identification Number 50EA1TEA8PA\*\*\*\*

Summary of Complaint

CRASHNo

FIRENo

INJURIES0

DEATHS0

The contact owns a 2023 Lucid Air. The contact stated that he had purchased and picked up the vehicle from the Service Center. The contact stated that the vehicle had a 425-mile range, and the mile range at pick-up was 408. The contact stated that while driving 64 MPH, the heater became inoperable. Additionally, the vehicle started to lose charging range. The message "Battery Critically Low Vehicle May Shut Down Unexpectedly - Charge Immediately" was displayed. The contact stated that he drove to a charging station. The contact stated that he was able to charge the vehicle after several attempts. Additionally, the charging port failed to close and was stuck after charging the vehicle. The Service Center was notified of the failure and picked up the vehicle. The Service Center later informed the contact that the heater had drained the battery, and no other issue was found. The contact stated that he noticed through the App connected to the vehicle that the Service Center had not test-driven the

vehicle. The service center declined to trade the vehicle. The vehicle was not repaired. The manufacturer was notified of the failure. The failure mileage was 3,165.

Thank you

**Ann-Marie Ambrose**  
**Quality Control Specialist**  
**ASRC Federal Holding Company**  
[aambrose@asrcfederal.com](mailto:aambrose@asrcfederal.com)  
7000 Muirkirk Meadows Drive, Beltsville, MD 20705  
[asrcfederal.com](http://asrcfederal.com) | Purpose Driven. Enduring Commitment.

---

The preceding message (including attachments) is covered by the Electronic Communication Privacy Act, 18 U.S.C. sections 2510-2512, is intended only for the person or entity to which it is addressed, and may contain information that is confidential, protected by attorney-client or other privilege, or otherwise protected from disclosure by law. If you are not the intended recipient, you are hereby notified that any retention, dissemination, distribution, or copying of this communication is strictly prohibited. Please reply to the sender that you have received the message in error and destroy the original message and all copies.