

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

AUTO SAFETY HOTLINE

VEHICLE OWNER'S QUESTIONNAIRE

NATIONWIDE 1-800-424-9393
DC METRO AREA 202-386-0123

POSTED

FOR AGENCY USE ONLY

DATE RECEIVED

00 JUN 12 AM 9:27

od. or _____
r. dt _____
od. rt _____
up. hr _____

REFERENCE NO.

OFFICE
DEFECTS INVESTIGATION

552578

DAY TIME TELEPHONE NO. (AREA CODE)

OWNER INFORMATION (TYPE OR PRINT)

NAME and ADDRESS

COPIED

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES ☒ NO ☐
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

SIGNATURE OF OWNER

DATE 7-13-99

VEHICLE INFORMATION

VEHICLE IDENTIFICATION NO.*

1G1FP87F7GN161594

VEHICLE MAKE

CHEVROLET

VEHICLE MODEL

IROC

MODEL YEAR

86

*LOCATED AT BOTTOM OF WINDSHIELD ON DRIVER'S SIDE

CURRENT ODOMETER READING

114000

DATE

PURCHASED 1997

DEALER'S NAME, CITY & STATE

PRIVATE

ENGINE SIZE

(CID/CC/L) 5.0

☐ TURBO
☐ DIESEL
☐ GAS
☒ FUEL INJECTOR

NO. CYLINDERS 8

TRANSMISSION TYPE

☐ MANUAL
☒ AUTOMATIC

ANTILOCK BRAKES

☐ YES
☒ NO

RESTRAINT SYSTEM

☐ DRIVERSIDE AIRBAG ☐ MOTORBELT
☐ PASSENGERSIDE AIRBAG
☐ 3-POINT BELT ☒ 2-POINT BELTCRUISE
CONTROL☒ YES
☐ NO

DRIVETRAIN

☐ FRONT
☒ REAR
☐ 4-WHEEL

BODY STYLE

STAWAG 4 DR
2 DR ☒ HATCH BK
VAN
PK UP TRK
OTHER

FAILED COMPONENT(S)/PART(S) INFORMATION (REPORT TIRE INFORMATION ON BACK)

COMPONENT

STEERING
IGNITION

PART NAME(S)

KNUCKLE?

LOCATION

☐ LEFT FRONT
☐ RIGHT REAR

FAILED PART(S)

☒ ORIGINAL
☐ REPLACEMENT

NO. OF FAILURES

12
AT LEAST

DATE(S) OF FAILURE(S) SINCE Oct 98

MILEAGE AT FAILURE(S) 101,000 - 114,000
5 MPH to 40 MPH

VEHICLE SPEED AT FAILURE(S)

MANUFACTURER
CONTACTED☒ YES ☐ NONHTSA PREVIOUSLY
CONTACTED☐ YES ☒ NO

APPLICABLE ACCIDENT INFORMATION

ACCIDENT

☐ YES ☐ NO

FIRE

☐ YES ☐ NO

NUMBER PERSONS INJURED

NUMBER OF FATALITIES

PROPERTY
DAMAGE
EST\$

POLICE REPORTED

☐ YES ☐ NO

NARRATIVE DESCRIPTION OF FAILURE(S), ACCIDENT(S), INJURY(IES)

Bolt nuts loose on tilt steering wheel Inside steering column
Ignition shuts off while turning steering wheel causing NO
power steering / Power brakes " NO CONTROL OVER VEHICLE "

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974
Public Law 93-579This information is requested pursuant to authority vested in the National
Highway Traffic Safety Act and subsequent amendments. You are
under no obligation to respond to this questionnaire. Your response maybe used to assist the NHTSA in determining whether a manufacturer
should take appropriate action to correct a safety defect. If the NHTSA
proceeds with administrative enforcement or litigation against a man-
ufacturer, your response, or a statistical summary thereof, may be used in
support of the agency's action.