

9956

 AUTO SAFETY HOTLINE VEHICLE OWNER'S QUESTIONNAIRE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION NATIONWIDE 1-800-424-9393 DC METRO AREA 202-366-0123		FOR AGENCY USE ONLY DATE RECEIVED _____ REFERENCE NO. 560158	
OWNER INFORMATION (TYPE OR PRINT) NAME _____ ADDRESS _____ CITY _____ STATE _____ ZIP _____		DO YOU AUTHORIZE NHTSA TO PROVIDE A COPY OF THIS REPORT TO THE MANUFACTURER OF YOUR VEHICLE? YES ☐ NO ☐ IN THE ABSENCE OF AN AUTHORIZATION, NHTSA WILL NOT PROVIDE YOUR NAME OR ADDRESS TO THE VEHICLE MANUFACTURER.	
SIGNATURE OF OWNER _____		DATE 3-13-00	
VEHICLE INFORMATION VEHICLE IDENTIFICATION NO. 4VG7DECH7XN766295 *LOCATED AT BOTTOM OF WINDSHIELD ON DRIVER'S SIDE VEHICLE MAKE Volvo VEHICLE MODEL VNL64T MODEL YEAR 1999 CURRENT ODOMETER READING 239756 DATE PURCHASED 7/15/98 DEALER'S NAME CITY & STATE Denver Volvo, CO ☒ NEW ☐ USED ENGINE SIZE (CID/CCA) _____ NO. CYLINDERS 6			
TRANSMISSION TYPE ☒ MANUAL ☐ AUTOMATIC	ANTILOCK BRAKES ☒ YES ☐ NO	RESTRAINT SYSTEM ☐ DRIVER'S SIDE AIRBAG ☐ PASSENGER'S SIDE AIRBAG ☒ 3-POINT BELT ☐ 2-POINT BELT	CRUISE CONTROL ☒ YES ☐ NO
DRIVE SHAFT ☐ FRONT ☐ REAR ☐ 4-WHEEL	BODY STYLE STATION WAGON ☐ 4 DR ☐ 2 DR ☐	HATCH BACK ☐ VAN ☐ PICK UP TRUCK ☐ OTHER ☒	THURBO ☐ DIESEL ☐ GAS ☐ FUEL INJECTOR ☐
FAILED COMPONENT(S)/PART(S) INFORMATION (REPORT TIRE INFORMATION ON BACK)			
COMPONENT Seals, Wheel Bearings Cones/Races	PART NAME(S) _____	LOCATION ☐ LEFT FRONT ☐ RIGHT REAR	FAILED PART(S) ☐ ORIGINAL REPLACEMENT
NO. OF FAILURES _____	DATE(S) OF FAILURE(S) _____ MILEAGE AT FAILURE(S) _____ VEHICLE SPEED AT FAILURE(S) _____	MANUFACTURER CONTACTED ☒ YES ☐ NO	NHTSA PREVIOUSLY CONTACTED ☐ YES ☒ NO
APPLICABLE ACCIDENT INFORMATION			
ACCIDENT ☐ YES ☐ NO	FIRE ☐ YES ☐ NO	NUMBER PERSONS INJURED _____	NUMBER OF FATALITIES _____
PROPERTY DAMAGE \$ \$ \$ _____		POLICE REPORTED ☐ YES ☐ NO	
NARRATIVE DESCRIPTION OF FAILURE(S), ACCIDENT(S), INJURY(IES) PREMATURE WEAR FROM STEER TIRES RESULTING FROM IMPROPER COMBINATION OF RACE/BEARINGS IN MERITOR AXLES			
CONTINUE ON BACK IF NEEDED			
The Privacy Act of 1974 Public Law 93-572 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may		be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.	

REPAIR HISTORY BY SYSTEM CODE orderhsr

Run Date: 03/09/00

Page 127

Tractor * thru * 01/01/1998 thru 03/09/2000 System 18 thru 18

Tractor Sys	Date	Description of Part/Labor/Tire	Hub	WO	Qty
9956	continued...				
		HM212049 BEARING - CONE		94682	1.00
		HM212011 BEARING - RACE		94682	1.00
		35066 SEAL - STEER		94682	1.00
		Labor			
		REPLACE WHEEL SEAL, OUTER BRGS, & RACES		94682	1.50
	09/24/99	Parts	195091		
		3720 BEARING - 3720 TIMKEN		92153	1.00
		HM212049 BEARING - CONE		92153	1.00
		HM212011 BEARING - RACE		92153	1.00
		65263U SEAL - STEER		92153	1.00
		Labor			
		REPLACE L WHL BEARING SEAL AND RACES		92153	1.00
		2 THOUSANDS			
	03/05/99	Labor	203418		
		ADJUST BOTH STEER AXLE WHEEL BEARINGS		84533	1.00
9956	18 11/10/99	Parts	219928		
		3720 BEARING - 3720 TIMKEN		94682	1.00