

POSTED by NCM

U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
TO REPORT VEHICLE SAFETY DEFECTS
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov/hotline

COPIED

FOR AGENCY USE ONLY

Od. or _____
rt. dt. _____
ad. rt. _____
up. ltr. _____

01 AUG -1 AM 11:20

Reference No.

OFFICE
DEFECTS INVS

562286

OWNER INFORMATION (Type or Print)

Name _____
Street _____
City _____

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

Signature of Owner _____

Date

7,24,01

PRODUCT INFORMATION

| | | | | |
|--|---|---|--|---|
| Vehicle Identification No. (VIN) (17 Digits) JHLRD2844YS00509P | | Make HONDA | Model CRV | Year 2000 |
| Purchased Date July 2000 | Dealer's Name MILLER HONDA | | Engine Size (CID/CC/L) L8 | <input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Fuel Injection |
| <input checked="" type="checkbox"/> New <input type="checkbox"/> Used | Dealer's City CULVER CITY | State CA | Zip Code 90230 | No. Cylinders 4 |
| Manufacture Date (on driver's door or pillar) JUNE 2000 | Transmission Type <input type="checkbox"/> Manual <input checked="" type="checkbox"/> Automatic | Restraint System <input checked="" type="checkbox"/> Driver's Side Air Bag <input type="checkbox"/> Passenger's Side Air Bag <input checked="" type="checkbox"/> 3-Point Belt <input type="checkbox"/> Motorbelt <input type="checkbox"/> 2-Point Belt | Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Drivetrain <input checked="" type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel |
| Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Van <input type="checkbox"/> Minivan <input type="checkbox"/> Other | | Body Style <input type="checkbox"/> 2-Door <input checked="" type="checkbox"/> 4-Door <input type="checkbox"/> Station Wagon <input type="checkbox"/> Pick Up Truck <input type="checkbox"/> Other | | |

FAILED COMPONENT(S)/PART(S) INFORMATION

| | | | |
|-----------------------|--|--|---|
| Part Name(s) TIRES | Location <input checked="" type="checkbox"/> Left <input checked="" type="checkbox"/> Right <input type="checkbox"/> Front <input type="checkbox"/> Rear | Failed Part(s) <input checked="" type="checkbox"/> Original <input type="checkbox"/> Replacement | Handicap Adaptive Equip <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
|-----------------------|--|--|---|

TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

| | | | |
|--|---|--|--|
| Tire Brand BRIDGE STONE / FIRESTONE | Tire Name DUELLER H/T | | |
| Complete Tire Size P205 / 70 R 15 95S | DOT No. | | |
| No. of Failures SEVERAL | Date(s) of Failure(s) SEPT. 2000 THRU MARCH 2001 | Failed Part(s) Available? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | NHTSA Previously Contacted? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Mileage at Failure(s) 4,000 MILES | Vehicle Speed at Failure(s) 5 MPH | | |

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies). Attach photos if available.)

| | | | | |
|--|---|---------------------------|----------------------|---|
| Crash <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Frog <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Number of Persons Injured | Number of Fatalities | Reported to Manufacturer <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
|--|---|---------------------------|----------------------|---|

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies).

The front tires lose traction and spin upon gradual acceleration from a stop with two or three attempts to get moving forward especially when making left turns. Honda dealer contacted but "could not duplicate problem". Tire manufacturer (Bridgestone/Firestone) contacted and tires were replaced on 26 March 2001 with Dueller H/L UNI-T. No traction problems with new tires (Dueller H/L) on wet pavement conditions.

Continue on back.

The Privacy Act of 1974 - Public Law 93-579 This information is requested pursuant to a 49 U.S.C. Chapter 301. You are under no obligation to respond to this questionnaire. Your response may be used to assist NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Mail postage free or fax to 202-366-7882

THE FOLLOWING PAGES ARE WITHHELD TO
PROTECT UNWARRANTED INVASION OF
PERSONAL PRIVACY PURSUANT TO
EXEMPTION 6 OF THE FREEDOM OF
INFORMATION ACT, 5 U.S.C. 552(b)(6)

(Page 1 through Page 4)





