



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
TO REPORT VEHICLE SAFETY DEFECT
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET: www.nhtsa.dot.gov

FOR AGENCY USE ONLY

Od _ _
ri _ _
od _ _
up _ _

Reference: No

OWNER INFORMATION (Type or Print)

Name: [REDACTED]
Street: [REDACTED]
City: [REDACTED]
State: [REDACTED]
Zip: [REDACTED]
Vehicle Identification Number (VIN): **564424**

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☒ YES ☐ NO
In the absence of an authorization, NHTSA will NOT provide your name or address to the vehicle manufacturer.

Signature of Owner

Date 12/29/01

PRODUCT INFORMATION

Vehicle Ident. No. (VIN) (17-12 digits) 1GCCS14AXM8182247		Make Chery		Model 510		Year 91	
Purchased Date 9-95		Dealer's Name		Engine Size (CID/Gal) 4		☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection	
☐ New ☒ Used		Dealer's City		State		Zip Code	
Manufacture Date (on driver's door or pillar) FADED OUT		Transmission Type ☒ Manual ☐ Automatic		Restraint System: ☐ Air Bag ☒ Seat Belt ☐ Child Seat		Drive Train ☐ 4-Wheel 2 wheel	

FAILED COMPONENT(S)/PART(S) INFORMATION

Part Name(s) EXHAUST MAN. FOLD	Location ☒ Left ☐ Right ☒ Front ☐ Rear	Failed Part(s) ☒ Original ☐ Replacement
--	--	--

TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Brand	Tire Name	Complete Tire Size
No. of Failures	Date(s) of Failure(s): Mileage at Failure(s): Vehicle Speed at Failure(s):	Failed Part(s) Available? ☐ Yes ☐ No NHTSA Previously Compacted? ☐ Yes ☐ No

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies). Attach photos if available.)

Crash ☐ Yes ☒ No	Fire ☒ Yes ☐ No	Number Persons Injured 0	Number of Fatalities 0	Reported to Manufacturer ☐ Yes ☒ No
--	---	------------------------------------	----------------------------------	---

Narrative Description of Incident(s), Failure(s), Crash(es), and Injury(ies):

**MANIFOLD BURNED THROUGH ON ENGINE BLOCK
SIDE, CAUSING EXHAUST GASES TO BLOW
AGAINST ENGINE, BURNED UP O₂ SENSORS
PREMATURELY**

Continue on back

The Privacy Act of 1974 - Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.