


 U.S. Department
of Transportation

 National Highway
Traffic Safety
Administration

AUTO SAFETY HOTLINE

VEHICLE OWNER'S QUESTIONNAIRE

 NATIONWIDE 1-800-424-9393
DC METRO AREA 202-386-0123

OWNER INFORMATION (TYPE OR PRINT)

FOR AGENCY USE ONLY

DATE RECEIVED

 96 SEP -9 AM 11:03
30 Jul 1996

 OFFICE
DEFECTS INVESTIGATION

 od. or
rt. di
od. rt
up. rt

REFERENCE NO.

800257

DAY TIME TELEPHONE NO. (AREA CODE)

 Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES ☒ NO ☐
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

SIGNATURE OF OWNER

DATE

8/30/96

VEHICLE INFORMATION

VEHICLE IDENTIFICATION NO.*

2P4FH453OKR158050

VEHICLE MAKE

MINI Van

VEHICLE MODEL

VOYAGER

MODEL YEAR

1989

*LOCATED AT BOTTOM OF WINDSHIELD ON DRIVER'S SIDE

CURRENT ODOMETER READING

DATE

PURCHASED

DEALER'S NAME, CITY & STATE

 ENGINE SIZE
(CID/CC/L)

☐ TURBO
☐ DIESEL
☐ GAS
☐ FUEL INJECTN

NO. CYLINDERS

TRANSMISSION TYPE

ANTILOCK BRAKES

RESTRAINT SYSTEM

CRUISE CONTROL

DRIVETRAIN

BODY STYLE

☐ MANUAL
☒ AUTOMATIC

☐ YES
☒ NO

☐ DRIVERSIDE AIRBAG ☐ MOTORBELT
☐ PASSENGERSIDE AIRBAG
☐ 3-POINT BELT ☐ 2-POINT BELT

☒ YES
☐ NO

☒ FRONT
☐ REAR
☐ 4-WHEEL

 STAWAG ☐ HATCH BK
4 DR ☐ VAN
2 DR ☐ PK UP TRK
OTHER ☐

FAILED COMPONENT(S)/PART(S) INFORMATION (REPORT TIRE INFORMATION ON BACK)

COMPONENT

PART NAME(S)

LOCATION

FAILED PART(S)

920

 INTERIOR SYSTEMS: ACTIVE RESTRAINTS: BELT
BUCKLES

☐ LEFT
☒ FRONT

☒ RIGHT
☐ REAR

☒ ORIGINAL
☐ REPLACEMENT

NO. OF FAILURES

DATE(S) OF FAILURE(S)

 MANUFACTURER
CONTACTED

 NHTSA PREVIOUSLY
CONTACTED

MILEAGE AT FAILURE(S)

☐ YES ☒ NO

☐ YES ☒ NO

VEHICLE SPEED AT FAILURE(S)

APPLICABLE ACCIDENT INFORMATION

ACCIDENT

FIRE

NUMBER PERSONS INJURED

NUMBER OF FATALITIES

 PROPERTY
DAMAGE
ESTS

POLICE REPORTED

☐ YES ☒ NO

☐ YES ☒ NO

☐ YES ☒ NO

☐ YES ☒ NO

☐ YES ☒ NO

☐ YES ☒ NO

NARRATIVE DESCRIPTION OF FAILURE(S), ACCIDENT(S), INJURY(IES)

THE FRONT PASS. SEAT BELT BUCKLE DOES NOT LOCK. PLEASE EXPLAIN MORE. *AK
Front passenger seat belt buckle does not lock completely and releases
by its self.

CONTINUE ON BACK IF NEEDED

 The Privacy Act of 1974
Public Law 93-579

 This information is requested pursuant to authority vested in the National
Highway Traffic Safety Act and subsequent amendments. You are
under no obligation to respond to this questionnaire. Your response may

 be used to assist the NHTSA in determining whether a manufacturer
should take appropriate action to correct a safety defect. If the NHTSA
proceeds with administrative enforcement or litigation against a manufac-
turer, your response, or a statistical summary thereof, may be used in
support of the agency's action.

NUMBER

800257

CHANGED

TO

690/300