

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT
1-888-327-4236
www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Data Received

26-FEB-2000

 Od_or _____
 rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

719320

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? YES NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) <small>(Listed at front of windshield or driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1G3WX52H7YF220833	OLDSMOBILE	INTRIGUE	2000	

Purchase Date 01-DEC-1999	Dealer's Name _____	Engine Size (CID/CC/L) 3.5	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input type="checkbox"/> Fuel Injection
<input checked="" type="checkbox"/> New <input type="checkbox"/> Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input type="checkbox"/> 3-Point Belt <input type="checkbox"/> Motorbell <input type="checkbox"/> Driverside Airbag <input type="checkbox"/> 2-Point Belt <input type="checkbox"/> Passengerside Airbag	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input checked="" type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Sport Ult <input type="checkbox"/> Van <input type="checkbox"/> Truck <input type="checkbox"/> Minivan <input type="checkbox"/> Motorcycle <input type="checkbox"/> Other _____	Body Style <input type="checkbox"/> 2-Door <input checked="" type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input type="checkbox"/> Other _____
--	---	---	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05200000 12424000	Par. Name(s) ENGINE COOLING SYSTEM INTERIOR SYSTEMS:INSTRUMENT PANEL:GAUGE:INDICATOR:TEM	Location <input type="checkbox"/> Left <input type="checkbox"/> Right <input type="checkbox"/> Frnt <input type="checkbox"/> Rear	Failed Part(s) <input type="checkbox"/> Original <input type="checkbox"/> Replacement
-----------------------------------	--	---	---

No. of Failures 3	Date(s) of Failure(s) 03-FEB-2000	Mileage at Failure(s) 868	Vehicle Speed at Failure(s) 80	Failed Part(s) Available? <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously Contacted? <input type="checkbox"/> Yes <input type="checkbox"/> No
-----------------------------	--	----------------------------------	---------------------------------------	---	---

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE CAR HAS OVERHEATED ON 3 DIFFERENT OCCASIONS. THE 1ST INCIDENT WAS ON RTE 95 AT NIGHT WHICH MAKES FOR A DANGEROUS SITUATION. THE DEALER CHECKED THE CAR AND CLAIMED NOTHING WAS WRONG. FROM THIS POINT ON WE WATCHED AND REALIZED THAT THE TEMPERATURE GAUGE WENT FROM THE MIDDLE POINT UP TO THE TOP OF THE GAUGE FREQUENTLY. WE BROUGHT THE CAR BACK TO THE DEALER AGAIN AND WERE TOLD THAT GM SAID THAT THE OPERATING TEMPERATURE WAS ANYWHERE IN THE WHITE ZONE. THIS PAST WEEKEND WE DROVE ABOUT 40 MILES FROM HOME AND TWICE THE CAR OVERHEATED. THE 3RD TRIP BACK TO THE DEALER HAPPENED ON A DAY THAT GM FIELD TECHS WERE IN THE DEALER SERVICE AREA. ACCORDING TO THE SERVICE MANAGER, THESE TECHS WERE AWARE OF THE PROBLEM. THE TEMPORARY SOLUTION W

CONTINUED ON BACK PLEASE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.