

U.S. Department  
of TransportationNational Highway  
Traffic Safety  
Administration

**DOT Auto Safety Hotline**  
**Vehicle Owner's Questionnaire (VOQ)**

NATIONWIDE 1-888-DASH-2-DOT  
1-888-327-4236  
www.nhtsa.dot.gov/hotline

**FOR AGENCY USE ONLY 258**

Data Received

09-JUN-2000

 Od\_or \_\_\_\_\_  
 rt\_dt \_\_\_\_\_  
 od\_rt \_\_\_\_\_  
 up\_ltr \_\_\_\_\_

Reference No.

723809

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?  YES  NO  
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

**VEHICLE INFORMATION**

Vehicle Ident. No. (VIN) <small>(Listed at front of windshield or drivers side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1B4GP54L6TB412862	DODGE TRUCK	GRAND CARAVA	1996	

Purchase Date <b>01-JAN-1996</b>	Dealer's Name _____	Engine Size (CID/CC/L) _____	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input type="checkbox"/> Fuel Injection
<input checked="" type="checkbox"/> New <input type="checkbox"/> Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input type="checkbox"/> 3-Point Belt <input type="checkbox"/> Motorbell <input type="checkbox"/> Driverside Airbag <input type="checkbox"/> 2-Point Belt <input type="checkbox"/> Passengerside Airbag	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input checked="" type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Sport Ult <input checked="" type="checkbox"/> Van <input type="checkbox"/> Truck <input type="checkbox"/> Minivan <input type="checkbox"/> Motorcycle <input type="checkbox"/> Other _____	Body Style <input type="checkbox"/> 2-Door <input type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input type="checkbox"/> Other _____
--	---	---	--	---	---	---

**FAILED COMPONENT(S)/PART(S) INFORMATION**

Component 12110000 15300000	Part Name(s) INTERIOR SYSTEMS:PASSIVE RESTRAINT:AIR BAG EQUIPMENT:SPEED CONTROL	Location <input type="checkbox"/> Left <input type="checkbox"/> Right <input type="checkbox"/> Front <input type="checkbox"/> Rear	Failed Part(s) <input type="checkbox"/> Original <input type="checkbox"/> Replacement
-----------------------------------	---	--	---

No. of Failures <b>1</b>	Date(s) of Failure(s) <u>01-AUG-1999</u> Mileage at Failure(s) _____ Vehicle Speed at Failure(s) _____	Failed Part(s) Available? <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously Contacted? <input type="checkbox"/> Yes <input type="checkbox"/> No
-----------------------------	--	---	---

**APPLICATION INCIDENT INFORMATION**

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured _____	Number of Fatalities _____	Estimated Property Damage _____	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	---------------------------------	----------------------------	---------------------------------	---

**NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)**

**CLOCK SPRING IN STEERING WHEEL NEEDED TO BE REPLACED AGAIN (EST \$250). THIS IS THE SECOND TIME WITHIN 18 MONTHS. THIS SWITCH CONTROLS CRUISE CONTROL, HORN, AND AIR BAG FUNCTIONS. WHEN IT FAILS, THOSE FUNCTIONS DON'T WORK. PARTICULARLY THE AIR BAG AND HORN ARE MAJOR SAFETY ISSUES. THE FRONT WIPERS WOULD ACTIVATE FOR NO REASON (STARTLING DRIVER) - REPAIRED AT OWNERS EXPENSE BY DEALER. DOOR LOCKS HAVE ALWAYS ACTED SPOOKY. IMMEDIATELY LOCKING AFTER UNLOCKING WITH FOB OR WITH KEY. DEALER FOUND DOOR DRIVERS DOOR SWITCH SHORTED. REPAIRED AT OWNERS EXPENSE (EST \$160). LOCAL DEALER NOTIFIED OF ALL PROBLEMS - HAVE NOT CONTACT MANUFACTURER DIRECTLY.**

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.